

GENERALISED SOLUTION FOR CIRCULAR PLATES ON ELASTIC FOUNDATIONS



A THESIS

Submitted in Partial Fulfilment of the Requirements

FOR
THE DEGREE
OF
MASTER OF TECHNOLOGY




By
APURBA KUMAR CHAKRABORTI



Thesis
620.11282
C349

ME - 1971 - M - CHA - GEN
TO THE

DEPARTMENT OF MECHANICAL ENGINEERING
INDIAN INSTITUTE OF TECHNOLOGY
KANPUR
AUGUST, 1971



CERTIFICATE

This is to certify that the thesis entitled "GENERALISED SOLUTION FOR CIRCULAR PLATES ON ELASTIC FOUNDATIONS" is a record of work carried out under my supervision and that it has not been submitted elsewhere for a degree.

A. Ghosh

August 1971

Assistant Professor
Department of Mechanical Engineering
Indian Institute of Technology
Kanpur

POST GRADUATE OFFICE
This thesis has been approved
for the award of the Degree of
Master of Technology (M.Tech.)
in accordance with the
regulations of the Indian
Institute of Technology Kanpur
Dated. 2.9.71 24

(i)

ACKNOWLEDGEMENTS

I am extremely indebted to Dr. A. Ghosh for suggesting the problem and his constant inspiration, guidance and encouragement during the work. I am grateful to him for freely giving his valuable time for discussion throughout the work.

Thanks are due to Mr. A.K. Mallik for his untiring help during the work.

Thanks are also due to all my friends and colleagues especially Mr. S.P. Dasgupta, Mr. D.M.S. Nanda, Mr. D.K. Banwet and Mr. P.S. Debkanungo.

My acknowledgements are also due to the staff of the Computer Centre without whose cooperation this work would have been incomplete.

I am thankful to Mr. R.D. Tripathi for his excellent and flawless typing.

SYNOPSIS

of the
Dissertation on

"GENERALISED SOLUTION FOR CIRCULAR
PLATES ON ELASTIC FOUNDATIONS"

Submitted in Partial Fulfilment of
the Requirements for the Degree
of

MASTER OF TECHNOLOGY IN MECHANICAL ENGINEERING

by

A.K. Chakraborti
Department of Mechanical Engineering
Indian Institute of Technology, Kanpur
August, 1971

In the present work the author has developed a method of analysis in polar co-ordinate system, for a loaded circular plate on an elastic foundation by using finite difference technique. The subgrade has been assumed as semi-infinite elastic isotropic homogenous material. No assumption regarding the contact pressure distribution has been made. The equations have been developed in non-dimensional form and the results also have been obtained in non-dimensional form. The deflections are assumed to be small and the plate is assumed to be thin.

The results have been compared with some experimental results given in Reference 6. The agreement is quite good. The problem has been solved for a single concentrated load at various radial positions various values of D/μ . This is the most general case of loading and the results for any particular case of loading can be obtained from the results of the present method by proper superimposition. To show how to do this a few

particular cases of loadings have been solved.

Finally the results have been presented in the form of polynomial equations involving the various independent variables of the problem. The co-efficients have been tabulated and the method of using this co-efficients to get the deflection for any particular case have been discussed. Using these co-efficients, the deflections for any particular case can be obtained by using a small digital computer or even a desk calculator.

(iv)

TABLE OF CONTENTS

	Page
CERTIFICATE	i
ACKNOWLEDGEMENTS	ii
SYNOPSIS	iii
LIST OF TABLES	vii
LIST OF CHARTS	viii
LIST OF FIGURES	ix
NOMENCLATURE	x
CHAPTER I INTRODUCTION	
1.1 Introduction	1
1.2 Review of past work	3
1.3 Object and scope of the present work	7
CHAPTER II THEORETICAL ANALYSIS	
2.1 Mathematical model and idealisations	9
2.2 Approach to numerical solution	10
2.2.1 Finite difference expression for plate equation	10
2.2.2 Finite difference expression for moments	14
2.3 Formulation of the theoretical analysis	15
2.3.1 Development of the concept of deflection co-efficient for elastic subgrade, $\gamma(I, J, K)$	15
2.3.2 Definition of the deflection co-efficient $\gamma(I, J, K)$	17
2.3.4 Numerical form of the generalised equation of plates on elastic foundation	22
2.3.5 Non-dimensional form of the generalised plate equation	25

2.3.6	Non-dimensional form of the moment equations	27
2.3.7	Boundary conditions	28
2.4	Method of solution of the problem	30
2.4.1	Calculation of β (I, J, K)	30
2.4.2	Method of solving for deflections	30
CHAPTER III RESULTS AND DISCUSSION		
3.1	General discussion	43
3.2	Results	45
3.3	Examples	45
3.4	Discussion on results	49
CHAPTER IV CONCLUSIONS		
4.1	Relative merits of the present method over the conventional design method	122
4.2	Conclusions	124
APPENDIX A		129
APPENDIX B		132
APPENDIX C		134

LIST OF TABLES

Table No.	Page No.	
1	Deflections for a single concentrated load	51
2	Moments, \bar{M}_y , for a single concentrated load	54
3	Moment \bar{M}_θ for a single concentrated load	57
4	Deflections for two equally spaced concentrated loads	60
5	Deflections for three equally spaced concentrated loads	62
6	Deflections for four equally spaced concentrated loads	
7	Deflections for six equally spaced concentrated loads	
8	Deflections for eight equally spaced concentrated loads	
9	Deflections for twelve equally spaced concentrated loads	
10	Deflections due to a ring load	70
11	Deflections due to a radial line load	70
12	Deflections due to diametral line load	71
13	Deflections due to an uniformly distributed load on the whole plate	71
14	Co-efficients of polynomial equations	72
	A. For sector 1	72
	B. For sector 2	75
	C. For sector 3	78
	D. For sector 4	81
	E. For sector 5	84
	F. For sector 6	87
	G. For sector 7	90
	H. For sector 8	93
	I. For sector 9	96
	J. For sector 10	99
	K. For sector 11	102
	L. For sector 12	105
	M. For sector 13	108

LIST OF CHARTS

Chart No.		Page
1	Finite difference expression for biharmonic equation	36
2	Finite difference expression for M_g	37
3	Finite difference expression for M_θ	37
4.	Finite difference expression for first boundary condition	38
5	Finite difference expression for second boundary condition	38

LIST OF FIGURES

Fig. No.	Page
2.1 Grid arrangement	39
2.2 Co-ordinate system	40
2.3 Graphical representation of the method of determination of $\gamma(I, J, K)$	41
2.4 Determination of the radii and the angles	42
3.1 Approximations for the elliptic integrals in Reference No.6	111
3.2 Deflection contours for a single concentrated load at first radial position	112
3.3 Deflection contours for a single concentrated load at second radial position	113
3.4 Deflection contours for a single concentrated load at third radial position	114
3.5 Deflection contours for a single concentrated load at fourth radial position	115
3.6 Deflection contours for a single concentrated load at fifth radial position	116
3.7 Deflection contours for a single concentrated load at sixth radial position	117
3.8 Deflection contours for six equally spaced loads at fifth pitch circle	118
3.9 Deflection contours for a radial line load	119
3.10 Deflection contours for a diametral line load	120
3.11 Comparison of the results	121
4.1 Three extreme cases of r_I	131

NOMENCLATURE

w	=	Deflection of the plate and the subgrade
\bar{w}	=	Non-dimensional deflection of the plate and the subgrade
M_ρ	=	Radial component of moment
\bar{M}_ρ	=	Radial component of non-dimensional moment
\bar{M}_Θ	=	Tangential component of non-dimensional moment
$M_{\rho, \Theta}$	=	Twisting moment
E_p	=	Young's modulus of the plate material
E_s	=	Young's modulus of the subgrade material
μ	=	Poisson's ratio of the plate material
ν	=	Poisson's ratio of the subgrade material
h	=	Thickness of the plate
q	=	Loading on the plate
\bar{q}	=	Non-dimensional loading on the plate
p	=	Reactive pressure from the subgrade
M_Θ	=	Tangential component of moment
D	=	Flexural rigidity of the plate
\bar{D}	=	Non-dimensional flexural rigidity of the plate subgrade combination

Other notations used are described as and when used.

CHAPTER I

INTRODUCTION

1.1 Introduction

The study of plates on elastic foundation has an important application in foundation engineering. It is a formidable hurdle for engineers even today to arrive at an economical and rational basis of design for circular raft foundations. In the present analysis a method of solution has been discussed which is perfectly general in the sense that the results obtained by this can be used to solve problems of circular plates on elastic foundations for any type of loading by proper superimposition. This problem occurs in practice in the foundation of water towers, chimneys, silos and similar structures.

The assumptions on the basis of which the present formulation has been done are:

- i) The subgrade is assumed to be a semi-infinite, elastic, isotropic homogeneous solid. This is a very common assumption made for subgrade and in the case of normal structures under small settlement conditions this gives a realistic picture of the actual

stress condition. Another common assumption about the subgrade which has been used by many investigators is that of dense liquid subgrade, where it is assumed that the reactive pressure at any point is directly proportional to the deflection of the subgrade at that point. In this assumption the lateral continuity of the soil mass is ignored. Preference has been given to the elastic isotropic solid assumption over the dense liquid assumption because it gives a more realistic picture of the actual subgrade though it has been seen that the latter assumption gives quite agreeable solution in some cases.

ii) It is assumed that the theory of thin plates is applicable to the plate under consideration and thus the basic limitations of the plate theory are also applicable to the present problem.

iii) The plate is assumed to remain always in contact with the subgrade. This obviously implies that there must be some adhesive force to keep the plate from lifting. In practice the weight of the plate and the overlying mass of soil prevent lifting of the plate from the subgrade.

iv) The shear force at the interface of the plate and the subgrade has been neglected. This shear force which is developed owing to sliding tendency between the plate and the subgrade will be of very small magnitude and as such will have very little effect on the deflected shape of the plate.

v) The external moments at the loading points have been neglected.

vi) Deflections are small.

The main merit of the present method is that no assumption regarding the nature of contact pressure distribution is necessary. Equations have been formulated eliminating this unknown pressure distribution from the condition of equilibrium and compatibility of the forces and deflected shape of the plate and the subgrade surface.

1.2 Review of Past Work

The subject of plates on elastic foundations has received engineers' attention mostly since the second quarter of this century. Both plates and beams on elastic foundations constitute a vast field of study. A rather less intensive study has been devoted so far to the bending of plates on elastic foundations than to beams.

The contribution to the problem of plates on elastic foundation can be subdivided into three major groups, according to the different subgrade assumptions made in the analysis. These are:

i) The first group assumes the subgrade to have a constant subgrade modulus, i.e., the deflection of the elastic foundation at any point of the surface is directly proportional to the pressure at that point and is independent of pressures at other points.

Mathematically it can be expressed as

$$P = Kw$$

where

P = Reactive pressure

K = Constant subgrade modulus

w = Deflection of subgrade

This assumption, obviously ignores the lateral link in the semi-infinite continuum. Physically this model can be interpreted as a system of mutually independent separate springs with the same linear elastic properties. This occurs in practice in a dense liquid, on which structures remain in a floating condition.

ii) A second kind of assumption for the subgrade which has been taken by many investigators and accepted by the author in the present analysis is that of a semi-infinite isotropic homogeneous elastic solid. In this case the deflection of a particular point of the subgrade is dependent not only on the pressure at that particular point, but also on the pressure at all other points of the subgrade.

Obviously, this assumption presents a rather complicated mathematical barrier. But engineers have many a time accepted this trouble by including in their analysis this logical assessment of the subgrade properties.

iii) The third group includes various kinds of assumptions other than the two described above, e.g., elastic layer system,

anisotropic behaviour, elastic properties varying with depth, composite layer foundation etc.

Incidentally, the first type of assumption as stated above was made by Winkler³⁶. This assumption, despite its limitations, leads to good results for many practical problems such as floating bridges, floating ice ferries where the relation $P = Kw$ represents a simple consequence of the law of Archimedes, as well as in the case of plates and beams resting on a sufficiently thin deformable layer.

Pickett²⁷ has commented that, when the subgrade is an elastic layer of finite thickness, and is supported by a base of much more rigid material, then for bearing plates of diameter larger than the thickness of the elastic layer, the effect of the subgrade on the bearing plate will be more nearly like dense liquid than that of semi-infinite elastic solid. With this model of foundation a rapid development of the field of plates on elastic foundations occurred after the second world war, particularly to cope up with the problem of designing concrete road pavements and aircraft runways.

A large amount published work^{7,11,13,21,24,27,34,35} appeared, mainly concerned with furnishing engineers with practical design methods. But most of these works concern with infinite slab loaded with a concentrated force or a patch load. These works were mainly carried out in U.S.A. at different Highway Research Institutes.

A large number works with the same assumption of dense liquid have been published in many other countries, particularly U.S.S.R., Japan and Germany. A comprehensive review of the works

done in Russia is given by Korenev^{21,22}. A series of papers by Atsushi Saito et.al.^{1,2} have dealt with the solution of finite circular plates with help of infinite series involving Ber, Bei, Ker and Kei functions.

In the third group first comes Reissner foundation^{28,29}. In this case the subgrade is assumed as a vertically loaded elastic layer in which the horizontal stress components are neglected. Rhines²⁹ points out that this model may predict excessive stresses in the structure because this is not very realistic for relatively thick foundation layer.

Next comes the Hetenyi foundation^{14,15,16}. Here the subgrade is represented by two sets of springs with two different spring constants and a fictitious member in between them. In this case an arbitrary degree of discontinuity may be allowed for the subgrade. This assumption has been applied to plates on elastic foundation by Lee²³.

Here it should be noted that the Reissner foundation leads to a sixth order differential equation and Hetenyi foundation leads to an eighth order differential equation. Though this provides greater adaptability, while solving them mathematically they become very much complicated.

With elastic isotropic solid subgrade assumption, probably Hogg¹⁷ and Holl¹⁸ had been the first to publish their works in 1938. They have independently solved the problem of a thin slab of semi-

infinite dimension supported by a semi-infinite elastic subgrade.

Pickett and Badruddin²⁶ has given some influence charts for design of semi-infinite pavement slabs with this assumption.

In a more recent work Chatterjee and Ghosh⁶ have solved the case of a circular plate on elastic foundation for six equally spaced concentrated loads. The present work is a generalisation of their work.

A comprehensive review of the various foundation models has been given by Kerr²⁰.

In the present analysis the subgrade has been assumed as a semi-infinite homogeneous, isotropic elastic body. Because as pointed out earlier Winkler's assumption neglects completely the lateral continuity of the soil mass and the models of the third group are very complicated mathematically. The reason for avoiding complicated mathematics being that the purpose of the present analysis is to provide engineers with a sound method of design of circular plates on elastic foundations.

1.3 Object and Scope of the Present Work

The main object of the present analysis is to find a method of solution for circular plates on elastic foundations, which is perfectly general and can be used for any type of loading. The results have been obtained in non-dimensional form so that this solution is valid for any plate material, any type of subgrade material and for any dimension of the plate.

Scientists have idealised the subgrade, though the behaviour of actual subgrade is very much unpredictable even with elaborate soil tests. The assumption of isotropic elastic homogeneous solid is a very common assumption and perhaps the most widely used in solving settlement problems of foundation engineering. Terzaghi¹⁹ pointed out, "if the factor of safety of a mass of soil with respect to failure by flow exceeds a value of about 3, the state of stress computed in the soil is likely to be more or less similar to the stress computed on the assumption that the soil is perfectly elastic. Hence, the state of stress in a mass of soil under influence of moderate stresses can be estimated by means of theory of elasticity". The range of stress and strain in soil underneath normal foundation of a structure will be well below the plastic state.

Thus, it is obvious that the present work has a potential applicability in the field of "Foundation Engineering".

CHAPTER II

THEORETICAL ANALYSIS

2.1 Mathematical Model and Idealisation

Taking all the assumptions described earlier in Chapter I, the mathematical equation for plates on elastic subgrade³³ is given by

$$D \left(\frac{\partial^2}{\partial x^2} + \frac{\partial^2}{\partial y^2} \right) \left(\frac{\partial^2 w}{\partial x^2} + \frac{\partial^2 w}{\partial y^2} \right) = q(x,y) - p(x,y) \quad (2.1)$$

where, D = Flexural rigidity of the plate

$$= \frac{E_p h^3}{12(1-\mu^2)}$$

E_p = Modulus of elasticity of the plate material

h = Thickness of the plate

μ = Poisson's ratio of the plate material

w = Deflection of the plate

$q(x,y)$ = Loading pressure on the plate

$p(x,y)$ = Reactive pressure from the subgrade on the plate

Out of all the variables as listed above the only unknowns are w and $p(x,y)$. The reactive pressure $p(x,y)$ depends upon the properties of the subgrade and plate, dimension of the plate and the loading pattern.

The above equation (2.1) when expressed in polar co-ordinate system takes the form

$$D \left(\frac{\partial^2}{\partial \rho^2} + \frac{1}{\rho} \frac{\partial}{\partial \rho} + \frac{1}{\rho^2} \frac{\partial^2}{\partial \theta^2} \right) \left(\frac{\partial^2 w}{\partial \rho^2} + \frac{1}{\rho} \frac{\partial w}{\partial \rho} + \frac{1}{\rho^2} \frac{\partial^2 w}{\partial \theta^2} \right) = q(\rho, \theta) - p(\rho, \theta) \quad \dots \dots (2.2)$$

where ρ is the radial coordinate and θ is the angular co-ordinate of a point on the plate.

2.2 Approach to Numerical Solution

2.2.1 Finite Difference Expression for Plate Equation

The left hand side of the plate equation is nothing but the biharmonic operator. So to find the finite difference expression of the plate first the polar biharmonic operator is expanded as shown below:

$$\begin{aligned} \nabla^4 &= \left(\frac{\partial^2}{\partial \rho^2} + \frac{1}{\rho} \frac{\partial}{\partial \rho} + \frac{1}{\rho^2} \frac{\partial^2}{\partial \theta^2} \right) \left(\frac{\partial^2}{\partial \rho^2} + \frac{1}{\rho} \frac{\partial}{\partial \rho} + \frac{1}{\rho^2} \frac{\partial^2}{\partial \theta^2} \right) \\ &= \frac{\partial^4}{\partial \rho^4} + \frac{2}{\rho^2} \frac{\partial^4}{\partial \rho^2 \partial \theta^2} + \frac{1}{\rho^4} \frac{\partial^4}{\partial \theta^4} + \frac{2}{\rho} \frac{\partial^3}{\partial \rho^3} - \frac{2}{\rho^3} \frac{\partial^3}{\partial \rho \partial \theta^2} \\ &\quad - \frac{1}{\rho^2} \frac{\partial^2}{\partial \rho^2} + \frac{4}{\rho^4} \frac{\partial^2}{\partial \theta^2} + \frac{1}{\rho^3} \frac{\partial}{\partial \rho} \end{aligned} \quad \dots \dots (2.3)$$

The plate has been divided into elements by radial lines and concentric circles as shown in Fig. 2.1. The points at which the differences are taken are the central point of each element and not the intersection of the grid lines. The reason for this will be pointed out later on.

For the arrangement of elements in polar system as shown in Fig. 2.1 the finite difference expressions^{3,9,30} for the various partial derivatives of w in $\nabla^4 w$ for an element I, v are:

$$\left(\frac{\partial w}{\partial \rho}\right)_{I,v} = \frac{w_{I+1,v} - w_{I-1,v}}{2\delta}$$

$$\left(\frac{\partial^2 w}{\partial \rho^2}\right)_{I,v} = \frac{w_{I+1,v} - 2w_{I,v} + w_{I-1,v}}{\delta^2}$$

$$\left(\frac{\partial^3 w}{\partial \rho^3}\right)_{I,v} = \frac{w_{I+2,v} - 2w_{I+1,v} + 2w_{I-1,v} - w_{I-2,v}}{2\delta^3}$$

$$\left(\frac{\partial^4 w}{\partial \rho^4}\right)_{I,v} = \frac{w_{I+2,v} - 4w_{I+1,v} + 6w_{I,v} - 4w_{I-1,v} + w_{I-2,v}}{\delta^4}$$

$$\left(\frac{\partial w}{\partial \theta}\right)_{I,v} = \frac{w_{I,v+1} - w_{I,v-1}}{2\lambda}$$

$$\left(\frac{\partial^2 w}{\partial \theta^2}\right)_{I,v} = \frac{w_{I,v+1} - 2w_{I,v} + w_{I,v-1}}{\lambda^2}$$

$$\left(\frac{\partial^3 w}{\partial \theta^3}\right)_{I,v} = \frac{w_{I,v+2} - 2w_{I,v+1} + 2w_{I,v-1} - w_{I,v-2}}{2\lambda^3}$$

$$\left(\frac{\partial^4 w}{\partial \theta^4}\right)_{I,v} = \frac{w_{I,v+2} - 4w_{I,v+1} + 6w_{I,v} - 4w_{I,v-1} + w_{I,v-2}}{\lambda^4}$$

$$\begin{aligned} \left(\frac{\partial^3 w}{\partial \beta \partial \theta^2}\right)_{I,v} &= \frac{\partial}{\partial \beta} \left(\frac{w_{I,v+1} - 2w_{I,v} + w_{I,v-1}}{\lambda^2} \right) \\ &= \frac{1}{2\lambda^2 \delta} \left[(w_{I+1,v+1} - w_{I-1,v+1}) \right. \\ &\quad \left. - 2(w_{I+1,v} - w_{I-1,v}) + (w_{I+1,v-1} - w_{I-1,v-1}) \right] \end{aligned}$$

$$\begin{aligned} \left(\frac{\partial^4 w}{\partial \beta^2 \partial \theta^2}\right)_{I,v} &= \frac{1}{\lambda^2} \frac{\partial^2}{\partial \beta^2} (w_{I,v+1} - 2w_{I,v} + w_{I,v-1}) \\ &= \frac{1}{\lambda^2 \delta^2} \left[(w_{I+1,v+1} - 2w_{I,v+1} + w_{I-1,v+1}) \right. \\ &\quad \left. - 2(w_{I+1,v} - 2w_{I,v} + w_{I-1,v}) \right. \\ &\quad \left. + (w_{I+1,v-1} - 2w_{I,v-1} + w_{I-1,v-1}) \right] \end{aligned}$$

Substituting these in the equation (2.3) and using the relation

$$\zeta = (I - .5) \delta$$

the final form, after simplification, of the biharmonic operator is given by,

$$\begin{aligned}
\nabla^4 w = \frac{1}{\delta^4} & \left[\left(1 + \frac{1}{I-5} \right) w_{I+2,v} + \left(-4 - \frac{1}{(I-5)^2 \lambda^2} - \frac{2}{(I-5)} \right. \right. \\
& + \frac{2}{(I-5)^3 \lambda^2} - \frac{1}{(I-5)^2} + \frac{1}{2(I-5)^3} \left. \right) w_{I+1,v} \\
& + \left(6 + \frac{6}{(I-5)^4 \lambda^4} + \frac{8}{(I-5)^2 \lambda^2} - \frac{8}{(I-5)^4 \lambda^2} + \frac{2}{(I-5)^2} \right) w_{I,v} \\
& + \left(-4 - \frac{4}{(I-5)^2 \lambda^2} + \frac{2}{(I-5)} - \frac{2}{(I-5)^3 \lambda^2} - \frac{1}{(I-5)^2} \right. \\
& \left. - \frac{1}{2(I-5)^3} \right) w_{I-1,v} + \left(1 - \frac{1}{(I-5)} \right) w_{I-2,v} \\
& + \left(-\frac{2}{(I-5)^2 \lambda^2} - \frac{1}{(I-5)^3 \lambda^2} \right) w_{I+1,v+1} \\
& + \left(-\frac{2}{(I-5)^2 \lambda^2} - \frac{1}{(I-5)^3 \lambda^2} \right) w_{I+1,v-1} + \left(\frac{1}{(I-5)^4 \lambda^4} \right) w_{I,v+2} \\
& + \left(-\frac{1}{(I-5)^4 \lambda^4} - \frac{4}{(I-5)^2 \lambda^2} + \frac{4}{(I-5)^4 \lambda^2} \right) w_{I,v+1} \\
& + \left(-\frac{4}{(I-5)^4 \lambda^4} - \frac{4}{(I-5)^2 \lambda^2} + \frac{4}{(I-5)^4 \lambda^2} \right) w_{I,v-1}
\end{aligned}$$

$$\begin{aligned}
 & + \left(\frac{1}{(I-.5)^4 \lambda^4} \right) w_{I,v-2} + \left(\frac{2}{(I-.5)^2 \lambda^2} + \frac{1}{(I-.5)^5 \lambda^2} \right) w_{I-1,v+1} \\
 & + \left. \left(\frac{2}{(I-.5)^2 \lambda^2} + \frac{1}{(I-.5)^3 \lambda^2} \right) w_{I-1,v-1} \right] \dots \dots \quad (2.4)
 \end{aligned}$$

The above equation (2.4) can be conveniently expressed in a chart form as shown in Chart 1.

2.2.2 Finite Difference Expressions for Moments

The expressions for M_ρ and M_θ in terms of deflections (w) is also expanded in finite difference form as shown below. These will be necessary for calculating M_ρ and M_θ after getting the deflections.

The expressions for M_ρ and M_θ in terms of deflections in polar form are given by,

$$M_\rho = -D \left[\frac{\partial^2 w}{\partial \rho^2} + \mu \left(\frac{1}{\rho} \frac{\partial w}{\partial \rho} + \frac{1}{\rho^2} \frac{\partial^2 w}{\partial \theta^2} \right) \right] \quad (2.5)$$

$$M_\theta = -D \left[\frac{1}{\rho} \frac{\partial w}{\partial \rho} + \frac{1}{\rho^2} \frac{\partial^2 w}{\partial \theta^2} + \mu \frac{\partial^2 w}{\partial \rho^2} \right] \quad (2.6)$$

The finite difference form of the above expressions are,

$$(M_\rho)_{I,v} = -D \left[w_{I+1,v} \left(\frac{1}{\delta^2} + \frac{\mu}{2(I-.5)\delta^2} \right) + w_{I,v} \left(-\frac{2}{\delta^2} - \frac{2\mu}{(I-.5)^2 \delta^2 \lambda^2} \right) \right]$$

$$+ w_{I-1,v} \left(\frac{1}{\delta^2} - \frac{\mu}{2(I-.5)\delta^2} \right) + \frac{\mu}{(I-.5)^2 \lambda^2 \delta^2} (w_{I,v+1} + w_{I,v-1}) \right] \\ \dots \dots \quad (2.7)$$

$$(M_\theta)_{I,v} = -D \left[w_{I+1,v} \left(\frac{1}{2(I-.5)\delta^2} + \frac{\mu}{\delta^2} \right) + w_{I,v} \left(-\frac{2}{(I-.5)^2 \lambda^2 \delta^2} - \frac{2\mu}{\delta^2} \right) \right. \\ \left. + w_{I-1,v} \left(\frac{1}{2(I-.5)\delta^2} + \frac{\mu}{\delta^2} \right) + \frac{1}{(I-.5)^2 \lambda^2 \delta^2} (w_{I,v+1} + w_{I,v-1}) \right] \\ \dots \dots \quad (2.8)$$

The above equations in chart form are shown in Charts 2 and 3.

2.3 Formulation of the Theoretical Analysis

The basic method in solving the problem is to find expressions for the deflection pattern of the subgrade in terms of the reactive pressure and the deflection pattern of the plate in terms of the reactive pressure and the external load applied. After getting these two expressions the reactive pressure from the subgrade is eliminated between these and a new expression involving only one unknown, viz, deflection pattern is obtained. This can be done because the deflection patterns of the subgrade and the plate will be the same. The reason for doing this is that in the plate equation (2.2) there are two unknowns, the deflection w and the reactive pressure p .

2.3.1 Development of the Concept of Deflection Co-efficient for Elastic Subgrade, $\beta(I, J, K)$

When a concentrated load is acting on the surface of a semi-infinite elastic solid, according to Boussinesq³², the expression

for deflection of a point on the surface at a distance of r from the load point is given by,

$$w = \frac{P(1-v)^2}{\pi E_s r} \quad (2.9)$$

where, w = Deflection of the point

P = Concentrated point load

E_s = Modulus of elasticity of the elastic solid

v = Poisson's ratio of the material

In this subsection only the deflection of the subgrade will be considered. For solving the present problem the contact area between the plate and the subgrade has been subdivided into 144 elements by radial lines and concentric circles as the plate (Fig. 2.1). The pressure intensity in one particular element has been assumed to remain constant.

Each element is represented by ρ and θ co-ordinates as shown in Fig. 2.2. So the actual co-ordinates of the central point of the ρ - θ element is given by $[(\rho - 0.5)\delta, \theta]$.

From Fig. 2.3, it is clear that the deflection at the centre of J-n element due to a load intensity of p on the elemental area (shaded) of I-v element, which may be considered as concentrated at the centre of that infinitesimal area, will be given according to equation (2.9) by

$$\begin{aligned}
 \delta_{w_{J-n}} &= \frac{1-\nu^2}{\pi E_s} p r d\theta dr \\
 &= \frac{1-\nu^2}{\lambda E_s} p d\theta dr
 \end{aligned} \tag{2.10}$$

Since, the pressure intensity on the I-v element has been considered as uniform the deflection at the centre of J-n element due to the load on I-v element will be given by,

$$w_{J-n} = \frac{1-\nu^2}{\lambda E_s} p \iint dr d\theta$$

Now, replacing the pressure intensity by, $\frac{P_{I,v}}{\text{Area of the loaded element}}$, the expression becomes

$$w_{J-n} = \frac{1-\nu^2}{\lambda E_s} \frac{P_{I,v}}{(I-5)\lambda \delta^2} \iint dr d\theta \tag{2.11}$$

where $P_{I,v}$ = Total uniformly distributed load on I-v element.

2.3.2 Definition of the Deflection Co-effecient $\gamma_{(I,J,K)}$

The right hand side of the above equation (2.11) can be expressed as a constant quantity multiplied by a non-dimensional variable given by,

$$\frac{1}{(I-5)\delta} \iint dr d\theta$$

Now this expression of the variable is found to depend on r , which is again dependent on three other independent variables I,J,K. Where I,J are the ρ - co-ordinates of I-v and J-n elements respectively and K

is the difference of their θ co-ordinates, ($n \sim v$). The above quantity is described as $\gamma(I, J, K)$. Hence $\gamma(I, J, K)$ may be defined as a triple subscripted non-dimensional co-efficient, which when multiplied by the constant, $P_{I-v} (1-\nu^2)/\pi E_s \lambda \delta$, depending upon the subgrade properties and the dimensions of the particular problem, gives the deflection of the centre of $J-n$ element due to an uniformly distributed total load of P_{I-v} on $I-v$ element of the subgrade surface.

Thus the equation (2.11) can be written as

$$w_{J-n} = \frac{(1-\nu^2) P_{I-v}}{\pi E_s \lambda \delta} \gamma(I, J, K) \quad (2.12)$$

where

$$\gamma(I, J, K) = \frac{1}{(I-5)\delta} \iint dr d\theta \quad (2.13)$$

The integral $\iint dr d\theta$ in $\gamma(I, J, K)$ can be expressed as the line integral $\int_C r d\theta$ where C is the peripheral line of the $I-v$ element in the clockwise direction and r is the distance of the points on C from the centre of $J-n$ element.

Now if the sides of the $I-v$ element be represented by I, II, III and IV and the corresponding radius vectors by r_I, r_{II}, r_{III} and r_{IV} as shown in Fig. 2.4. then the integral $\int_C r d\theta$ takes the form,

$$\int_C r d\theta = \int_{\theta_T}^{\theta_S} r_I d\theta + \int_{\theta_S}^{\theta_V} r_{IV} d\theta + \int_{\theta_V}^{\theta_U} r_{III} d\theta + \int_{\theta_U}^{\theta_T} r_{II} d\theta \dots \dots \dots (2.14)$$

Thus the expression for $\gamma(I, J, K)$ becomes,

$$\gamma(I, J, K) = \frac{1}{(I-.5)\delta} \left[r_I d\theta + r_{II} d\theta + r_{III} d\theta + r_{IV} d\theta \right] \quad \dots \dots \dots (2.15)$$

θ_S θ_T θ_U θ_V
 θ_T θ_U θ_V θ_S

The expressions for the variables $r_I, r_{II}, r_{III}, r_{IV}$ are developed in terms of θ as shown below, by using Fig. 2.4:

$$r_I = QX = QR + RX$$

$$\text{From } \Delta OQR, OR = OQ \cos \theta$$

$$= (J-.5) \delta \cos \theta$$

$$\begin{aligned} \text{From } \Delta XQR, RX &= \sqrt{OQ^2 - OR^2} \\ &= \sqrt{I^2 \delta^2 - ((J-.5) \delta \cos \theta)^2} \\ &= \delta \sqrt{I^2 - (J-.5)^2 \sin^2 \theta} \end{aligned}$$

So the expression for r_I is

$$r_I = \delta \left[(J-.5) \cos \theta \pm \sqrt{I^2 - (J-.5)^2 \sin^2 \theta} \right] \quad (2.16)$$

In an exactly similar way

$$r_{III} = \delta \left[(J-.5) \cos \theta \pm \sqrt{(I-1)^2 - (J-.5)^2 \sin^2 \theta} \right] \quad \dots \dots \dots \quad (2.17)$$

Using the properties of triangles the expressions for r_{II} and r_{IV}

are obtained as,

$$r_{II} = \frac{(J-.5) \int \sin (K+.5) \lambda}{\sin \{(K+.5) \lambda + \theta\}} \quad (2.18)$$

$$r_{IV} = \frac{(J-.5) \int \sin (K-.5) \lambda}{\sin \{(K-.5) \lambda + \theta\}} \quad (2.19)$$

The limits of the integrals in equation (2.15) are expressed as,

$$\theta_S = \tan^{-1} \left[\frac{I \sin (K-.5) \lambda}{(J-.5) - I \cos (K-.5) \lambda} \right] \quad (2.20)$$

$$\theta_V = \tan^{-1} \left[\frac{(I-1) \sin (K-.5) \lambda}{(J-.5) - (I-1) \cos (K-.5) \lambda} \right] \quad (2.21)$$

$$\theta_U = \tan^{-1} \left[\frac{(I-1) \sin (K+.5) \lambda}{(J-.5) - (I-1) \cos (K+.5) \lambda} \right] \quad (2.22)$$

$$\theta_T = \tan^{-1} \left[\frac{I \sin (K+.5) \lambda}{(J-.5) - I \cos (K+.5) \lambda} \right] \quad (2.23)$$

Substituting equations (2.16) through (2.19) in equation (2.15),

$$\begin{aligned}
 \gamma(I, J, K) = & \frac{1}{(I-.5)} \int_{\theta_T}^{\theta_S} \left[(J-.5) \cos \theta \pm \sqrt{I^2 - (J-.5)^2 \sin^2 \theta} \right] d\theta \\
 & + \frac{1}{(I-.5)} \int_{\theta_U}^{\theta_T} \frac{(J-.5) \sin (K+.5)\lambda}{\sin \{(K+.5)\lambda + \theta\}} d\theta \\
 & + \frac{1}{(I-.5)} \int_{\theta_V}^{\theta_U} \left[(J-.5) \cos \theta \pm \sqrt{(I-1)^2 - (J-.5)^2 \sin^2 \theta} \right] d\theta \\
 & + \frac{1}{(I-.5)} \int_{\theta_S}^{\theta_V} \frac{(J-.5) \sin (K-.5)\lambda}{\sin \{(K-.5)\lambda + \theta\}} d\theta
 \end{aligned} \quad \dots \quad (2.24)$$

where $\theta_S, \theta_V, \theta_U, \theta_T$ are expressed by equations (2.20) through (2.23).

To get the final values of $\gamma(I, J, K)$ by integration it is found that in the first and third integrals there are terms like $\int \sqrt{I^2 - (J-.5)^2 \sin^2 \theta} d\theta$ and $\int \sqrt{(I-1)^2 - (J-.5)^2 \sin^2 \theta} d\theta$. These can be very easily reduced to the form of a $\int \sqrt{1-b^2 \sin^2 \theta} d\theta$, which is nothing but standard elliptic integral of second kind for which no closed form integral is available. So the first and third integrals have been calculated by numerical integration using Simpson's Rule with 50 divisions.

The second and fourth integrals pose no problem and they can be integrated in closed form. After doing this the final form of $\gamma(I, J, K)$ is obtained as

$$\begin{aligned}
 \gamma(I, J, K) = & \frac{1}{(I-0.5)} \int_{\theta_T}^{\theta_S} \left[(J-0.5) \cos \theta \pm \sqrt{I^2 - (J-0.5)^2 \sin^2 \theta} \right] d\theta \\
 & + \frac{(J-0.5)}{(I-0.5)} \sin (K+0.5) \lambda \left[\log_e \tan \left[\frac{(K+0.5)\lambda + \theta}{2} \right] \right]_{\theta_U}^{\theta_T} \\
 & + \frac{1}{(I-0.5)} \int_{\theta_V}^{\theta_U} \left[(J-0.5) \cos \theta \pm \sqrt{(I-1)^2 - (J-0.5)^2 \sin^2 \theta} \right] d\theta \\
 & + \frac{(J-0.5)}{(I-0.5)} \sin (K-0.5) \lambda \left[\log_e \tan \left[\frac{(K-0.5)\lambda + \theta}{2} \right] \right]_{\theta_S}^{\theta_V} \\
 & \dots \dots \quad (2.25)
 \end{aligned}$$

From equation (2.25) it is observed that $\gamma(I, J, K)$ is a nondimensional quantity.

2.3.4 Numerical Form of the Generalised Equation of Plates on Elastic Foundations

In section 2.3.2 it was seen that the deflection of the central point of $J-n$ element of the subgrade, due to a uniformly distributed total load of $P_{I,v}$ on $I-v$ element of the subgrade, is given by,

$$\Delta w_{J-n} = \gamma(I, J, K) \frac{(1-\gamma^2) P_{I,v}}{\pi E_s \lambda \delta} \quad (2.26)$$

The only difference between this equation and equation (2.12) is that here w_{J-n} has been replaced by Δw_{J-n} to signify that it is the deflection due to the reactive load on $I-v$ -th element only.

But pressure on the subgrade acts on the whole of the circular area covered by the plate of which $I-v$ is only a small element. Thus the actual deflection of the centre of the $J-n$ element of the subgrade will be given by the summation of effects of all such $I-v$ elements within the circular area and thus the expression becomes,

$$w_{J-n} = \sum_I \sum_v \frac{(1-\nu^2) P_{I,v}}{\pi E_s \lambda \delta} \gamma_{(I,J,K)} \quad (2.27)$$

Equation (2.27) is the exact form of the deflection of the central point of the $J-n$ element of the subgrade, being loaded by the pressure on the whole of the circular area below the plate. Thus this equation gives the deflection pattern for the subgrade. Now this deflection is exactly equal to the deflection of the central point of the $J-n$ -th element of the plate.

Till now only the deflections of the central points of the elements of the subgrade have been considered. Now the expressions for deflections of the central points of the elements of the plate are to be found out from plate equation.

The deflection of the central point of $I-v$ element of the plate, being loaded by the imposed load on top and by the reactive pressure from the bottom can be obtained by solving the plate equation,

$$D \nabla^4 w_{I,v} = \frac{q_{I,v}}{(I-5) \lambda \delta^2} - \frac{P_{I,v}}{(I-5) \lambda \delta^2} \quad (2.28)$$

where, $q_{I,v}$ = Applied load on plate at the I-v element

$P_{I,v}$ = Total reactive load on the I-v element of the plate

Equation (2.28) gives the deflection pattern of the plate.

Here it is assumed that the total applied load, $q_{I,v}$, can be represented by an uniform pressure distribution on the element and same is the case with $P_{I,v}$.

Now using the finite difference form of $\nabla^4 w$ as given by equation (2.4), the equation (2.28) can be expressed as,

$$\frac{(I-.5)}{\delta^4} D f(w) = \frac{q_{I,v}}{\lambda \delta^2} - \frac{P_{I,v}}{\lambda \delta^2} \quad (2.29)$$

where,

$$f(w) = (1 + \frac{1}{(I-.5)}) w_{I+2,v} + (-4 - \frac{1}{(I-.5)^2} \lambda^2) w_{I,v} - \frac{3}{(I-.5)}$$

$$+ \frac{2}{(I-.5)^3 \lambda^5} - \frac{1}{(I-.5)^2} + \frac{1}{2(I-.5)^3} w_{I+1,v} + (6 + \frac{3}{(I-.5)^4} \lambda^4)$$

$$+ \frac{8}{(I-.5)^2 \lambda^2} - \frac{8}{(I-.5)^4 \lambda^2} + \frac{2}{(I-.5)^2} w_{I,v} + (-4 - \frac{4}{(I-.5)^2} \lambda^2)$$

$$+ \frac{2}{(I-.5)} - \frac{2}{(I-.5)^3 \lambda^2} - \frac{1}{(I-.5)^2} - \frac{1}{2(I-.5)^3} w_{I-1,v} + (1 - \frac{1}{(I-.5)}) w_{I-2,v}$$

$$+ (\frac{2}{(I-.5)^2 \lambda^2} - \frac{1}{(I-.5)^3 \lambda^2}) w_{I+1,v+1} + (\frac{2}{(I-.5)^2 \lambda^2} - \frac{1}{(I-.5)^3 \lambda^2}) w_{I+1,v-1}$$

$$\begin{aligned}
& + \left(\frac{1}{(I-5)^4 \lambda^4} w_{I,v+2} + \left(-\frac{4}{(I-5)^4 \lambda^4} - \frac{4}{(I-5)^2 \lambda^2} + \frac{4}{(I-5)^4 \lambda^2} \right) w_{I,v+1} \right. \\
& + \left. \left(-\frac{4}{(I-5)^4 \lambda^4} - \frac{2}{(I-5)^2 \lambda^2} + \frac{4}{(I-5)^4 \lambda^2} \right) w_{I,v-1} \right. \\
& + \left. \left(\frac{1}{(I-5)^4 \lambda^4} w_{I,v-2} + \left(\frac{2}{(I-5)^2 \lambda^2} + \frac{1}{(I-5)^3 \lambda^2} \right) w_{I-1,v+1} \right. \right. \\
& + \left. \left. \left(\frac{2}{(I-5)^2 \lambda^2} + \frac{1}{(I-5)^3 \lambda^2} \right) w_{I-1,v-1} \right. \right. \\
& \dots \dots \dots \quad (2.30)
\end{aligned}$$

Now by eliminating $P_{I,v}$ between the equations (2.29) and (2.27), the final form of the generalised equation for plates on elastic foundation is given by,

$$\begin{aligned}
& \frac{\lambda E_s}{(1-\nu^2) \delta} w_{J,n} + \sum_I \sum_v \frac{(I-5)D}{\delta} \gamma_{(I,J,K)} f(w) \\
& = \sum_I \sum_v \gamma_{(I,J,K)} \frac{q_{I,v}}{\lambda \xi^2} \\
& \dots \dots \dots \quad (2.31)
\end{aligned}$$

2.3.5 Non-dimensional Form of the Generalised Plate Equation

The generalised equation of plate as given by equation (2.31) is not non-dimensional because it contains terms like E_s, D , which are dependent on plate properties and quantities like δ , which depends upon the plate dimension. Now to make the equation (2.31)

non-dimensional both sides of the equation are divided by $(1-\nu^2)/\lambda E_s$ to obtain the following equation,

$$\begin{aligned} \frac{w_{J,n}}{\delta} + \sum_I \sum_v \frac{D}{\delta^3} \frac{(1-\nu^2)}{\lambda E_s} \gamma_{(I,J,K)} \frac{1}{\delta} f(w) (I-5) \\ = \sum_I \sum_v \gamma_{(I,J,K)} \frac{(1-\nu^2) q_{I,v}}{\lambda \lambda E_s \delta^2} \dots \dots \quad (2.32) \end{aligned}$$

Now if the following quantities are considered

$$\bar{w} = \frac{w}{\delta} \quad (2.33)$$

$$\begin{aligned} \bar{D} &= \frac{D}{\delta^3} \frac{(1-\nu^2)}{\lambda E_s} \\ &= \frac{1}{12\lambda} \frac{E_p}{E_s} \left(\frac{h}{\delta}\right)^3 \frac{(1-\nu^2)}{(1-\mu^2)} \quad (2.34) \end{aligned}$$

$$\bar{q}_{I,v} = \frac{q_{I,v}}{E_s \delta^2} \frac{1}{\lambda \lambda} (1-\nu^2) \quad (2.35)$$

then it can be seen that the quantities \bar{w} , \bar{D} and $\bar{q}_{I,v}$ are all non-dimensional. Now let $f(\bar{w}) = \frac{1}{\delta} f(w)$ such that all the terms in $f(\bar{w})$ are terms containing $(w_{I,v})/\delta$, $(w_{I-1,v})/\delta$ etc, then it can be seen that $f(\bar{w})$ is also non-dimensional. So the above equation (2.32) becomes,

$$\bar{w}_{J,n} + \sum_I \sum_v \bar{D} (I-5) \gamma_{(I,J,K)} f(\bar{w}) = \sum_I \sum_v \gamma_{(I,J,K)} \bar{q}_{I,v}$$

Equation (2.36) is the non-dimensional form of the generalised plate equation.

2.3.6 Non-dimensional Form of the Moment Equations

In section 2.2.2 it was shown that the moments M_p and M_θ per unit length are given by equations (2.7) and (2.8) respectively. By multiplying both sides of these equations by $(1-\nu^2)/\lambda E_s \delta^2$ and defining the following quantities,

$$\tilde{M}_p = M_p \frac{(1-\nu^2)}{\lambda E_s \delta^2} \quad (2.37)$$

$$\tilde{M}_\theta = M_\theta \frac{(1-\nu^2)}{\lambda E_s \delta^2} \quad (2.38)$$

the following equations may be obtained

$$\begin{aligned} \tilde{M}_p = -\tilde{D} \left[\tilde{w}_{I+1,v} \left(1 + \frac{\mu}{2(I-0.5)} \right) + \tilde{w}_{I,v} \left(-2 - \frac{2\mu}{(I-0.5)^2 \lambda^2} \right) \right. \\ \left. + \tilde{w}_{I-1,v} \left(1 - \frac{\mu}{2(I-0.5)} \right) + \frac{\mu}{(I-0.5)^2 \lambda^2} (\tilde{w}_{I,v+1} + \tilde{w}_{I,v-1}) \right] \dots \dots \quad (2.39) \end{aligned}$$

$$\begin{aligned} \tilde{M}_\theta = -\tilde{D} \left[\tilde{w}_{I+1,v} \left(\frac{1}{2(I-0.5)} + \mu \right) + \tilde{w}_{I,v} \left(-\frac{2}{(I-0.5)^2 \lambda^2} - 2\mu \right) \right. \\ \left. + \tilde{w}_{I-1,v} \left(\frac{1}{2(I-0.5)} + \mu \right) + \frac{1}{(I-0.5)^2 \lambda^2} (\tilde{w}_{I,v+1} + \tilde{w}_{I,v-1}) \right] \dots \dots \quad (2.40) \end{aligned}$$

The quantities \bar{M}_ρ and \bar{N}_θ are non-dimensional and thus equations (2.39) and (2.40) are the non-dimensional moment equations.

2.3.7 Boundary Conditions

In the present problem the boundary of the plate is assumed to be free. For this case the boundary conditions are,

$$M_\rho = 0 \quad (2.41)$$

$$Q_\rho = 0 \quad (2.42)$$

$$M_{\rho\theta} = 0 \quad (2.43)$$

at the edges.

Kirchoff found that the third condition is a superfluous one, and can be combined with the second. Thus the two boundary conditions for the present problem can be expressed as,

$$(M_\rho)_{\rho=a} = -D \left[\frac{\partial^2 w}{\partial \rho^2} + \mu \left(\frac{1}{\rho} \frac{\partial w}{\partial \rho} + \frac{1}{\rho^2} \frac{\partial^2 w}{\partial \theta^2} \right) \right]_{\rho=a} = 0 \quad \dots \dots \quad (2.44)$$

$$\text{and, } (v)_\rho=a = (Q_\rho - \frac{1}{\rho} \frac{\partial M_\rho}{\partial \theta})_{\rho=a} = 0 \quad \dots$$

$$\text{or, } -D \left[\frac{\partial^2 w}{\partial \rho^3} + \frac{1}{\rho} \frac{\partial^2 w}{\partial \rho^2} - \frac{1}{\rho^2} \frac{\partial w}{\partial \rho} - \frac{(3-\mu)}{\rho^3} \frac{\partial^2 w}{\partial \theta^2} \right. \\ \left. + \frac{(2-\mu)}{\rho^2} \frac{\partial^3 w}{\partial \rho \partial \theta^2} \right]_{\rho=a} = 0 \quad \dots \dots \quad (2.45)$$

where a = Radius of the plate. In this particular problem $a = 6$.

The equations (2.44) and (2.45), when expressed in finite difference form become,

$$\begin{aligned}
 & \frac{1}{2} w_{a+2,v} + \left(-\frac{\mu}{2a^2 \lambda^2} \right) w_{a+1,v-1} + \left(-\frac{1}{2} + \frac{\mu}{a} - \frac{\mu}{a^2 \lambda^2} \right) w_{a+1,v} \\
 & + \left(-\frac{\mu}{2a^2 \lambda^2} \right) w_{a+1,v+1} + \left(-\frac{\mu}{2a^2 \lambda^2} \right) w_{a,v-1} + \left(-\frac{1}{2} - \frac{\mu}{a} - \frac{\mu}{a^2 \lambda^2} \right) w_{a,v} \\
 & + \left(\frac{\mu}{2a^2 \lambda^2} \right) w_{a,v+1} + \frac{1}{2} w_{a-1,v} = 0 \\
 & \dots \dots \quad (2.46)
 \end{aligned}$$

$$\begin{aligned}
 \text{and, } & \left(1 + \frac{1}{2a} \right) w_{a+2,v} + \left(\frac{2-\mu}{a^2 \lambda^2} - \frac{3-\mu}{2a^3 \lambda^2} \right) w_{a+1,v-1} \\
 & + \left(-3 - \frac{1}{2a} - \frac{1}{a^2} - \frac{2(2-\mu)}{a^2 \lambda^2} + \frac{(3-\mu)}{a^3 \lambda^2} \right) w_{a+1,v} \\
 & + \left(\frac{2-\mu}{a^2 \lambda^2} - \frac{3-\mu}{2a^3 \lambda^2} \right) w_{a+1,v+1} + \left(-\frac{2-\mu}{a^2 \lambda^2} - \frac{3-\mu}{2a^3 \lambda^2} \right) w_{a,v-1} \\
 & + \left(3 - \frac{1}{2a} + \frac{1}{a^2} + \frac{2(2-\mu)}{a^2 \lambda^2} + \frac{(3-\mu)}{a^3 \lambda^2} \right) w_{a,v} \\
 & + \left(-\frac{2-\mu}{a^2 \lambda^2} - \frac{3-\mu}{2a^3 \lambda^2} \right) w_{a,v+1} + \left(-1 + \frac{1}{2a} \right) w_{a-1,v} = 0 \\
 & \dots \dots \quad (2.47)
 \end{aligned}$$

The equations (2.46) and (2.47) can be written in a chart form as shown in Charts 4 and 5.

To convert these equations to non-dimensional form, what is to be done is simply to divide the equations by \mathcal{D} , so that w 's are replaced by \tilde{w} 's.

2.4 Method of Solution of the Problem

2.4.1 Calculation of γ (I,J,K)

In the present problem the contact area of the circular plate has been divided into 144 elements by 24 radial lines and 6 concentric circles as shown in Fig. 2.1. The extra 48 elements, shown by dotted lines, are auxiliary elements which are needed to get the finite difference equations for the boundary conditions. Since there is no plate at those elements, the γ (I,J,K) values for them will be zero.

While calculating the γ (I,J,K) values on digital computer the value of K is taken as $|n-v| + 1$ instead of $|n-v|$ as a digital computer does not accept a zero or negative subscript in FORTRAN IV language. So in this case the angle between two elements I-v and J-n is $(K-1)\lambda$ and not $K\lambda$.

From symmetry of the problem along any diameter it is obvious that it is sufficient to calculate γ (I,J,K) for K varying from 1 to 13, because for each J-n element there will be two I-v elements which are symmetrically placed on either side of the diameter passing through the centre of J-n element. The γ (I,J,K) values for these two I-v elements will be the same. So that we will have γ (I,J,K) = γ (I,J,26-K) for $K > 1$.

2.4.2 Method of Solution for Deflections

The present problem deals with a single concentrated load at the centre of any of the 144 elements of the plate. As will be

clear later, in Chapter 3, this case is the general case of loading and the solution for any particular loading case can be obtained from this solution by proper superimposition.

Again referring to the symmetry of the problem on either side of the diameter passing through the load point it is obvious that the deflection pattern of the plate will also be symmetrical about the same diameter. Thus it is sufficient to solve for the deflection pattern of only half of the plate, viz., for sectors 1 to 13, to describe the deflection pattern of the whole plate.

Now it is possible to write down 78 numbers of equations from the general form of the equation (2.36), one for each of the J-n elements in the sectors 1 through 13. Since the I-v elements are to be summed over the whole of the plate, terms containing deflections of each of the elements including the imaginary elements will be present in each of these equations. Thus each equation will have 104 unknown deflections, viz., the deflections of the 78 real elements and the 26 auxiliary elements. There will be only 104 unknowns and not 192 because it has already been noted that there is a diametral symmetry of the problem. So by using equation (2.36) 78 simultaneous equations in 104 unknowns are obtained. The rest 26 equations are obtained from the two boundary conditions given by equations (2.46) and (2.47), satisfying both of them for each sector. Finally these 104 equations in 104 unknowns are solved on the computer to get the deflections.

The simple basis of the method outlined above, presents great trouble in getting the co-efficients for each of the 104 unknown deflections in each of the equations. To get the co-efficients of each unknown deflection in each equation, it has to be kept in mind that in the basic equation (2.36), the J-n element is taken as the fixed point and the biharmonic part has been written and summed for each of the 192 I-v elements of the plate. So to get the co-efficient for any generalised I-v element, its co-efficients from the different biharmonic equations have to be collected. It may be recollected that in writing the finite difference expansion for the biharmonic equation about any I-v element, thirteen numbers of I-v elements have to be incorporated. Thus when collecting co-efficient of a particular I-v element in a particular equation all thirteen biharmonic expansions about these neighbouring thirteen points will contribute towards the co-efficient. Keeping this in view, for any generalised element I-v, its co-efficients in collected form can be expressed as,

$$\begin{aligned}
 C(I, v) = & \bar{D} \left[(I-0.5) \varphi(I, J, K) \left(6 + \frac{3}{(I-0.5)^4 \lambda^4} + \frac{8}{(I-0.5)^2 \lambda^2} \right. \right. \\
 & \left. \left. - \frac{3}{(I-0.5)^4 \lambda^2} + \frac{2}{(I-0.5)^2} \right) + (I-2.5) \varphi(I-2, J, K) \left(1 + \frac{1}{I-2.5} \right) \right. \\
 & \left. + (I-1.5) \varphi(I-1, J, K) \left(-4 - \frac{4}{(I-1.5)^2 \lambda^2} - \frac{2}{(I-1.5)} \right. \right. \\
 & \left. \left. + \frac{2}{(I-1.5)^3 \lambda^2} - \frac{1}{(I-1.5)^2} + \frac{1}{2(I-1.5)^3} \right) \right]
 \end{aligned}$$

$$\begin{aligned}
& + (I+.5) \gamma_{(I+1,J,K)} \left(-4 - \frac{4}{(I+.5)^2 \lambda^2} + \frac{2}{(I+.5)} - \frac{2}{(I+.5)^3 \lambda^2} \right. \\
& \quad \left. - \frac{1}{(I+.5)^2} - \frac{1}{2(I+.5)^3} \right) + (I+1.5) \gamma_{(I+2,J,K)} \left(1 - \frac{1}{I+1.5} \right) \\
& + (I-.5) \gamma_{(I,J,K-2)} \left(\frac{1}{(I-.5)^4 \lambda^4} \right) + (I-.5) \gamma_{(I,J,K-1)} \\
& \quad \left(- \frac{4}{(I-.5)^4 \lambda^4} - \frac{4}{(I-.5)^2 \lambda^2} - \frac{4}{(I-.5)^4 \lambda^2} \right) + (I-.5) \gamma_{(I,J,K+1)} \\
& \quad \left(- \frac{4}{(I-.5)^4 \lambda^4} - \frac{4}{(I-.5)^2 \lambda^2} - \frac{4}{(I-.5)^4 \lambda^2} \right) + (I-.5) \gamma_{(I,J,K+2)} \\
& \quad \left(\frac{1}{(I-.5)^4 \lambda^4} \right) + (I-1.5) \gamma_{(I-1,J,K-1)} \left(\frac{2}{(I-1.5)^2 \lambda^2} - \frac{1}{(I-1.5)^3 \lambda^2} \right) \\
& + (I-1.5) \gamma_{(I-1,J,K+1)} \left(\frac{2}{(I-1.5)^2 \lambda^2} - \frac{1}{(I-1.5)^3 \lambda^2} \right) \\
& + (I+.5) \gamma_{(I+1,J,K-1)} \left(\frac{2}{(I+.5)^2 \lambda^2} + \frac{1}{(I+.5)^3 \lambda^2} \right) \\
& + (I+.5) \gamma_{(I+1,J,K+1)} \left(\frac{2}{(I+.5)^2 \lambda^2} + \frac{1}{(I+.5)^3 \lambda^2} \right) \\
& \quad \dots \dots \quad (2.48)
\end{aligned}$$

To calculate various $C(I,v)$'s in various equations, by using equation (2.48) the following points have to be kept in mind,

- (i) The value of n varies from 1 to 13.
- (ii) The value of J varies from 1 to 6.
- (iii) The value of I varies from 1 to 8.
- (iv) The value of v varies from 1 to 24.
- (v) $\gamma_{(I,J,K)}$ for $I > 6$ is zero.

(vi) If $I = 2$ then the term containing $\gamma(I-2, J, K)$ has to be replaced by,

$$(I-1.5) \gamma(I-1, J, K+12) \left(1 - \frac{1}{I-1.5}\right)$$

because in that case the $(I-2, v)$ element becomes $(I-1, v+12)$ element.

(vii) If $I = 1$ then

(a) The term containing $\gamma(I-2, J, K)$ has to be replaced by,

$$(I+.5) \gamma(I+1, J, K+12) \left(1 - \frac{1}{I+.5}\right)$$

(b) The term containing $\gamma(I-1, J, K)$ has to be replaced by,

$$(I-.5) \gamma(I, J, K+12) \left(-4 - \frac{4}{(I-.5)^2 \lambda^2} + \frac{2}{(I-.5)} - \frac{1}{(I-.5)^3 \lambda^2} - \frac{1}{(I-.5)^2} - \frac{1}{2(I-.5)^3}\right)$$

(c) The term containing $\gamma(I-1, J, K+1)$ has to be replaced by,

$$(I-.5) \gamma(I, J, K+11) \left(\frac{2}{(I-.5)^2 \lambda^2} + \frac{1}{(I-.5)^3 \lambda^2}\right)$$

(d) The term containing $\gamma(I-1, J, K-1)$ has to be replaced by,

$$(I-.5) \gamma(I, J, K+13) \left(\frac{2}{(I-.5)^2 \lambda^2} + \frac{1}{(I-.5)^3 \lambda^2}\right)$$

The co-efficients as obtained by using equation (2.48) have to be properly grouped together by using the symmetry property of the problem. While grouping it has to be kept in mind that from

symmetry of the problem for $I \neq 1$ and $I \neq 13$

$$\bar{w}(I, v) = \bar{w}(I, 26-v) \quad (2.49)$$

After doing the grouping of the co-efficients by using equation (2.49), the co-efficient of the first term $\bar{w}_{J,n}$ in equation (2.38) has to be added to the co-efficient of the proper $\bar{w}(I, v)$ in the equation.

Thus 104 simultaneous equations in 104 unknown deflections are obtained. These equations are solved by inverting the co-efficient matrix (this is possible because the matrix is non-singular), using Gauss-Jordan method, to get the deflections of the 104 elements. This is done by varying the load position six times, each time the load being at a different radial position.

Everytime for the sector in which the load is acting, it is assumed, $n = 1$ and $v = 1$, i.e., this is taken as the reference.

The whole method is repeated for five different values of \bar{D} and five different values of μ . Everytime $\bar{q}_{I,v}$ is taken as unity.

Finally the results are given in the form of polynomial equations involving the different independent variables for each sector. The co-efficients have been tabulated. By using the method as described in section 3.4 the deflection pattern for all cases can be determined.

I+2, V

$$\frac{1}{64} \left[1 + \frac{1}{(1-5)} \right]$$

I+1, V-1

$$\frac{1}{64} \left[\frac{2}{(1-5)^2 \lambda^2} - \frac{1}{(1-5)^3 \lambda^2} \right]$$

I+1, V

$$\frac{1}{64} \left[\frac{4}{(1-5)^2 \lambda^2} - \frac{2}{(1-5)^3 \lambda^2} - \frac{1}{(1-5)^2} - \frac{2}{2(1-5)^3} \right]$$

I+1, V+1

$$\frac{1}{64} \left[\frac{2}{(1-5)^2 \lambda^2} - \frac{1}{(1-5)^3 \lambda^2} \right]$$

I, V-2

$$\frac{1}{64} \left[\frac{1}{(1-5)^2 \lambda^4} \right]$$

I, V

$$\frac{1}{64} \left[\frac{6}{(1-5)^4 \lambda^4} + \frac{8}{(1-5)^2 \lambda^2} - \frac{8}{(1-5)^4 \lambda^2} - \frac{2}{(1-5)^2} \right]$$

I, V+2

$$\frac{1}{64} \left[\frac{4}{(1-5)^4 \lambda^4} - \frac{4}{(1-5)^2 \lambda^2} + \frac{4}{(1-5)^3 \lambda^2} - \frac{2}{(1-5)^2} - \frac{2}{2(1-5)^3} \right]$$

I+1, V+2

$$\frac{1}{64} \left[\frac{2}{(1-5)^2 \lambda^2} - \frac{1}{(1-5)^3 \lambda^2} \right]$$

I-1, V-1

$$\frac{1}{64} \left[\frac{2}{(1-5)^2 \lambda^2} + \frac{1}{(1-5)^3 \lambda^2} - \frac{1}{(1-5)^2} - \frac{1}{2(1-5)^3} \right]$$

I-1, V



$$\frac{1}{64} \left[\frac{4}{(1-5)^4 \lambda^4} - \frac{4}{(1-5)^2 \lambda^2} + \frac{4}{(1-5)^3 \lambda^2} - \frac{2}{(1-5)^2} - \frac{2}{2(1-5)^3} \right]$$

I-1, V+1

$$\frac{1}{64} \left[\frac{2}{(1-5)^2 \lambda^2} + \frac{1}{(1-5)^3 \lambda^2} \right]$$

I-2, V

$$\frac{1}{64} \left[\frac{1}{1-(1-5)} \right]$$

CHART 2 - FINITE DIFFERENCE EXPRESSION FOR M_ϕ CHART 3 - FINITE DIFFERENCE EXPRESSION FOR M_θ

	a+2,v	
		$\frac{1}{2}$
a+1,v-1	a+1,v	a+1,v+1
$\frac{\mu}{2a^2\lambda^2}$	$-\frac{1}{2} + \frac{\mu}{a} - \frac{\mu}{a^2\lambda^2}$	$\frac{\mu}{2a^2\lambda^2}$
a,v-1	a,v	a,v+1
$\frac{\mu}{2a^2\lambda^2}$	$-\frac{1}{2} - \frac{\mu}{a} - \frac{\mu}{a^2\lambda^2}$	$\frac{\mu}{2a^2\lambda^2}$
	a-1,v	
		$\frac{1}{2}$

CHART 4 - FIRST BOUNDARY CONDITION $(M_f)_{f=a}$

	a+2,v	
		$1 + \frac{1}{2a}$
a+1,v-1	a+1,v	a+1,v+1
$\frac{2-\mu}{a^2\lambda^2} - \frac{3-\mu}{2a^3\lambda^2}$	$-3 - \frac{1}{2a} - \frac{1}{a^2} - \frac{2(2-\mu)}{a^2\lambda^2} + \frac{3-\mu}{a^3\lambda^2}$	$\frac{2-\mu}{a^2\lambda^2} - \frac{3-\mu}{2a^3\lambda^2}$
a,v-1	a,v	a,v+1
$-\frac{2-\mu}{a^2\lambda^2} - \frac{3-\mu}{2a^3\lambda^2}$	$3 - \frac{1}{2a} + \frac{1}{a^2} + \frac{2(2-\mu)}{a^2\lambda^2} + \frac{3-\mu}{a^3\lambda^2}$	$-\frac{2-\mu}{a^2\lambda^2} - \frac{3-\mu}{2a^3\lambda^2}$
	a-1,v	
		$-1 + \frac{1}{2a}$

CHART 5 - SECOND BOUNDARY CONDITION $(v_f)_{f=a}$





FIG-2.1 GRID ARRANGEMENTS





FIG. 2.2 CO-ORDINATE SYSTEM




FIG. 2.3 GRAPHICAL REPRESENTATION OF THE METHOD FOR DETERMINATION OF $\gamma(i,j,k)$





FIG. 2.4 DETERMINATION OF THE RADII AND THE ANGLE

CHAPTER III

RESULTS AND DISCUSSION

3.1 General Discussion

In the generalised nondimensional equation (2.36) terms containing properties of subgrade are \bar{D} and \bar{q}_{I-v} and therefore various kinds of settlement characteristics can be accommodated.

For solving the present problem the contact area of the subgrade and the plate has been divided into a number of elements by radial lines and concentric circles. The pressure intensity within one particular element has been assumed to remain constant. So it is obvious that the accuracy of the method will depend upon the fineness of the grid arrangement. The points at which the finite difference equations have been written are taken as the central points of the elements and not the intersection of the two sets of grid lines, as is conventionally done. The reason being that if there is a concentrated load at such a grid point it can be assumed with reasonable accuracy that the load is uniformly distributed over the whole element. But if the grid points were taken as the intersection, this could not have been done.

It was seen that the deflection co-efficients $\psi(I, J, K)$ involve elliptic integrals. In the present analysis these integrals have been evaluated by numerical integration using Simpson's Rule. Another method of approximately evaluating these integrals, as used by Ghosh and Chatterjee⁶, is to assume that the approximate values of the integrals are $m'n'$ and $m''n''$ as shown in Fig. 3.1. The values of $\psi(I, J, K)$ calculated by both the methods are quite near except for the elements in the central zone. The reason probably is that the assumptions of the latter method are not acceptable there. The deflection as obtained by using the present method of calculating $\psi(I, J, K)$ by numerical integration are in better agreement with the experimental results.

The present method is perfectly general in the sense that once the results for the present problem of a single concentrated load at various radial positions are known the solution for any particular loading condition can be very easily obtained by proper superposition. To demonstrate how this can be done a few examples for various types of loadings have been solved in the section 3.3.

As the present analysis is non-dimensional it can be used for any plate dimension and any plate or subgrade material.

Though there may be some inaccuracy in the deflection pattern for a single concentrated load (specially when the load is near the central zone), the results are found to be sufficiently consistent and accurate when there is a number of concentrated loads or when the load is distributed over a considerable portion of the plate.

3.2 Results

In the present work the non-dimensional deflection \bar{w} , moments \bar{M}_p and \bar{M}_θ have been calculated for 25 different combinations of \bar{D} and μ (five different values of \bar{D} and five different values of μ). This covers quite a wide range of situations that may arise in practice.

A sample set of results for $\bar{D} = .01$ and $\mu = .2$ are given in Tables 1 through 3. The deflection contours for this case are shown in Fig. 3.2 through Fig. 3.7.

But the main object of the present work is to provide the designers with some simple and ready-made method of solution for circular plates on elastic foundation. This is done by presenting the final results in the form of polynomial equation in terms of the independent variables like, \bar{D} , μ , the co-ordinates of a particular point and also the load position. One polynomial equation is given for each of the thirteen sectors. The method used to determine the polynomials is given in Appendix B. The co-efficients of the polynomial equations are given in Tables 14 A through M. The method of determining the deflections for various cases of loadings, by using these co-efficients, has been discussed in section 3.4.

3.3 Examples

Example 1: In this case the deflections for two equally spaced concentrated loads have been determined. The loads are in

sectors 1 and 13. From symmetry it is seen that it is sufficient to calculate the deflections only for the elements in sectors 1 through 7. To determine the deflection of any particular element we have to add algebraically the deflections of that element due to the two loads. The results are shown in Table 4.

Example II : In this example the deflections for three equally spaced loads have been obtained. The loads are assumed to be at sectors 1, 9 and 17. From symmetry of the problem it is seen that it is sufficient to calculate the deflections of the elements in sectors 1 through 5. Here to get the deflection, the deflections due to the three loads are to be added algebraically. The results are shown in Table 5.

Example III : In this example the deflections due to four equally spaced loads have been calculated. The loads are assumed to be in sectors 1, 7, 13 and 19. From symmetry, it is sufficient to calculate deflections of the elements in sectors 1 through 4. Here the deflections due to the four different loads are to be added. The results are shown in Table 6.

Example IV : In this example the deflections due to six equally spaced loads have been calculated. The loads are at sectors 1, 5, 9, 13, 17 and 21. Here it is sufficient to calculate the deflections for elements in sectors 1 through 3. in this case the deflections due to the six loads are to be added. The results are shown in Table 7. The deflection contours when the loads are on the fifth pitch circle are shown in Fig. 3.8.

Example V : In this example the deflections due to eight equally spaced concentrated loads have been calculated. The loads are at sectors 1,4,7,10,13,16,19 and 22. Here it is sufficient to calculate the deflections of the 12 elements in the first two sectors. In this case the deflections due to the eight different loads are to be added. Results are shown in Table 8.

Example VI : In this example the deflections due to twelve equally spaced concentrated loads have been calculated. The loads are assumed to be at sectors 1,3,5,7,9,11,13,15,17,19,21 and 23. Here also it is sufficient to calculate the deflections of the 12 elements in the first two sectors. In this case the deflections due to the twelve loads are to be added. The results are shown in Table 9.

Example VII : In this example the deflections due to a ring load have been calculated. In this case from the symmetry of the problem it is seen that the deflection is independent of Θ and hence it is sufficient to calculate the deflections for the six elements in sector 1. Here the deflections due to the loads in the 24 elements of the ring are to be added algebraically. The results are shown in Table 10.

Example VIII : In this example the deflections due to a diametral line load have been calculated. The load line is assumed to be the centre line of sector 1 and sector 13. Here from symmetry of the problem it is seen that it is sufficient to calculate the deflections of the elements in sectors 1 through 13. Here the

deflections due the loads on the 12 elements of the load line has to be added. The results are shown in Table 12. The deflection contour has been shown in Fig. 3.10.

Example IX : In this example deflections for a radial line load have been calculated. The load line is assumed to be the central line of sector 1. Here from symmetry it is necessary to calculate the deflections of the elements in sectors 1 through 13. In this case the deflections due to the six load on six elements of the load line are to be added. The results are shown in Table 11. The deflection contour has been shown in Fig. 3.9.

Example X : In this example deflections for a uniformly distributed load over the whole plate has been calculated. Here it has to be noted that the loads on the various elements are not equal because in this case the load is directly proportional to the area of the particular element. It has been assumed that the load on the elements (1,v) are unity. The loads at the other elements have been calculated accordingly. From symmetry of the problem it is seen that as in Example VII here also the deflections will be independent of θ and hence it is sufficient to calculate the deflections only for the six elements in the first sector. In this case the deflections due to the loads on each of the 144 elements of the plate are to be added. The results are shown in Table 13, The corresponding pressure is found to $(2/\lambda \delta^2)$.

3.4 Discussion on Results

The results obtained by the present method have been compared with some experimental results for the case of six concentrated loads, given by Chatterjee and Ghosh⁶. The agreement of the results are quite good. The maximum variation is about 20% very near the centre of the plate where the deflection is not very important. The variation in the maximum deflection is only about 1.5%. The deflection obtained by the present theoretical method is on the safer side. What is more important is that the nature of variation of the deflection as obtained by this method is almost the same as in experimental case. This has been shown in Fig. 3.11.

From the results obtained it is seen that the deflections are the maximum under the load points in the case of single concentrated load. This is quite reasonable. One more point to be noted is that though the deflection pattern as a whole depends to some extent on the value of Poisson's Ratio, μ , of the plate, the maximum deflection is almost independent of μ . The variation being of only about 5% when μ is changed from .1 to .4.

From the results obtained it has been found that though at certain points far away from the load point deflections may increase with the increase in \bar{D} , due to some change in the deflection pattern, the maximum deflection decreases substantially with the increase in \bar{D} . This is what one expects.

From the deflection contours it is seen that away from the load point the contours become almost circles, with the centre at the load point, which is reasonable. Near the load point the eccentricity of the load plays an important role and thus the contours are no longer circular in nature.

From the results it has been found that as the load point is moved away from the centre of the plate the maximum deflection under the load at first decreases and then increases. It has been found that this deflection reaches a minimum when the load is at the fifth radial position for small values of \bar{D} and at fourth radial position when \bar{D} is larger. Same are the positions in the case of \bar{M}_ϕ and \bar{M}_θ .

To use the coefficients of the polynomial functions one has to keep in mind that the co-efficients are numbered 1 to 750. To get the deflections for a particular case, first \bar{D} has to be calculated. Then for the proper μ and load position the deflections for the various elements in each of the sectors can be calculated by using the Computer Program No.2 in Appendix C.

For all the results $\bar{q}_{I,v}$ is assumed to be unity. To get the deflections and moments for a particular load the quantities calculated will have to be multiplied by the proper $\bar{q}_{I,v}$, calculated from equation (2.35) for the particular load. This is possible because $\bar{q}_{I,v}$ appears on the right hand side of the generalised equation (2.36) for each and every I and v .

TABLE 1 - NONDIMENSIONAL DEFLECTIONS
 $D=0.01$ AND $\mu=0.2$

A. FOR LOAD AT RADIAL POSITION NO=1

111.1000 PUR
 CEN
 571
 Acc. 73

ECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1104E 01	0.3930E 00	0.1675E 00	0.1006E 00	0.7230E-01	0.5642E-01
2	0.1041E 01	0.3766E 00	0.1632E 00	0.9904E-01	0.7152E-01	0.5593E-01
3	0.8893E 00	0.3339E 00	0.1517E 00	0.9479E-01	0.6934E-01	0.5453E-01
4	0.6904E 00	0.2763E 00	0.1357E 00	0.8868E-01	0.6612E-01	0.5244E-01
5	0.4864E 00	0.2160E 00	0.1184E 00	0.8176E-01	0.6239E-01	0.5001E-01
6	0.3129E 00	0.1634E 00	0.1027E 00	0.7510E-01	0.5868E-01	0.4756E-01
7	0.1939E 00	0.1253E 00	0.9054E-01	0.6950E-01	0.5545E-01	0.4546E-01
8	0.1386E 00	0.1049E 00	0.8275E-01	0.6538E-01	0.5291E-01	0.4380E-01
9	0.1418E 00	0.1007E 00	0.7925E-01	0.6279E-01	0.5114E-01	0.4263E-01
10	0.1856E 00	0.1084E 00	0.7905E-01	0.6152E-01	0.5006E-01	0.4191E-01
11	0.2450E 00	0.1212E 00	0.8065E-01	0.6112E-01	0.4950E-01	0.4152E-01
12	0.2941E 00	0.1323E 00	0.8232E-01	0.6112E-01	0.4927E-01	0.4135E-01
13	0.3131E 00	0.1367E 00	0.8317E-01	0.6117E-01	0.4921E-01	0.4131E-01

B. FOR LOAD AT RADIAL POSITION NO=2

ECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.2970E 00	0.8090E 00	0.3054E 00	0.1443E 00	0.9086E-01	0.6652E-01
2	0.2901E 00	0.6064E 00	0.2593E 00	0.1345E 00	0.8791E-01	0.6526E-01
3	0.2710E 00	0.3957E 00	0.1937E 00	0.1162E 00	0.8101E-01	0.6188E-01
4	0.2437E 00	0.2588E 00	0.1415E 00	0.9904E-01	0.7274E-01	0.5732E-01
5	0.2134E 00	0.1823E 00	0.1193E 00	0.8470E-01	0.6484E-01	0.5229E-01
6	0.1849E 00	0.1412E 00	0.1005E 00	0.7508E-01	0.5922E-01	0.4754E-01
7	0.1623E 00	0.1184E 00	0.8718E-01	0.6784E-01	0.5470E-01	0.4491E-01
8	0.1474E 00	0.1052E 00	0.7932E-01	0.6237E-01	0.5099E-01	0.4261E-01
9	0.1402E 00	0.9746E-01	0.7354E-01	0.5834E-01	0.4812E-01	0.4065E-01
10	0.1392E 00	0.9329E-01	0.6976E-01	0.5551E-01	0.4601E-01	0.3913E-01
11	0.1417E 00	0.9134E-01	0.6745E-01	0.5366E-01	0.4460E-01	0.3806E-01
12	0.1446E 00	0.9062E-01	0.6623E-01	0.5262E-01	0.4379E-01	0.3744E-01
13	0.1459E 00	0.9046E-01	0.6585E-01	0.5229E-01	0.4353E-01	0.3723E-01

C. FOR LOAD AT RADIAL POSITION NO=3

CTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1340E 00	0.2943E 00	0.7968E 00	0.3072E 00	0.1433E 00	0.8851E-01
2	0.1328E 00	0.2541E 00	0.4373E 00	0.2229E 00	0.1253E 00	0.8367E-01
3	0.1292E 00	0.1974E 00	0.2283E 00	0.1457E 00	0.9911E-01	0.7341E-01
4	0.1237E 00	0.1524E 00	0.1418E 00	0.1056E 00	0.7781E-01	0.6250E-01
5	0.1171E 00	0.1220E 00	0.1046E 00	0.8337E-01	0.6604E-01	0.5303E-01
6	0.1103E 00	0.1023E 00	0.8539E-01	0.6974E-01	0.5734E-01	0.4760E-01
7	0.1040E 00	0.8939E-01	0.7362E-01	0.6068E-01	0.5079E-01	0.4309E-01
8	0.9884E-01	0.8069E-01	0.6576E-01	0.5444E-01	0.4601E-01	0.3950E-01
9	0.9502E-01	0.7474E-01	0.6037E-01	0.5009E-01	0.4258E-01	0.3682E-01
0	0.9250E-01	0.7072E-01	0.5670E-01	0.4710E-01	0.4018E-01	0.3492E-01
1	0.9104E-01	0.6816E-01	0.5432E-01	0.4515E-01	0.3861E-01	0.3364E-01
2	0.933E-01	0.6673E-01	0.5299E-01	0.4404E-01	0.3771E-01	0.3291E-01
3	0.9012E-01	0.6628E-01	0.5256E-01	0.4368E-01	0.3742E-01	0.3267E-01

D. FOR LOAD AT RADIAL POSITION NO=4

CTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.8680E-01	0.1382E 00	0.2993E 00	0.7602E 00	0.3023E 00	0.1378E 00
2	0.8634E-01	0.1301E 00	0.221E 00	0.3255E 00	0.1916E 00	0.1146E 00
3	0.8496E-01	0.1148E 00	0.1485E 00	0.1554E 00	0.1143E 00	0.8506E-01
4	0.8282E-01	0.9945E-01	0.1072E 00	0.9907E-01	0.8147E-01	0.6438E-01
5	0.8015E-01	0.8653E-01	0.8409E-01	0.7486E-01	0.6397E-01	0.5367E-01
6	0.7724E-01	0.7644E-01	0.7004E-01	0.6142E-01	0.5310E-01	0.4576E-01
7	0.7439E-01	0.6881E-01	0.6085E-01	0.5289E-01	0.4595E-01	0.4009E-01
8	0.7182E-01	0.6313E-01	0.5455E-01	0.4715E-01	0.4108E-01	0.3609E-01
9	0.6969E-01	0.5898E-01	0.5017E-01	0.4320E-01	0.3771E-01	0.3327E-01
0	0.6806E-01	0.5604E-01	0.4716E-01	0.4050E-01	0.3539E-01	0.3131E-01
1	0.6693E-01	0.5408E-01	0.4519E-01	0.3875E-01	0.3388E-01	0.3002E-01
2	0.6628E-01	0.5296E-01	0.4407E-01	0.3775E-01	0.3302E-01	0.2929E-01
3	0.6607E-01	0.5260E-01	0.4371E-01	0.3743E-01	0.3275E-01	0.2906E-01

E. FOR LOAD AT RADIAL POSITION NO=5

CTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.6525E-01	0.8809E-01	0.1396E 00	0.2964E 00	0.7114E 00	0.2878E 00
2	0.6498E-01	0.8571E-01	0.1235E 00	0.1905E 00	0.2551E 00	0.1625E 00
3	0.6417E-01	0.7999E-01	0.1001E 00	0.1179E 00	0.1178E 00	0.8804E-01
4	0.6293E-01	0.7301E-01	0.8098E-01	0.8275E-01	0.7682E-01	0.6544E-01
5	0.6137E-01	0.6617E-01	0.6730E-01	0.6423E-01	0.5840E-01	0.5150E-01
6	0.5965E-01	0.6020E-01	0.5771E-01	0.5317E-01	0.4789E-01	0.4263E-01
7	0.5794E-01	0.5329E-01	0.5094E-01	0.4599E-01	0.4120E-01	0.3682E-01
8	0.5636E-01	0.5142E-01	0.4611E-01	0.4111E-01	0.3671E-01	0.3289E-01
9	0.5502E-01	0.4848E-01	0.4266E-01	0.3773E-01	0.3362E-01	0.3016E-01
0	0.5396E-01	0.4633E-01	0.4025E-01	0.3541E-01	0.3152E-01	0.2830E-01
1	0.5321E-01	0.4488E-01	0.3866E-01	0.3390E-01	0.3015E-01	0.2708E-01
2	0.5277E-01	0.4404E-01	0.3775E-01	0.3304E-01	0.2937E-01	0.2639E-01
3	0.5262E-01	0.4376E-01	0.3736E-01	0.3276E-01	0.2912E-01	0.2617E-01

F. FOR LOAD AT RADIAL POSITION NO=6

CTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.5210E-01	0.6505E-01	0.8694E-01	0.1350E 00	0.2827E 00	0.7244E 00
2	0.5192E-01	0.6397E-01	0.8262E-01	0.1133E 00	0.1625E 00	0.2115E 00
3	0.5139E-01	0.6107E-01	0.7217E-01	0.8626E-01	0.9538E-01	0.9373E-01
4	0.5057E-01	0.5717E-01	0.6323E-01	0.6690E-01	0.6654E-01	0.6226E-01
5	0.4955E-01	0.5303E-01	0.5480E-01	0.5426E-01	0.5159E-01	0.4759E-01
6	0.4642E-01	0.4917E-01	0.4823E-01	0.4587E-01	0.4265E-01	0.3908E-01
7	0.4728E-01	0.4583E-01	0.4328E-01	0.4013E-01	0.3684E-01	0.3363E-01
8	0.4623E-01	0.4309E-01	0.3959E-01	0.3612E-01	0.3290E-01	0.2997E-01
9	0.4531E-01	0.4095E-01	0.3689E-01	0.3330E-01	0.3017E-01	0.2745E-01
0	0.4458E-01	0.3935E-01	0.3497E-01	0.3134E-01	0.2831E-01	0.2573E-01
1	0.4405E-01	0.3824E-01	0.3368E-01	0.3005E-01	0.2709E-01	0.2461E-01
2	0.4374E-01	0.3760E-01	0.3295E-01	0.2931E-01	0.2640E-01	0.2398E-01
3	0.4363E-01	0.3739E-01	0.3271E-01	0.2908E-01	0.2617E-01	0.2377E-01

TABLE 2 .. NONDIMENSIONAL MOMENTS M_ϕ
 $D = .01$ AND $\mu = .2$

A. FOR LOAD AT RADIAL POSITION NO=1

TOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1870E 00-0.3203E-01	0.1623E-03	0.4479E-04	0.3843E-04	0.3741E-03	
2	-0.6001E-01	0.3190E-01	-0.1039E-01	0.2196E-04	-0.4044E-04	0.1342E-03
3	-0.1995E-01	-0.4914E-02	0.9487E-02	-0.4837E-02	0.3275E-05	-0.5439E-04
4	-0.5630E-02	-0.1835E-02	0.4169E-04	0.1956E-02	-0.1791E-02	-0.7145E-05
5	-0.4152E-02	-0.4495E-03	-0.1305E-03	-0.1822E-03	0.1476E-02	-0.1344E-02
6	-0.8156E-02	-0.1501E-03	-0.5261E-04	-0.5231E-04	-0.1404E-02	0.3891E-02
7	-0.1186E 00	0.2499E-04	-0.3100E-04	-0.4779E-04	-0.3403E-03	-0.1624E-02
8	0.2141E 00	-0.1805E-01	0.3070E-04	-0.3223E-04	-0.1176E-03	-0.4154E-03
9	-0.5399E-01	0.2368E-01	-0.7674E-02	0.1114E-04	-0.5097E-04	-0.1341E-03
0	-0.1827E-01	-0.2882E-02	0.5214E-02	-0.3030E-02	-0.3849E-05	-0.5477E-04
1	-0.5269E-02	-0.1167E-02	0.1081E-03	0.1158E-02	-0.1322E-02	0.8300E-04
2	-0.4170E-02	-0.3068E-03	-0.4161E-04	-0.8378E-03	0.2671E-02	-0.1824E-02
3	-0.1214E-01	-0.5856E-03	-0.2513E-03	-0.2944E-03	-0.1872E-02	0.4978E-02

B. FOR LOAD AT RADIAL POSITION NO=2

TOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	-0.1146E 00	-0.8370E-02	0.2408E-03	0.4170E-04	-0.1194E-04	-0.1123E-03
2	0.1308E 00	-0.1264E-02	-0.3112E-02	0.1230E-0	-0.1679E-04	-0.6935E-04
3	-0.3969E-01	0.7024E-02	0.1035E-02	-0.2114E-02	0.2730E-04	-0.3645E-04
4	-0.1408E-01	-0.1032E-02	0.2475E-03	0.1526E-02	-0.1462E-02	-0.1770E-05
5	-0.7825E-02	-0.3453E-03	-0.9338E-04	-0.2648E-03	0.1529E-02	-0.1221E-02
6	-0.2226E-02	-0.1124E-03	-0.6647E-03	-0.9261E-04	-0.3857E-03	0.1713E-02
7	-0.3146E-01	0.1158E-03	-0.3691E-04	-0.4592E-04	-0.1388E-03	-0.4063E-03
8	-0.3503E-02	-0.5210E-02	0.5421E-04	-0.2201E-04	-0.6471E-04	-0.1546E-03
9	0.8591E-01	0.1183E-02	-0.743E-02	0.1467E-0	-0.2921E-04	-0.7429E-04
0	-0.2502E-01	0.2410E-02	0.1726E-02	-0.1795E-02	0.1056E-04	-0.4195E-04
1	-0.1066E-01	-0.5805E-03	-0.1486E-03	0.1600E-02	-0.1325E-02	-0.1003E-04
2	-0.8697E-02	-0.2121E-03	-0.1062E-03	-0.3429E-03	0.1650E-02	-0.1227E-02
3	-0.7231E-02	-0.6373E-03	-0.2590E-03	-0.2258E-03	-0.5202E-03	0.1877E-02

C. FOR LOAD AT RADIAL POSITION NO=3

TOR

RADIAL POSITIONS

	1	2	3	4	5	6
1	-0.3596E-01-0.3154E-02	0.3643E-03	0.2611E-04-0.2716E-04	-0.6141E-04		
2	-0.3661E-01-0.4611E-03	-0.1219E-02	0.3020E-04-0.2946E-04	-0.5186E-04		
3	0.1276E 00-0.4254E-02	0.3617E-03	-0.9679E-03	0.9135E-05-0.3401E-04		
4	-0.3811E-01 0.1869E-02	-0.7292E-03	0.7476E-03-0.8121E-03	-0.9830E-05		
5	-0.1365E-01-0.6218E-05	-0.2185E-03	-0.2029E-03	0.8410E-03-0.7376E-03		
6	-0.1497E-02-0.4098E-05	-0.6791E-03	-0.1130E-03	-0.1642E-03	0.8810E-03	
7	-0.1630E-01 0.3620E-03	-0.3518E-04	-0.5615E-04	-0.8856E-04-0.1558E-03		
8	-0.2239E-02-0.2149E-02	0.7037E-04	-0.1978E-04	-0.5408E-04-0.8475E-04		
9	-0.4774E-02 0.2837E-03	-0.1226E-02	0.3577E-04	-0.3378E-04-0.5275E-04		
0	0.5087E-01-0.1700E-02	0.7408E-03	-0.9121E-03	-0.4319E-05-0.3556E-04		
1	-0.1725E-01-0.3591E-05	-0.3016E-03	0.8572E-03	-0.7843E-03-0.1394E-04		
2	-0.7649E-02-0.7736E-04	-0.1510E-03	0.1748E-03	0.8868E-03-0.7295E-03		
3	-0.1005E-01-0.6894E-03	-0.1822E-03	0.1608E-03	-0.2147E-03 0.9456E003		

D. FOR LOAD AT RADIAL POSITION NO=4

OR

RADIAL POSITIONS

	1	2	3	4	5	6
1	-0.1166E-01-0.1866E-02	0.5379E-03	-0.1341E-04-0.4079E-04	-0.4611E-04		
2	-0.1259E-01 0.1319E-03	-0.6614E-03	0.6181E-04-0.4139E-04	-0.4354E-04		
3	-0.3299E-01-0.1402E-02	0.2435E-03	-0.4975E-03-0.1043E-04	-0.3190E-04		
4	0.1189E 00-0.4701E-02	-0.4274E-03	0.4284E-03-0.4901E-03	-0.1460E-04		
5	-0.3111E-01 0.1220E-04	-0.4943E-03	-0.1517E-03	0.5134E-03-0.4792E-03		
6	-0.4123E-02 0.4755E-04	-0.2251E-03	0.1169E-03	-0.1023E-03 0.5492E-03		
7	-0.2361E-01 0.9647E-03	-0.8994E-04	0.8209E-04-0.6922E-04	-0.8751E-04		
8	0.3300E-02-0.1281E-02	0.1257E-03	-0.4918E-04-0.4936E-04	-0.5826E-04		
9	-0.6207E-02 0.2090E-03	-0.5869E-03	0.5090E-05-0.3531E-04	-0.4202E-04		
0	-0.4671E-02-0.7740E-03	0.4040E-03	-0.5169E-03-0.1347E-04	-0.3112E004		
1	0.3076E-01-0.1503E-02	-0.2211E-03	0.5081E-03-0.4954E-03	-0.1618E-04		
2	-0.5104E-02-0.4311E-03	-0.1965E-03	0.1181E-03 0.5497E-03	-0.4818E-03		
3	-0.1736E-01-0.5519E-03	-0.2015E-03	0.1229E-03-0.1247E-03	0.5936E-03		

E. FOR LOAD AT RADIAL POSITION NO=5

RADIAL POSITIONS

TOR	1	2	3	4	5	6
1	-0.5843E-02	-0.9975E-03	0.5653E-03	-0.7569E-04	-0.4482E-04	-0.3769E-04
2	-0.4395E-02	0.2380E-04	-0.2564E-03	0.1484E-04	-0.4543E-04	-0.3751E-04
3	-0.1198E-01	-0.4134E-03	0.1206E-03	-0.2667E-03	-0.2250E-04	-0.2957E-04
4	-0.2640E-01	-0.1440E-02	-0.2230E-03	0.2752E-03	-0.3198E-03	-0.1738E004
5	0.1100E 00	-0.4767E-02	-0.3412E-03	-0.1098E-03	0.3503E-03	-0.3373E-03
6	-0.1323E-01	-0.6306E-03	-0.3632E-03	-0.1024E-03	-0.7344E-04	0.3845E-03
7	-0.3971E-01	0.1280E-02	-0.1505E-03	0.8668E-03	-0.5654E-04	-0.5905E-04
8	0.2483E-02	-0.1279E-02	0.2278E-03	-0.6534E-04	-0.4462E-04	-0.4420E-04
9	-0.6723E-02	0.1725E-03	-0.2589E-03	-0.2172E-03	-0.3509E-04	-0.3447E-04
0	-0.4187E-02	-0.3014E-03	0.2350E-03	-0.3150E-03	-0.1952E-04	-0.2733E-04
1	0.2002E-02	-0.7201E-03	-0.1454E-03	0.3374E-03	-0.3386E-03	-0.1688E004
2	0.2175E-01	-0.1242E-02	-0.1654E-03	-0.8635E-04	0.3809E-03	-0.3459E-03
3	-0.1981E-01	-0.7012E-03	-0.1960E-03	-0.9614E-04	-0.8567E-04	0.4191E-03

F. FOR LOAD AT RADIAL POSITION NO=6

RADIAL POSITIONS

OR	1	2	3	4	5	6
	-0.6852E-02	0.9718E-02	-0.1693E-02	-0.1066E-03	-0.4272E-04	-0.3107E-04
	-0.1659E-02	-0.3085E-02	0.2334E-03	-0.1038E-03	-0.4490E-04	-0.3229E-04
	-0.2957E-02	-0.1500E-03	-0.8323E-05	-0.1268E-03	-0.3277E-04	-0.2691E-04
	-0.1047E-01	-0.3751E-03	-0.1256E-03	0.1858E-03	-0.2171E-03	-0.1881E-04
	-0.3021E-01	-0.1446E-02	-0.1979E-03	-0.7917E-04	0.2541E-03	-0.2485E-03
	0.1632E-01	-0.5293E-02	-0.2706E-03	0.8127E-04	-0.5490E-04	-0.2850E-03
	0.1873E 00	-0.9279E-02	-0.2792E-03	-0.7767E-04	-0.4616E-04	-0.4283E-04
	-0.1339E 00	0.1335E-02	-0.3045E-03	-0.6821E-04	-0.3916E-04	-0.3494E-04
	-0.2359E-02	-0.6561E-03	-0.3076E-04	-0.5204E-04	-0.3320E-04	-0.2891E-04
	-0.1553E-02	-0.1372E-03	0.1285E-03	-0.1946E-03	-0.2336E-04	-0.2426E-04
	-0.1274E-02	-0.2892E-03	-0.9651E-04	0.2385E-03	-0.2422E-03	-0.1679E-04
	0.2032E-02	-0.6409E-03	-0.1191E-03	-0.6440E-04	0.2800E-03	-0.2599E-03
	0.1420E-01	-0.1132E-02	-0.1552E-03	-0.7521E-04	-0.6230E-04	0.3122E-03

TABLE 3 - NONDIMENSIONAL MOMENTS M_θ
 $D = .01$ AND $\mu = .2$

A. FOR LOAD AT RADIAL POSITION NO=1

CTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.8338E 00-0.1086E 00	0.5785E-03	0.2457E-03	0.1430E-03	0.2916E-04	
2	-0.2916E 00	0.9487E-01-0.1077E-01	-0.1908E-04	-0.4616E-04	-0.8073E-04	
3	-0.9506E-01	-0.2524E-01	0.1854E-01	-0.2278E-02	-0.1539E-04	-0.4132E-04
4	-0.2269E-01	-0.8538E-02	-0.3944E-02	0.3218E-02	-0.9962E-03	-0.1523E-04
5	-0.5075E-02	-0.2194E-02	-0.1452E-02	-0.4539E-03	0.1416E-02	-0.1194E-02
6	0.7108E-02	-0.7738E-03	-0.4312E-03	-0.1940E-03	-0.5812E-03	0.2387E-02
7	-0.5921E 00	-0.1178E-03	-0.1914E-03	-0.1125E-03	-0.1579E-03	-0.9149E-03
8	0.9753E 00	-0.4175E-01	-0.3555E-04	-0.7031E-04	-0.8358E-04	-0.2447E-03
9	-0.2695E 00	-0.7204E-01	-0.6717E-02	-0.1946E-04	-0.4867E-04	-0.9141E-04
10	-0.8892E-01	-0.1808E-01	-0.1101E-01	-0.1522E-02	-0.1726E-04	-0.4397E-04
11	-0.2130E-01	-0.6267E-02	-0.1976E-02	0.1971E-02	-0.1264E-02	0.1007E-04
12	-0.4596E-02	-0.1683E-02	-0.7796E-03	-0.4148E-03	0.2190E-02	-0.1480E-02
13	-0.9941E-02	-0.2987E-02	-0.1320E-02	-0.6101E-03	-0.1669E-02	-0.3471E-02

B. FOR LOAD AT RADIAL POSITION NO=2

CTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	-0.5964E 00-0.2911E-01	0.6829E-03	0.2685E-03	0.1438E-03	0.8484E-04	
2	0.5934E 00	0.8540E-02	-0.4354E-02	-0.1337E-04	-0.3261E-04	-0.4916E-04
3	-0.2023E 00	0.2204E-01	0.5424E-02	-0.1759E-02	-0.6564E-05	-0.2816E-04
4	-0.6250E-01	-0.8078E-02	0.8247E-03	0.2451E-02	-0.9487E-03	-0.9330E-05
5	-0.1316E-01	-0.2794E-02	-0.6594E-03	-0.2346E-03	0.1424E-02	-0.6915E-03
6	0.2958E-03	-0.1080E-02	-0.3568E-03	-0.1558E-03	-0.2647E-03	0.1139E-02
7	-0.1565E 00	-0.1162E-03	-0.1826E-03	-0.1000E-03	-0.1131E-03	-0.2670E-03
8	-0.4006E-01	-0.1383E-01	-0.1408E-04	-0.5100E-04	-0.6099E-04	-0.1057E-03
9	0.3874E 00	0.1354E-01	-0.3693E-02	-0.1161E-04	-0.3420E-04	-0.5223E-04
10	-0.1307E 00	0.8526E-02	-0.5002E-02	-0.1550E-02	-0.9144E-05	-0.3022E-04
11	-0.4444E-01	-0.3925E-02	-0.9483E-04	-0.2231E-02	-0.9305E-03	-0.1173E-04
12	-0.8336E-02	-0.1524E-02	-0.3755E-03	-0.3083E-03	-0.1458E-02	-0.7084E-03
13	-0.2467E-01	-0.3433E-02	-0.1204E-02	-0.6620E-03	-0.8088E-03	-0.1475E-02

C. FOR LOAD AT RADIAL POSITION NO=3

CTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	-0.1865E 00-0.1076E-01	0.7826E-03	0.2390E-03	0.1119E-03	0.6589E-04	
2	-0.1991E 00	0.1634E-02-0.2042E-02	0.6501E-05-0.1864E-04	0.2892E-04		
3	0.5816E 00	0.3646E-02	0.1858E-02-0.9552E-03	0.8873E-06-0.1836E-04		
4	-0.1881E 00	0.8032E-02	0.5926E-03	0.1195E-02-0.5624E-03	0.6429E-05	
5	-0.6282E-01	-0.2119E-02	0.1502E-03-0.1418E-03	0.8010E-03-0.4012E-03		
6	-0.4850E-02	-0.1285E-02	-0.5204E-04-0.4312E-04	-0.9230E-04	0.6066E-03	
7	-0.8002E-01	-0.3119E-04	-0.7941E-04-0.3833E-04	-0.5398E-04-0.9899E-04		
8	-0.1738E-01	-0.6449E-02	0.1059E-04-0.2496E-04	0.3374E-04-0.5270E-04		
9	-0.3545E-01	0.3658E-02	0.1960E-02	0.3662E-05-0.2106E-04	0.3144E-04	
10	0.2344E 00	0.3153E-02	0.2129E-02	0.8954E-03-0.4793E-05	0.2037E-04	
11	-0.6260E-01	0.1979E-02	0.2218E-03	0.1202E-02-0.5512E-03	0.8741E-05	
12	-0.3108E-01	-0.4113E-03	-0.1061E-04	-0.8153E-04	0.8079E-03-0.4013E-03	
13	-0.4812E-01	-0.3553E-02	-0.7148E-03	-0.3749E-03-0.3705E-03	0.7965E-03	

D. FOR LOAD AT RADIAL POSITION NO=4

CTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	-0.5921E-01	-0.5908E-02	0.9742E-03	0.1888E-03	0.8215E-04	0.4738E-04
2	-0.6296E-01	0.1272E-02	-0.1302E-02	0.2297E-04-0.1014E-04	0.1849E-04	
3	-0.1725E 00	0.1805E-03	0.8528E-03	-0.5462E-03	0.1145E-05-0.1260E-04	
4	0.5392E 00	0.2884E-02	0.2547E-03	0.6428E-03-0.3546E-03	0.4851E-05	
5	-0.1708E 00	0.3689E-02	0.2191E-03	0.1660E-04	0.4885E-03-0.2629E-03	
6	-0.2422E-01	-0.5274E-03	0.9503E-04	-0.1594E-05	-0.4009E-04	0.3821E-03
7	-0.1146E 00	0.4277E-03	0.3068E-04	-0.9154E-05	-0.2784E-04	0.4971E-04
8	0.1720E-01	-0.4438E-02	0.5909E-04	-0.7840E-05	-0.1930E-04	0.3115E-04
9	-0.2504E-01	0.1362E-02	-0.1080E-02	0.9609E-05	-0.1289E-04	0.2100E-04
10	-0.3219E-02	0.8551E-03	0.1011E-02	-0.5449E-03	-0.2556E-05	0.1449E-04
11	0.1421E 00	0.1485E-02	0.1492E-03	0.6986E-03	-0.3566E-03	0.6981E-05
12	-0.3252E-01	0.8923E-03	0.7946E-04	-0.2216E-04	0.5038E-03	0.2653E-03
13	-0.8970E-01	-0.2131E-02	-0.3750E-03	-0.2134E-03	-0.2037E-03	0.5163E-03

E. FOR LOAD AT RADIAL POSITION NO=5

TOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	-0.2561E-01	-0.2840E-02	0.9055E-03	0.1385E-03	0.6005E-04	0.3473E-04
2	-0.1511E-01	0.4694E-03	-0.7206E-03	0.2618E-04	-0.5397E-05	-0.1281E-04
3	-0.6033E-01	-0.9940E-04	0.3095E-03	-0.3263E-03	0.1721E-05	-0.9148E-05
4	-0.1497E-00	0.5925E-03	0.1186E-03	0.3799E-03	-0.2398E-03	-0.3881E-05
5	0.4915E-00	0.2222E-02	0.1461E-03	0.1431E-04	0.3278E-03	-0.1875E-03
6	-0.8500E-01	0.2436E-02	0.1176E-03	0.7986E-05	-0.2209E-04	0.2675E-03
7	-0.1948E-00	0.1243E-02	0.7462E-04	0.2420E-05	-0.1628E-04	-0.3027E-04
8	0.2191E-01	-0.4637E-02	0.8999E-04	0.1128E-05	-0.1189E-04	-0.2086E-04
9	-0.4678E-02	0.9758E-03	-0.5872E-03	0.1094E-04	-0.8399E-05	-0.1492E-04
0	-0.1506E-01	0.2754E-03	0.4972E-03	-0.3523E-03	-0.1611E-05	-0.1088E-04
1	0.2308E-02	0.6589E-03	0.8633E-04	0.4465E-03	-0.2493E-03	-0.5691E-05
2	0.9248E-01	0.8627E-03	0.7302E-04	-0.7896E-05	0.3468E-03	-0.1919E-03
3	-0.1078E-00	-0.5287E-03	-0.1837E-03	-0.1313E-03	-0.1298E-03	0.3699E-03

F. FOR LOAD AT RADIAL POSITION NO=6

TOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	-0.1641E-01	0.2858E-01	0.3511E-03	0.9594E-04	0.4418E-04	0.2611E-04
2	-0.4274E-02	-0.1453E-01	0.9340E-04	0.1664E-04	-0.2729E-05	-0.9279E-05
3	-0.1475E-01	-0.6099E-04	-0.1837E-03	-0.1840E-03	0.1280E-05	-0.6890E-05
4	-0.5783E-01	0.1257E-03	0.6292E-04	0.2291E-03	-0.1683E-03	-0.3328E-05
5	-0.1710E-00	0.6871E-03	0.8981E-04	0.9759E-05	0.2321E-03	-0.1397E-03
6	0.1915E-01	0.1756E-02	0.9364E-04	0.8861E-05	-0.1388E-04	-0.1975E-03
7	0.8866E-00	0.1661E-02	0.7689E-04	0.6227E-05	-0.1047E-04	-0.2024E-04
8	-0.6354E-00	0.2676E-02	0.6378E-04	0.5041E-05	-0.7643E-05	-0.1486E-04
9	-0.1941E-02	-0.3015E-02	-0.2114E-03	0.9062E-05	-0.5656E-05	-0.1110E-04
0	-0.6471E-02	0.1156E-03	0.1888E-03	-0.2322E-03	-0.1126E-05	-0.8497E-05
1	-0.1007E-01	0.2971E-03	0.5121E-04	0.3002E-03	-0.1819E-03	-0.4733E-05
2	0.8928E-03	0.4884E-03	0.5371E-04	-0.3758E-05	0.2520E-03	-0.1452E-03
3	0.5649E-01	0.2555E-03	-0.8507E-04	-0.8614E-04	-0.8924E-04	0.2780E-03

TABLE 4 - EXAMPLE 1

A. FOR LOAD AT RADIAL POSITION NO=1

CTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1417E 01	0.5297E 00	0.2507E 00	0.1617E 00	0.1215E 00	0.9773E-01
2	0.1335E 01	0.5089E 00	0.2457E 00	0.1602E 00	0.1208E 00	0.9728E-01
3	0.1134E 01	0.4550E 00	0.2323E 00	0.1559E 00	0.1188E 00	0.9605E-01
4	0.8760E 00	0.3846E 00	0.2147E 00	0.1502E 00	0.1162E 00	0.9435E-01
5	0.6282E 00	0.3167E 00	0.1976E 00	0.1446E 00	0.1135E 00	0.9264E-01
6	0.4515E 00	0.2682E 00	0.1855E 00	0.1405E 00	0.1116E 00	0.9136E-01
7	0.3877E 00	0.2507E 00	0.1811E 00	0.1390E 00	0.1109E 00	0.9091E-01

B. FOR LOAD AT RADIAL POSITION NO=2

CTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.4429E 00	0.8994E 00	0.3713E 00	0.1966E 00	0.1344E 00	0.1038E 00
2	0.4347E 00	0.6970E 00	0.3255E 00	0.1871E 00	0.1317E 00	0.1027E 00
3	0.4127E 00	0.4871E 00	0.2612E 00	0.1699E 00	0.1256E 00	0.9994E-01
4	0.3829E 00	0.3521E 00	0.2183E 00	0.1545E 00	0.1188E 00	0.9645E-01
5	0.3536E 00	0.2798E 00	0.1928E 00	0.1430E 00	0.1130E 00	0.9294E-01
6	0.3323E 00	0.2464E 00	0.1798E 00	0.1374E 00	0.1102E 00	0.9015E-01
7	0.3246E 00	0.2368E 00	0.1758E 00	0.1357E 00	0.1094E 00	0.8982E-01

C. FOR LOAD AT RADIAL POSITION NO=3

CTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.2241E 00	0.3606E 00	0.8493E 00	0.3509E 00	0.1807E 00	0.1212E 00
2	0.2231E 00	0.3208E 00	0.4903E 00	0.2669E 00	0.1630E 00	0.1166E 00
3	0.2202E 00	0.2656E 00	0.2826E 00	0.1909E 00	0.1377E 00	0.1071E 00
4	0.2162E 00	0.2231E 00	0.1985E 00	0.1527E 00	0.1180E 00	0.9741E-01
5	0.2121E 00	0.1967E 00	0.1650E 00	0.1335E 00	0.1086E 00	0.8985E-01
6	0.2091E 00	0.1830E 00	0.1512E 00	0.1242E 00	0.1033E 00	0.8710E-01
7	0.2080E 00	0.1788E 00	0.1472E 00	0.1214E 00	0.1016E 00	0.8618E-01

D. FOR LOAD AT RADIAL POSITION NO=4

RADIAL POSITIONS

TOR	1	2	3	4	5	6
1	0.1529E 00	0.1908E 00	0.3430E 00	0.7976E 00	0.3350E 00	0.1669E 00
2	0.1526E 00	0.1830E 00	0.2641E 00	0.3633E 00	0.2247E 00	0.1439E 00
3	0.1519E 00	0.1689E 00	0.1937E 00	0.1942E 00	0.1482E 00	0.1151E 00
4	0.1509E 00	0.1555E 00	0.1544E 00	0.1396E 00	0.1169E 00	0.9569E-01
5	0.1498E 00	0.1455E 00	0.1333E 00	0.1181E 00	0.1017E 00	0.8693E-01
6	0.1491E 00	0.1396E 00	0.1236E 00	0.1086E 00	0.9418E-01	0.8185E-01
7	0.1488E 00	0.1376E 00	0.1217E 00	0.1058E 00	0.9190E-01	0.8017E-01

E. FOR LOAD AT RADIAL POSITION NO=5

RADIAL POSITIONS

TOR	1	2	3	4	5	6
1	0.1179E 00	0.1318E 00	0.1771E 00	0.3291E 00	0.7405E 00	0.3140E 00
2	0.1177E 00	0.1297E 00	0.1612E 00	0.2236E 00	0.2845E 00	0.1889E 00
3	0.1174E 00	0.1249E 00	0.1387E 00	0.1518E 00	0.1479E 00	0.1151E 00
4	0.1169E 00	0.1193E 00	0.1212E 00	0.1182E 00	0.1083E 00	0.9374E-01
5	0.1164E 00	0.1147E 00	0.1100E 00	0.1020E 00	0.9203E-01	0.8166E-01
6	0.1160E 00	0.1116E 00	0.1038E 00	0.9428E-01	0.8460E-01	0.7551E-01
7	0.1159E 00	0.1106E 00	0.1019E 00	0.9198E-01	0.8240E-01	0.7365E-01

F. FOR LOAD AT RADIAL POSITION NO=6

RADIAL POSITIONS

TOR	1	2	3	4	5	6
1	0.9573E-01	0.1024E 00	0.1196E 00	0.1641E 00	0.3089E 00	0.7481E 00
2	0.9566E-01	0.1016E 00	0.1156E 00	0.1429E 00	0.1889E 00	0.2345E 00
3	0.9544E-01	0.9932E-01	0.1069E 00	0.1163E 00	0.1225E 00	0.1183E 00
4	0.9515E-01	0.9652E-01	0.9820E-01	0.9824E-01	0.9484E-01	0.8799E-01
5	0.9486E-01	0.9398E-01	0.9169E-01	0.8755E-01	0.8176E-01	0.7504E-01
6	0.9465E-01	0.9227E-01	0.8783E-01	0.8199E-01	0.7554E-01	0.6905E-01
7	0.9457E-01	0.9166E-01	0.8656E-01	0.8027E-01	0.7368E-01	0.6726E-01

D. FOR LOAD AT RADIAL POSITION NO=4

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.2262E 00	0.2562E 00	0.3996E 00	0.8466E 00	0.3776E 00	0.2044E 00
2	0.2262E 00	0.2493E 00	0.3218E 00	0.4132E 00	0.2681E 00	0.1820E 00
3	0.2263E 00	0.2377E 00	0.2545E 00	0.2471E 00	0.1942E 00	0.1552E 00
4	0.2263E 00	0.2289E 00	0.2214E 00	0.1982E 00	0.1676E 00	0.1394E 00
5	0.2264E 00	0.2257E 00	0.2119E 00	0.1872E 00	0.1607E 00	0.1364E 00

E. FOR LOAD AT RADIAL POSITION NO=5

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1753E 00	0.1850E 00	0.2249E 00	0.3718E 00	0.7786E 00	0.3481E 00
2	0.1753E 00	0.1835E 00	0.2098E 00	0.2671E 00	0.3233E 00	0.2237E 00
3	0.1753E 00	0.1802E 00	0.1897E 00	0.1978E 00	0.1891E 00	0.1519E 00
4	0.1753E 00	0.1772E 00	0.1764E 00	0.1690E 00	0.1541E 00	0.1345E 00
5	0.1754E 00	0.1761E 00	0.1721E 00	0.1612E 00	0.1459E 00	0.1202E 00

F. FOR LOAD AT RADIAL POSITION NO=6

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1427E 00	0.1469E 00	0.1607E 00	0.2016E 00	0.3431E 00	0.7793E 00
2	0.1427E 00	0.1464E 00	0.1562E 00	0.1811E 00	0.2237E 00	0.2662E 00
3	0.1427E 00	0.1451E 00	0.1501E 00	0.1564E 00	0.1593E 00	0.1520E 00
4	0.1427E 00	0.1439E 00	0.1444E 00	0.1421E 00	0.1356E 00	0.1253E 00
5	0.1427E 00	0.1435E 00	0.1423E 00	0.1376E 00	0.1294E 00	0.1190E 00

TABLE 6 → EXAMPLE 3

A. FOR LOAD AT RADIAL POSITION NO=1

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1804E 01	0.7804E 00	0.4318E 00	0.3008E 00	0.2324E 00	0.1886E 00
2	0.1787E 01	0.7772E 00	0.4311E 00	0.3006E 00	0.2324E 00	0.1886E 00
3	0.1763E 01	0.7718E 00	0.4300E 00	0.3005E 00	0.2324E 00	0.1887E 00
4	0.1752E 01	0.7693E 00	0.4295E 00	0.3004E 00	0.2324E 00	0.1887E 00

B. FOR LOAD AT RADIAL POSITION NO=2

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.7675E 00	0.1136E 01	0.5470E 00	0.3323E 00	0.2438E 00	0.1936E 00
2	0.7670E 00	0.9433E 00	0.5053E 00	0.3246E 00	0.2419E 00	0.1928E 00
3	0.7662E 00	0.7669E 00	0.4530E 00	0.3129E 00	0.2386E 00	0.1929E 00
4	0.7659E 00	0.7042E 00	0.4365E 00	0.3091E 00	0.2375E 00	0.1929E 00

C. FOR LOAD AT RADIAL POSITION NO=3

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.4321E 00	0.5394E 00	0.9966E 00	0.4723E 00	0.2823E 00	0.2074E 00
2	0.4322E 00	0.5038E 00	0.6415E 00	0.3911E 00	0.2663E 00	0.2037E 00
3	0.4323E 00	0.4623E 00	0.4476E 00	0.3243E 00	0.2463E 00	0.1969E 00
4	0.4324E 00	0.4462E 00	0.3971E 00	0.3053E 00	0.2360E 00	0.1948E 00

D. FOR LOAD AT RADIAL POSITION NO=4

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.3017E 00	0.3284E 00	0.4637E 00	0.9034E 00	0.4269E 00	0.2471E 00
2	0.3017E 00	0.3226E 00	0.3887E 00	0.4718E 00	0.3188E 00	0.2258E 00
3	0.3017E 00	0.3144E 00	0.3280E 00	0.3123E 00	0.2499E 00	0.2020E 00
4	0.3018E 00	0.3110E 00	0.3088E 00	0.2791E 00	0.2337E 00	0.1914E 00

E. FOR LOAD AT RADIAL POSITION NO=5

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.2338E 00	0.2424E 00	0.2790E 00	0.4211E 00	0.8229E 00	0.3876E 00
2	0.2338E 00	0.2414E 00	0.2650E 00	0.3179E 00	0.3691E 00	0.2644E 00
3	0.2338E 00	0.2395E 00	0.2487E 00	0.2538E 00	0.2400E 00	0.1968E 00
4	0.2338E 00	0.2387E 00	0.2425E 00	0.2363E 00	0.2167E 00	0.1875E 00

F. FOR LOAD AT RADIAL POSITION NO=6

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1903E 00	0.1941E 00	0.2052E 00	0.2444E 00	0.3826E 00	0.8154E 00
2	0.1903E 00	0.1938E 00	0.2034E 00	0.2249E 00	0.2644E 00	0.3036E 00
3	0.1903E 00	0.1933E 00	0.1985E 00	0.2039E 00	0.2042E 00	0.1934E 00
4	0.1903E 00	0.1930E 00	0.1964E 00	0.1965E 00	0.1897E 00	0.1760E 00

TABLE 7 - EXAMPLE 4

A. FOR LOAD AT RADIAL POSITION NO=1

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.2673E 01	0.1163E 01	0.6460E 00	0.4509E 00	0.3486E 00	0.2830E 00
2	0.2663E 01	0.1162E 01	0.6459E 00	0.4508E 00	0.3486E 00	0.2830E 00
3	0.2656E 01	0.1161E 01	0.6457E 00	0.4508E 00	0.3486E 00	0.2830E 00

B. FOR LOAD AT RADIAL POSITION NO=2

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1150E 01	0.1459E 01	0.7569E 00	0.4827E 00	0.3603E 00	0.2896E 00
2	0.1150E 01	0.1295E 01	0.7236E 00	0.4791E 00	0.3607E 00	0.2893E 00
3	0.1150E 01	0.1211E 01	0.6981E 00	0.4755E 00	0.3606E 00	0.2897E 00

C. FOR LOAD AT RADIAL POSITION NO=3

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.6483E 00	0.7540E 00	0.1179E 01	0.6178E 00	0.3980E 00	0.3009E 00
2	0.6484E 00	0.7269E 00	0.8400E 00	0.5438E 00	0.3843E 00	0.3011E 00
3	0.6484E 00	0.7100E 00	0.7124E 00	0.5031E 00	0.3770E 00	0.3003E 00

D. FOR LOAD AT RADIAL POSITION NO=4

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.4525E 00	0.4818E 00	0.6115E 00	0.1034E 01	0.5384E 00	0.3407E 00
2	0.4526E 00	0.4781E 00	0.5431E 00	0.6114E 00	0.4357E 00	0.3215E 00
3	0.4526E 00	0.4755E 00	0.5091E 00	0.4942E 00	0.3883E 00	0.3103E 00

E. FOR LOAD AT RADIAL POSITION NO=5

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.3506E 00	0.3612E 00	0.3970E 00	0.5331E 00	0.9245E 00	0.4773E 00
2	0.3506E 00	0.3607E 00	0.3863E 00	0.4360E 00	0.4774E 00	0.3582E 00
3	0.3506E 00	0.3603E 00	0.3793E 00	0.3956E 00	0.3783E 00	0.3039E 00

F. FOR LOAD AT RADIAL POSITION NO=6

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.2855E 00	0.2904E 00	0.3030E 00	0.3392E 00	0.4724E 00	0.8982E 00
2	0.2855E 00	0.2904E 00	0.3016E 00	0.3231E 00	0.3592E 00	0.3916E 00
3	0.2855E 00	0.2903E 00	0.3003E 00	0.3129E 00	0.3186E 00	0.3039E 00

TABLE 8 - EXAMPLE 5

A. FOR LOAD AT RADIAL POSITION NO=1

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.3556E 01	0.1550E 01	0.8612E 00	0.6011E 00	0.4648E 00	0.3773E 00
2	0.3549E 01	0.1549E 01	0.8611E 00	0.6011E 00	0.4648E 00	0.3773E 00

B. FOR LOAD AT RADIAL POSITION NO=2

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1533E 01	0.1840E 01	0.9836E 00	0.6414E 00	0.4813E 00	0.3865E 00
2	0.1533E 01	0.1710E 01	0.9593E 00	0.6375E 00	0.4805E 00	0.3857E 00

C. FOR LOAD AT RADIAL POSITION NO=3

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.8645E 00	0.9856E 00	0.1394E 01	0.7776E 00	0.5183E 00	0.4022E 00
2	0.8645E 00	0.9661E 00	0.1019E 01	0.7154E 00	0.5127E 00	0.4006E 00

D. FOR LOAD AT RADIAL POSITION NO=4

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.6034E 00	0.6394E 00	0.7735E 00	0.1183E 01	0.6606E 00	0.4384E 00
2	0.6034E 00	0.6370E 00	0.7167E 00	0.7841E 00	0.5687E 00	0.4278E 00

E. FOR LOAD AT RADIAL POSITION NO=5

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.4675E 00	0.4811E 00	0.5214E 00	0.6574E 00	0.1040E 01	0.5751E 00
2	0.4675E 00	0.4809E 00	0.5137E 00	0.5716E 00	0.6090E 00	0.4612E 00

F. FOR LOAD AT RADIAL POSITION NO=6

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.3806E 00	0.3871E 00	0.4026E 00	0.4408E 00	0.5723E 00	0.9914E 00
2	0.3806E 00	0.3871E 00	0.4009E 00	0.4288E 00	0.4686E 00	0.4969E 00

TABLE 9 - EXAMPLE 6

A. FOR LOAD AT RADIAL POSITION NO=1

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.5330E 01	0.2324E 01	0.1292E 01	0.9017E 00	0.6972E 00	0.5660E 00
2	0.5326E 01	0.2324E 01	0.1292E 01	0.9017E 00	0.6971E 00	0.5660E 00

B. FOR LOAD AT RADIAL POSITION NO=2

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.2300E 01	0.2670E 01	0.1455E 01	0.9582E 00	0.7209E 00	0.5793E 00
2	0.2300E 01	0.2591E 01	0.1447E 01	0.9582E 00	0.7214E 00	0.5786E 00

C. FOR LOAD AT RADIAL POSITION NO=3

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1297E 01	0.1464E 01	0.1892E 01	0.1121E 01	0.7750E 00	0.6012E 00
2	0.1297E 01	0.1454E 01	0.1690E 01	0.1088E 01	0.7686E 00	0.6022E 00

D. FOR LOAD AT RADIAL POSITION NO=4

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.9051E 00	0.9573E 00	0.1121E 01	0.1528E 01	0.9267E 00	0.6511E 00
2	0.9031E 00	0.9562E 00	0.1086E 01	0.1223E 01	0.8714E 00	0.6429E 00

E. FOR LOAD AT RADIAL POSITION NO=5

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.7013E 00	0.7215E 00	0.7763E 00	0.9287E 00	0.1303E 01	0.7812E 00
2	0.7013E 00	0.7214E 00	0.7725E 00	0.8721E 00	0.9548E 00	0.7163E 00

F. FOR LOAD AT RADIAL POSITION NO=6

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.5709E 00	0.5807E 00	0.6033E 00	0.6521E 00	0.7910E 00	0.1202E 01
2	0.5709E 00	0.5807E 00	0.6032E 00	0.6463E 00	0.7185E 00	0.7831E 00

TABLE 10- EXAMPLE 7

LOAD POSN.	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1066E 02	0.4648E 01	0.2583E 01	0.1803E 01	0.1394E 01	0.1132E 01
2	0.4600E 01	0.5261E 01	0.2902E 01	0.1916E 01	0.1442E 01	0.1158E 01
3	0.2594E 01	0.2918E 01	0.3562E 01	0.2208E 01	0.1544E 01	0.1203E 01
4	0.1810E 01	0.1913E 01	0.2207E 01	0.2751E 01	0.1798E 01	0.1294E 01
5	0.1403E 01	0.1443E 01	0.1549E 01	0.1801E 01	0.2258E 01	0.1498E 01
6	0.1142E 01	0.1161E 01	0.1206E 01	0.1298E 01	0.1510E 01	0.1985E 01

TABLE 11- EXAMPLE 9

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.1739E 01	0.1788E 01	0.1796E 01	0.1744E 01	0.1603E 01	0.1361E 01
2	0.1667E 01	0.1517E 01	0.1286E 01	0.1086E 01	0.8939E 00	0.6925E 00
3	0.1490E 01	0.1183E 01	0.8954E 00	0.7164E 00	0.5770E 00	0.4567E 00
4	0.1254E 01	0.9171E 00	0.6775E 00	0.5420E 00	0.4415E 00	0.3643E 00
5	0.1008E 01	0.7261E 00	0.5485E 00	0.4432E 00	0.3672E 00	0.3081E 00
6	0.7934E 00	0.5927E 00	0.4645E 00	0.3804E 00	0.3189E 00	0.2702E 00
7	0.6398E 00	0.5031E 00	0.4071E 00	0.3370E 00	0.2849E 00	0.2440E 00
8	0.5593E 00	0.4484E 00	0.3681E 00	0.3066E 00	0.2606E 00	0.2249E 00
9	0.5471E 00	0.4213E 00	0.3429E 00	0.2854E 00	0.2433E 00	0.2110E 00
10	0.5840E 00	0.4141E 00	0.3279E 00	0.2714E 00	0.2315E 00	0.2013E 00
11	0.6419E 00	0.4178E 00	0.3199E 00	0.2626E 00	0.2238E 00	0.1949E 00
12	0.6919E 00	0.4243E 00	0.3164E 00	0.2579E 00	0.2196E 00	0.1914E 00
13	0.7114E 00	0.4272E 00	0.3154E 00	0.2564E 00	0.2182E 00	0.1902E 00

TABLE 12- EXAMPLE 8

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.2450E 01	0.2215E 01	0.2111E 01	0.2000E 01	0.1821E 01	0.1552E 01
2	0.2359E 01	0.1941E 01	0.1602E 01	0.1344E 01	0.1113E 01	0.8839E 00
3	0.2132E 01	0.1601E 01	0.1215E 01	0.9790E 00	0.8008E 00	0.6516E 00
4	0.1838E 01	0.1331E 01	0.1005E 01	0.8134E 00	0.6730E 00	0.5656E 00
5	0.1555E 01	0.1147E 01	0.8914E 00	0.7286E 00	0.6105E 00	0.5191E 00
6	0.1353E 01	0.1041E 01	0.8326E 00	0.6869E 00	0.5795E 00	0.4950E000
7	0.1280E 01	0.1006E 01	0.8142E 00	0.6741E 00	0.5699E 00	0.4880E 00

TABLE 13- EXAMPLE 10

SECTOR	RADIAL POSITIONS					
	1	2	3	4	5	6
1	0.7528E 02	0.7418E 02	0.7181E 02	0.6834E 02	0.6295E 02	0.5500E002

TABLE 14 - POLYNOMIAL CO-EFFICIENTS

A. FOR SECTOR 1

-0.17029E	04	0.17271E	05	-0.12033E	06	0.34285E	06	-0.34223E	06
0.11923E	06	-0.21030E	07	0.14702E	08	-0.41975E	08	0.41955E	08
-0.20955E	07	0.40703E	08	-0.28475E	09	0.81328E	09	-0.81310E	09
0.58779E	07	-0.11561E	09	0.80887E	09	-0.23104E	10	0.23099E	10
-0.43014E	07	0.84972E	08	-0.59452E	09	0.16981E	10	-0.16978E	10
0.19546E	04	-0.20141E	05	0.14032E	06	-0.39978E	06	0.39905E	06
-0.13835E	06	0.24520E	07	-0.17142E	08	0.48939E	08	-0.48915E	08
0.24379E	07	-0.47453E	08	-0.33197E	09	-0.94814E	09	0.94792E	09
-0.68406E	07	0.13478E	09	-0.94298E	09	0.26934E	10	-0.26928E	10
0.50065E	07	-0.99060E	08	0.69308E	09	-0.19796E	10	0.19792E	10
-0.79139E	03	0.82784E	04	-0.57672E	05	0.16430E	06	-0.16400E	06
0.56606E	05	-0.10077E	07	0.70446E	07	-0.20112E	08	0.20102E	08
-0.99985E	06	0.19499E	08	-0.13641E	09	0.38961E	09	-0.38952E	09
0.28064E	07	-0.55383E	08	0.38748E	09	-0.11067E	10	0.11065E	10
-0.20542E	07	0.40704E	08	-0.28479E	09	0.81343E	09	-0.81326E	09
0.13494E	03	-0.14280E	04	0.99486E	04	-0.28343E	05	0.28291E	05
-0.97320E	04	0.17383E	06	-0.12152E	07	0.34694E	07	-0.34677E	07
0.17221E	06	-0.33634E	07	0.23530E	08	-0.67203E	08	0.67187E	08
-0.48348E	06	0.95526E	07	-0.66834E	08	0.19089E	09	-0.19085E	09
0.35391E	06	-0.70207E	07	0.49120E	08	-0.14030E	09	0.14027E	09
-0.82419E	01	0.87976E	02	-0.61293E	03	0.17463E	04	-0.17431E	04
0.59815E	03	-0.10710E	05	0.74875E	05	-0.21376E	06	0.21366E	06
-0.10598E	05	0.20721E	06	-0.14496E	07	0.41402E	07	-0.41392E	07
0.29759E	05	-0.58848E	06	0.41173E	07	-0.11760E	08	0.11758E	08
-0.21785E	05	0.43250E	06	-0.30260E	07	0.86431E	07	-0.86413E	07
0.36749E	04	-0.37464E	05	0.26091E	06	-0.74317E	06	0.74171E	06
-0.25780E	06	0.45566E	07	-0.31852E	08	0.90929E	08	-0.90881E	08
0.45353E	07	-0.88171E	08	0.61680E	09	-0.17616E	10	0.17611E	10
-0.12723E	08	0.25044E	09	-0.17521E	10	0.50042E	10	-0.50031E	10
0.93113E	07	-0.18407E	09	0.12878E	10	-0.36782E	10	0.36774E	10
-0.42181E	04	0.43553E	05	-0.30328E	06	0.86381E	06	-0.86209E	06
0.29849E	06	-0.52957E	07	0.37017E	08	-0.10567E	09	0.10562E	09
-0.52616E	07	0.10246E	09	-0.71676E	09	0.20471E	10	-0.20465E	10
0.14765E	08	-0.29102E	09	0.20360E	10	-0.58151E	10	0.58138E	10
-0.10806E	08	0.21389E	09	-0.14964E	10	0.42741E	10	-0.42731E	10
0.17081E	04	-0.17863E	05	0.12439E	06	-0.35427E	06	0.35355E	06
-0.12196E	06	0.21718E	07	-0.15180E	08	0.43335E	08	-0.43311E	08
0.21540E	07	-0.42015E	08	0.29391E	09	-0.83939E	09	0.83917E	09
-0.60460E	07	0.11933E	09	-0.83483E	09	0.23844E	10	-0.23838E	10
0.44254E	07	-0.87702E	08	0.61358E	09	-0.17525E	10	0.17521E	10
-0.29132E	03	0.30770E	04	-0.21427E	05	0.61026E	05	-0.60903E	05
0.20949E	05	-0.37410E	06	0.26150E	07	0.7 650E	07	-0.74609E	07
-0.37056E	06	0.72368E	07	-0.50623E	08	0.14458E	09	-0.14454E	09
0.10403E	07	-0.20553E	08	0.14379E	09	-0.41068E	09	0.41059E	09

-0.76150E 06 0.15105E 08-0.10568E 09 0.30184E 09-0.30178E 09
 0.17799E 02-0.18938E 03 0.13188E 04-0.37562E 04 0.37487E 04
 -0.12868E 04 0.23027E 05-0.16096E 06 0.45949E 06-0.45924E 06
 0.22786E 05-0.44539E 06 0.31157E 07-0.88984E 07 0.88961E 07
 -0.63977E 05 0.12649E 07-0.88494E 07 0.2 275E 08-0.25270E 08
 0.46833E 05-0.92963E 06 0.65039E 07-0.18576E 08 0.18572E 08
 -0.27497E 04 0.28046E 05-0.19519E 06 0.55576E 06-0.55454E 06
 0.19259E 06-0.34055E 07 0.23801E 08-0.67938E 08 0.67897E 08
 -0.33877E 07 0.65876E 08-0.46079E 09 0.13160E 10-0.13156E 10
 0.95035E 07-0.18710E 09 0.13089E 10-0.37382E 10 0.37372E 10
 -0.69549E 07 0.13751E 09-0.96198E 09 0.27475E 10-0.27468E 10
 0.31690E 04-0.32720E 05 0.22771E 06-0.64830E 06 0.64685E 06
 -0.22382E 06 0.39721E 07-0.27760E 08 0.79239E 08-0.79190E 08
 0.39446E 07-0.76829E 08 0.53740E 09-0.11347E 10 0.15343E 10
 -0.11069E 08 0.21820E 09-0.15264E 10 0.43595E 10-0.43584E 10
 0.81008E 07-0.16036E 09 0.11219E 10-0.32042E 10 0.32034E 10
 -0.12875E 04 0.13456E 05-0.93636E 05 0.26659E 06-0.26598E 06
 0.91707E 05-0.16333E 07 0.11414E 08-0.32581E 08 0.32561E 08
 -0.16193E 07 0.31588E 08-0.22095E 09 0.63100E 09-0.63082E 09
 0.45448E 07-0.89710E 08 0.62756E 09-0.17923E 10 0.17919E 10
 -0.33265E 07 0.65930E 08-0.46123E 09 0.13173E 10-0.13170E 10
 0.22011E 03-0.23221E 04 0.16130E 05-0.46009E 05 0.45905E 05
 -0.15785E 05 0.28188E 06-0.19700E 07 0.56232E 07-0.56197E 07
 0.27912E 06-0.54512E 07 0.38130E 08-0.10889E 09 0.10886E 09
 -0.78354E 06 0.15481E 08-0.10830E 09 0.30930E 09-0.30923E 09
 0.57353E 06-0.11377E 08 0.79593E 08-0.22732E 09 0.22727E 09
 -0.13474E 02 0.14311E 03-0.99597E 03 0.28357E 04-0.28294E 04
 0.97109E 03-0.17374E 05 0.12143E 06-0.34660E 06 0.34639E 06
 -0.17188E 05 0.33597E 06-0.23500E 07 0.67114E 07-0.67095E 07
 0.48256E 05-0.95409E 06 0.66744E 07-0.19062E 08 0.19058E 08
 -0.35324E 05 0.70117E 06-0.49052E 07 0.14010E 08-0.14006E 08
 0.91905E 03-0.93364E 04 0.64920E 05-0.18474E 06 0.18427E 06
 -0.64040E 05 0.11310E 07-0.79026E 07 0.22554E 08-0.22538E 08
 0.11252E 07-0.21870E 08 0.15296E 09-0.43680E 09 0.43665E 09
 -0.31561E 07 0.62108E 08-0.43444E 09 0.12407E 10-0.12404E 10
 0.23095E 07-0.45645E 08 0.31929E 09-0.91188E 09 0.91163E 09
 -0.10634E 04 0.10929E 05-0.75990E 05 0.21623E 06-0.21567E 06
 0.74686E 05-0.13237E 07 0.92486E 07-0.21395E 08 0.26377E 08
 -0.13148E 07 0.25593E 08-0.17900E 09 0.51116E 09-0.51099E 09
 0.36885E 07-0.72681E 08 0.50139E 09-0.14519E 10 0.14515E 10
 -0.26994E 07 0.53414E 08-0.37364E 09 0.10671E 10-0.10668E 10
 0.43342E 03-0.45059E 04 0.31328E 05-0.89142E 05 0.88910E 05
 -0.30684E 05 0.54567E 06-0.38126E 07 0.10881E 08-0.10873E 08
 0.54114E 06-0.10550E 08 0.73783E 08-0.21070E 09 0.21063E 09
 -0.15185E 07 0.29959E 08-0.20955E 09 0.59846E 09-0.59828E 09
 0.11114E 07-0.22017E 08 0.15401E 09-0.43983E 09 0.43971E 09
 -0.74290E 02 0.77899E 03-0.54163E 04 0.15412E 05-0.15372E 05
 0.52921E 04-0.94347E 05 0.65921E 06-0.18814E 07 0.18800E 07
 -0.93457E 05 0.18240E 07-0.12757E 08 0.36429E 08-0.36417E 08
 0.26229E 06-0.51795E 07 0.36230E 08-0.10347E 09 0.10344E 09
 -0.19198E 06 0.38064E 07-0.26626E 08 0.76042E 08-0.76020E 08
 0.45565E 01-0.48068E 02 0.33424E 03-0.95115E 03 0.94871E 03
 -0.32605E 03 0.58228E 04-0.40685E 05 0.11612E 06-0.11603E 06

0.57632E 04-0.11256E 06 0.78727E 06-0.22482E 07 0.22475E 07
 -0.16177E 05 0.31964E 06-0.22358E 07 0.63853E 07-0.63835E 07
 0.11840E 05-0.23489E 06 0.16431E 07-0.46926E 07 0.46913E 07
 -0.14056E 03 0.14178E 04-0.98451E 04 0.27993E 05-0.27907E 05
 0.97158E 04-0.17116E 06 0.11955E 07-0.34111E 07 0.34083E 07
 -0.17040E 06 0.33081E 07-0.23133E 08 0.6 053E 08-0.66027E 08
 0.47780E 06-0.93939E 07 0.65699E 08-0.18761E 09 0.18755E 09
 -0.34960E 06 0.69034E 07-0.48284E 08 0.13788E 09-0.13784E 09
 0.16315E 03-0.16638E 04 0.11552E 05-0.32845E 05 0.32743E 05
 -0.11360E 05 0.20 81E 06-0.14025E 07 0.40019E 07-0.39985E 07
 0.19960E 06-0.38810E 07 0.27138E 08-0.77490E 08 0.77459E 08
 -0.55981E 06 0.11020E 08-0.77073E 08 0.22009E 09-0.22001E 09
 0.40964E 06-0.80985E 07 0.56642E 08-0.11 175E 09 0.16170E 09
 -0.66678E 02 0.68716E 03-0.47711E 04 0.13565E 05-0.13523E 05
 0.46769E 04-0.82934E 05 0.57924E 06-0.16528E 07 0.16513E 07
 -0.82316E 05 0.16028E 07-0.11208E 08 0.32002E 08-0.31989E 08
 0.23091E 06-0.45510E 07 0.31829E 08-0.90891E 08 0.90859E 08
 -0.16898E 06 0.33444E 07-0.23391E 08 0.66797E 08-0.66774E 08
 0.11454E 02-0.11894E 03 0.82592E 03-0.23483E 04 0.23410E 04
 -0.80782E 03 0.14358E 05-0.10028E 06 0.28614E 06-0.28590E 06
 0.14236E 05-0.27748E 06 0.19403E 07-0.55404E 07 0.55382E 07
 -0.39942E 05 0.78788E 06-0.55103E 07 0.15735E 08-0.15730E 08
 0.29231E 05-0.57897E 06 0.40494E 07-0.11564E 08 0.11560E 08
 -0.70372E 00 0.73453E 01-0.51 10E 02 0.14504E 03-0.14460E 03
 0.49824E 02-0.88689E 03 0.61947E 04-0.17676E 05 0.17661E 05
 -0.87881E 03 0.17140E 05-0.11986E 06 0.34225E 06-0.34211E 06
 0.24659E 04-0.48668E 05 0.34038E 06-0.97199E 06 0.97166E 06
 -0.18046E 04 0.35763E 05-0.25013E 06 0.71431E 06-0.71407E 06
 0.80046E 01-0.79977E 02 0.55440E 03-0.15747E 04 0.15688E 04
 -0.54765E 03 0.96137E 04-0.67115E 05 0.19145E 06-0.19125E 06
 0.958455 04-0.18578E 06 0.12988E 07-0.37081E 07 0.37063E 07
 -0.26866E 05 0.52751E 06-0.36886E 07 0.10532E 08-0.10528E 08
 0.19655E 05-0.38764E 06 0.27108E 07-0.77403E 07 0.77372E 07
 -0.93149E 01 0.94023E 02-0.65172E 03 0.18510E 04-0.18440E 04
 0.64162E 03-0.11300E 05 0.78885E 05-0.22502E 06 0.22479E 06
 -0.11249E 05 0.21837E 06-0.15266E 07 0.43585E 07-0.43563E 07
 0.31539E 05-0.62003E 06 0.43355E 07-0.12379E 08 0.12374E 08
 -0.23075E 05 0.45563E 06-0.31861E 07 0.90976E 07-0.90939E 07
 0.38153E 01-0.38882E 02 0.26951E 03-0.76546E 03 0.76256E 03
 -0.26454E 03 0.46729E 04-0.32621E 05 0.93052E 05-0.92955E 05
 0.46459E 04-0.90306E 05 0.63134E 06-0.18025E 07 0.18016E 07
 -0.13028E 05 0.25641E 06-0.17930E 07 0.51194E 07-0.51172E 07
 0.95327E 04-0.18842E 06 0.13176E 07-0.37623E 07 0.37607E 07
 -0.65653E 00 0.67349E 01-0.46687E 02 0.13261E 03-0.13211E 03
 0.45739E 02-0.80962E 03 0.56521E 04-0.16123E 05 0.16106E 05
 -0.80431E 03 0.15649E 05-0.10940E 06 0.31235E 06-0.31219E 06
 0.22559E 04-0.44432E 05 0.31069E 06-0.88711E 06 0.88674E 06
 -0.16506E 04 0.32650E 05-0.22832E 06 0.65193E 06-0.65167E 06
 0.40392E-01-0.41603E 00 0.28843E 01-0.81932E 01 0.81628E 01
 -0.28228E 01 0.50030E 02-0.34928E 03 0.99636E 03-0.99535E 03
 0.49682E 02-0.96718E 03 0.67619E 04-0.19305E 05 0.19296E 05
 -0.13936E 03 0.27462E 04-0.19203E 05 0.54830E 05-0.54808E 05
 0.10197E 03-0.20179E 04 0.14111E 05-0.40294E 05 0.40278E 05

B.FOR SECTOR 2

-0.40268E 03 0.27720E 04-0.18464E 05 0.51151E 05-0.50130E 05
 0.18877E 05-0.29920E 06 0.20631E 07-0.58414E 07 0.58074E 07
 -0.30191E 06 0.56271E 07-0.39108E 08 0.11125E 09-0.11095E 09
 0.83598E 06-0.15926E 08 0.11080E 09-0.31541E 09 0.31467E 09
 -0.60908E 06 0.11692E 08-0.81370E 08 0.20168E 09-0.23117E 09
 0.44476E 03-0.31310E 04 0.20104E 05-0.5 540E 05 0.56331E 05
 -0.21003E 05 0.33559E 06-0.23121E 07 0.65429E 07-0.65027E 07
 0.33674E 06-0.62983E 07 0.43754E 08-0.12444E 09 0.12408E 09
 -0.93276E 06 0.17821E 08-0.12394E 09 0.35273E 09-0.35185E 09
 0.67969E 06-0.13081E 08 0.91012E 08-0.25908E 09 0.25847E 09
 -0.17310E 03 0.12318E 04-0.81611E 04 0.22530E 05-0.22029E 05
 0.81728E 04-0.13096E 06 0.90137E 06-0.25492E 07 0.25325E 07
 -0.13092E 06 0.24514E 07-0.17022E 08 0.48397E 08-0.48246E 08
 0.36260E 06-0.69339E 07 0.48203E 08-0.13715E 09 0.13679E 09
 -0.26421E 06 0.50892E 07-0.35394E 08 0.10073E 09-0.10048E 09
 0.28490E 02-0.20372E 03 0.13468E 04-0.37127E 04 0.36267E 04
 -0.13420E 04 0.21522E 05-0.14102E 06 0.41841E 06-0.41555E 06
 0.21459E 05-0.40191E 06 0.27896E 07-0.79297E 07 0.79038E 07
 -0.59418E 05 0.11365E 07-0.78977E 07 0.22467E 08-0.22404E 08
 0.43292E 05-0.83403E 06 0.57985E 07-0.16499E 08 0.16456E 08
 -0.16889E 01 0.12103E 02-0.79884E 02 0.21999E 03-0.21474E 03
 0.79343E 02-0.12726E 04 0.87477E 04-0.24719E 05 0.24544E 05
 -0.12662E 04 0.23713E 05-0.16454E 06 0.4 764E 06-0.46607E 06
 0.35049E 04-0.67033E 05 0.46572E 06-0.13247E 07 0.13208E 07
 -0.25534E 04 0.49190E 05-0.34191E 06 0.97274E 06-0.97010E 06
 0.86018E 03-0.59198E 04 0.39241E 05-0.10837E 06 0.10598E 06
 -0.39774E 05 0.63032E 06-0.43391E 07 0.12273E 08-0.12193E 08
 0.63403E 06-0.11811E 08 0.82021E 08-0.23322E 09 0.23250E 09
 -0.17547E 07 0.33412E 08-0.23229E 09 0.66097E 09-0.65923E 09
 0.12783E 07-0.24524E 08 0.17057E 09-0.48545E 09 0.48424E 09
 -0.95269E 03 0.66937E 04-0.44253E 05 0.12199E 06-0.11917E 06
 0.44331E 05-0.70734E 06 0.48649E 07-0.13752E 08 0.13658E 08
 -0.70768E 06 0.13224E 08-0.91788E 08 0.26092E 09-0.26007E 09
 0.19590E 07-0.37397E 08 0.25989E 09-0.73932E 09 0.73726E 09
 -0.14272E 07 0.27445E 08-0.19081E 09 0.54295E 09-0.54153E 09
 0.37165E 03-0.26360E 04 0.17375E 05-0.47805E 05 0.46635E 05
 -0.17274E 05 0.27618E 06-0.18974E 07 0.53601E 07-0.53212E 07
 0.27532E 06-0.51487E 07 0.35718E 08-0.10150E 09 0.10115E 09
 -0.76194E 06 0.14555E 08-0.10110E 09 0.28753E 09-0.28668E 09
 0.55504E 06-0.10680E 08 0.74223E 08-0.21114E 09 0.21055E 09
 -0.61282E 02 0.43637E 03-0.28697E 04 0.78837E 04-0.76829E 04
 0.28396E 04-0.45413E 05 0.31174E 06-0.8 020E 06 0.87353E 06
 -0.45154E 05 0.84441E 06-0.58554E 07 0.16635E 08-0.16575E 08
 0.12492E 06-0.23862E 07 0.16569E 08-0.47112E 08 0.46966E 08
 -0.90986E 05 0.17508E 07-0.12163E 08 0.34593E 08-0.34492E 08
 0.36382E 01-0.25947E 02 0.17035E 03-0.46748E 03 0.45524E 03
 -0.16806E 03 0.26869E 04-0.18434E 05 0.52028E 05-0.51621E 05
 0.26658E 04-0.49839E 05 0.34549E 06-0.98135E 06 0.97767E 06
 -0.73722E 04 0.14079E 06-0.97738E 06 0.27786E 07-0.27696E 07
 0.53689E 04-0.10329E 06 0.71739E 06-0.20400E 07 0.20339E 07

-0.64010E 03 0.44785E 04-0.29519E 05 0.81217E 05-0.79229E 05
 0.29489E 05-0.46925E 06 0.32239E 07-0.91072E 07 0.90411E 07
 -0.46914E 06 0.87538E 07-0.60727E 08 0.17257E 09-0.17197E 09
 0.12980E 07-0.24747E 08 0.17190E 09-0.48888E 09 0.48743E 09
 -0.94538E 06 0.18159E 08-0.12620E 09 0.35900E 09-0.35800E 09
 0.71264E 03-0.50706E 04 0.33327E 05-0.91520E 05 0.89166E 05
 -0.32940E 05 0.52694E 06-0.36165E 07 0.10210E 08-0.10132E 08
 0.52419E 06-0.98043E 07 0.67980E 08-0.19312E 09 0.19241E 09
 -0.14503E 07 0.27707E 08-0.19238E 09 0.54696E 09-0.54525E 09
 0.10564E 07-0.20329E 08 0.1422E 09-0.40162E 09 0.40044E 09
 -0.27912E 03 0.19999E 04 0.13103E 05 0.35906E 05-0.34932E 05
 0.12859E 05-0.20591E 06-0.14116E 07-0.39821E 07 0.39497E 07
 -0.20413E 06 0.38191E 07-0.26464E 08 0.75153E 08-0.74861E 08
 0.56456E 06-0.10788E 08 0.74866E 08-0.21279E 09 0.21208E 09
 -0.41116E 06 0.79141E 07-0.54950E 08 0.15623E 09-0.15574E 09
 0.46166E 02-0.33152E 03 0.21667E 04-0.59278E 04 0.57606E 04
 -0.21173E 04 0.33887E 05-0.23209E 06 0.65438E 06-0.64882E 06
 0.33507E 05-0.62666E 06 0.43404E 07-0.12322E 08 0.12272E 08
 -0.92627E 05 0.17695E 07-0.12275E 08 0.34880E 08-0.34758E 08
 0.67447E 05-0.12979E 07 0.90082E 07-0.25606E 08 0.25522E 08
 -0.27474E 01 0.19736E 02-0.12876E 03 0.31187E 03-0.34168E 03
 0.12548E 03-0.20067E 04 0.13735E 05-0.38710E 05 0.38371E 05
 -0.19798E 04 0.37006E 05-0.25623E 06 0.72728E 06-0.72422E 06
 0.54702E 04-0.10445E 06 0.72437E 06-0.20580E 07 0.20506E 07
 -0.39824E 04 0.76606E 05-0.53155E 06 0.15107E 07-0.15055E 07
 0.21232E 03-0.14924E 04 0.97474E 04-0.26656E 05 0.25897E 05
 -0.96099E 04 0=15233E 06-0.10430E 07 0.29404E 07-0.29152E 07
 0.15154E 06-0.28208E 07 0.19536E 08-0.55459E 08 0.55231E 08
 -0.41869E 06 0.79665E 07-0.55258E 08 0.15701E 09-0.15646E 09
 0.30481E 06-0.58437E 07 0.40556E 08-0.11528E 09 0.11489E 09
 -0.23760E 03 0.16931E 04-0.11024E 05 0.30084E 05-0.29185E 05
 0.10758E 05-0.17123E 06 0.11171E 07-0.32990E 07 0.32691E 07
 -0.16952E 06 0.31612E 07-0.21880E 08 0.62091E 08-0.61821E 08
 0.46830E 06-0.89241E 07 0.61868E 08-0.17574E 09 0.17509E 09
 -0.34091E 06 0.65452E 07-0.45402E 08 0.12901E 09-0.12856E 09
 0.93469E 02-0.66938E 03 0.43432E 04-0.11824E 05 0.11452E 05
 -0.42090E 04 0.66999E 05-0.45760E 06 0.12880E 07-0.12756E 07
 0.66094E 05-0.12323E 07 0.85234E 07-0.2177E 08 0.24065E 08
 -0.18248E 06 0.34770E 07-0=24091E 08 0.68406E 08-0.68135E 08
 0.13282E 06-0.25497E 07 0.17676E 08-0.50211E 08 0.50024E 08
 -0.15514E 02 0=11119E 03-0.71952E 03 0.19554E 04-0.18916E 04
 0.69432E 03-0.11040E 05 0.75327E 05-0.21188E 06 0.20976E 06
 -0.10861E 05 0.20236E 06-0.13989E 07 0.39667E 07-0.39475E 07
 0.29968E 05-0.57069E 06 0.39522E 07-0.11219E 08 0.11173E 08
 -0.21807E 05 0.41842E 06-0.28995E 07 0.82340E 07-0.82019E 07
 0.92577E 00-0.66307E 01 0.42830E 02-0.11625E 03 0.11236E 03
 -0.41218E 02 0.65461E 03 0.44631E 04 0.12548E 05-0.12419E 05
 0.64237E 03-0.11960E 05 0.82642E 05-0.23428E 06 0.23312E 06
 -0.17714E 04 0.33713E 05-0.23339E 06 0.66239E 06-0.65956E 06
 0.12887E 04-0.24714E 05 0.17120E 06-0.48608E 06 0.48413E 06

-0.32425E 02 0.22903E 03-0.14780E 04 0.40090E 04-0.38729E 04
 0.14341E 04-0.22563E 05 0.15378E 06-0.43226E 06 0.42774E 06
 -0.22316E 05 0.41342E 06-0.28564E 07 0.80970E 07-0.80562E 07
 0.61520E 05-0.11658E 07 0.80696E 07-0.22901E 08 0.22802E 08
 -0.44750E 05 0.85465E 06-0.59199E 07 0.16807E 08-0.16739E 08
 0.36460E 02-0.26055E 03 0.16756E 04-0.45343E 04 0.43732E 04
 -0.16094E 04 0.25403E 05-0.17289E 06 0.48555E 06-0.48019E 06
 0.24997E 05-0.46373E 06 0.32016E 07-0.90715E 07 0.90231E 07
 -0.68890E 05 0.13069E 07-0.90410E 07 0.2 648E 08-0.25531E 08
 0.50105E 05-0.95796E 06 0.66315E 07-0.18820E 08 0.18739E 08
 -0.14405E 02 0.10334E 03 0.66204E 03 0.17868E 04-0.17202E 04
 0.63128E 03-0.99584E 04 0.67669E 05-0.18986E 06 0.18764E 06
 -0.97610E 04 0.18 97E 06-0.12484E 07 0.35355E 07-0.35155E 07
 0.26880E 05-0.50972E 06 0.35236E 07-0.99913E 07 0.99429E 07
 -0.19546E 05 0.37353E 06-0.25840E 07 0.73304E 07-0.72970E 07
 0.2 994E 01-0.17214E 02 0.10996E 03-0.29621E 03 0.28477E 03
 -0.10438E 03 0.16441E 04-0.11159E 05 0.31285E 05-0.30904E 05
 0.16063E 04-0.29754E 05 0.20512E 06-0.58065E 06 0.57722E 06
 -0.44202E 04 0.83751E 05-0.57862E 06 0.16402E 07-0.16319E 07
 0.32132E 04-0.61361E 05 0.42426E 06-0.12032E 07 0.11974E 07
 -0.14360E 00 0.10290E 0100.65611E 01 0.17E50E 02-0.16953E 02
 0.62100E 01-0.97678E 02 0.66240E 03-0.18561E 04 0.18329E 04
 -0.95144E 02 0.17607E 04-0.12132E 05 0.34334E 05-0.34125E 05
 0.26161E 03-0.49531E 04 0.34206E 05-0.9 937E 05 0.96430E 05
 -0.19012E 03 0.36282E 04-0.25076E 05 0.71097E 05-0.70746E 05
 0.18582E 01-0.13233E 02 0.84221E 02-0.22628E 03 0.21715E 03
 -0.80219E 02 0.125 7E 04-0.84758E 04 0.23739E 05-0.23436E 05
 0.12294E 04-0.22640E 05 0.15596E 06-0.44129E 06 0.43855E 06
 -0.33805E 04 0.63724E 05-0.43998E 06 0.12467E 07-0.12400E 07
 0.24566E 04-0.46686E 05 0.32260E 06-0.91451E 06 0.90993E 06
 -0.20982E 01 0.15097E 02-0.95723E 02 0.25650E 03-0.24569E 03
 0.90231E 02-0.14103E 04 0.95413E 04-0.26696E 05 0.26336E 05
 -0.13790E 04 0.25417E 05-0.17493E 06 0.49471E 06-0.49147E 06
 0.37897E 04-0.71496E 05 0.49325E 06-0.13970E 07 0.13891E 07
 -0.27535E 04 0.52367E 05-0.36159E 06 0.10246E 07-0.10192E 07
 0.83224E 00-0.60072E 01 0.37931E 02-0.10135E 03 0.96872E 02
 -0.35480E 02 0.55391E 03-0.37405E 04 0.10453E 05-0.10305E 05
 0.53926E 03-0.99302E 04 0.68276E 05-0.19296E 06 0.19162E 06
 -0.14806E 04 0.27911E 05-0.19239E 06 0.54459E 06-0.54134E 06
 0.10754E 04-0.20438E 05 0.14100E 06-0.39934E 06 0.39710E 06
 -0.13906E 00 0.10032E 01-0.63157E 01 0.16838E 02-0.16070E 02
 0.58789E 01-0.91611E 02 0.61777E 03-0.17249E 04 0.16994E 04
 -0.88865E 02 0.16343E 04-0.11228E 05 0.31719E 05-0.31488E 05
 0.24377E 03-0.45903E 04 0.31620E 05-0.89466E 05 0.88908E 05
 -0.17699E 03 0.33603E 04-0.23169E 05 0.65591E 05-0.65206E 05
 0.83440E-02-0.60102E-01 0.37760E 00-0.10053E 01 0.95848E 00
 -0.35040E 00 0.54514E 01-0.36727E 02 0.10249E 03-0.10093E 03
 0.52699E 01-0.96814E 02 0.66477E 03-0.18773E 04 0.18632E 04
 -0.14443E 02 0.27173E 03-0.18708E 04 0.52919E 04-0.52579E 04
 0.10483E 02-0.19887E 03 0.13705E 04-0.38789E 04 0.38554E 04

C.FOR SECTOR 3

-^ 11647E 03 0.11370E 04 -0.77710E 04 0.21882E 05 -0.21678E 05
 0.69404E 04 -0.13177E 06 0.91615E 06 -0.26069E 07 0.26001E 07
 -0.12429E 06 0.25290E 07 0.17646E 08 0.50322E 08 -0.50260E 08
 0.35003E 06 -0.71787E 07 -0.50114E 08 -0.14295E 09 0.14280E 09
 -0.25658E 06 0.52758E 07 -0.36836E 08 0.10508E 09 -0.10498E 09
 0.12500E 03 -0.12723E 04 0.86896E 04 -0.24458E 05 0.24223E 05
 -0.76626E 04 0.14718E 06 -0.10231E 07 0.29107E 07 -0.29029E 07
 0.13820E 06 -0.28242E 07 0.19704E 08 -0.56186E 08 0.56115E 08
 -0.38958E 06 0.80167E 07 -0.55959E 08 0.15961E 09 -0.15944E 09
 0.28568E 06 -0.58917E 07 0.41133E 08 -0.11734E 09 0.11722E 09
 -0.47469E 02 0.49596E 03 -0.33824E 04 0.95118E 04 -0.94151E 04
 0.29561E 04 -0.57159E 05 0.39714E 06 -0.11296E 07 0.11264E 07
 -0.53510E 05 0.10962E 07 0.76469E 07 0.21802E 08 -0.21773E 08
 0.15092E 06 -0.31117E 07 -0.21717E 08 -0.61938E 08 0.61867E 08
 -0.11069E 06 0.22870E 07 -0.15964E 08 0.45534E 08 -0.45484E 08
 0.76537E 01 -0.81348E 02 0.55412E 03 -0.15571E 04 0.15405E 04
 -0.48127E 03 0.93462E 04 -0.64914E 05 0.18460E 06 -0.18405E 06
 0.87326E 04 -0.17920E 06 0.12498E 07 -0.35629E 07 0.35579E 07
 -Q 24639E 05 0.50867E 06 -0.35496E 07 0.10123E 08 -0.10110E 08
 0.18074E 05 -0.37386E 06 0.26093E 07 -0.74419E 07 0.74334E 07
 -^ 44592E 00 0.47953E 01 -0.32634E 02 0.91650E 02 -0.90639E 02
 0.28219E 02 -0.54965E 03 0.38165E 04 -0.10851E 05 0.10818E 05
 -0.51293E 03 0.10538E 05 -0.73486E 05 0.20948E 06 -0.20918E 06
 0.14477E 04 -0.29915E 05 0.20873E 06 -0.59521E 06 0.59447E 06
 -0.10621E 04 0.21988E 05 -0.15344E 06 0.43761E 06 -0.43709E 06
 0.24778E 03 -0.23756E 04 0.16155E 05 -0.45348E 05 0.44833E 05
 -0.14308E 05 0.27165E 06 -0.18857E 07 0.53609E 07 -0.53437E 07
 0.25544E 06 -0.51981E 07 0.36244E 08 -0.10331E 09 0.10316E 09
 -0.71911E 06 0.14749E 08 -0.10290E 09 0.29340E 09 -0.29303E 09
 0.52707E 06 -0.10837E 08 0.75624E 08 -0.21566E 09 0.21540E 09
 -0.26617E 03 0.26604E 04 -0.18075E 05 0.50710E 05 -0.50116E 05
 0.15815E 05 -0.30349E 06 0.21062E 07 -0.59866E 07 0.59668E 07
 -0.28410E 06 0.58055E 07 -0.40474E 08 0.11536E 09 -0.11518E 09
 0.80049E 06 -0.16472E 08 0.11491E 09 -0.32763E 09 0.32719E 09
 -0.58689E 06 0.12104E 08 -0.84453E 08 0.24082E 09 -0.24052E 09
 0.10119E 03 -0.10375E 04 0.70382E 04 -0.19727E 05 0.19484E 05
 -0.61051E 04 0.11788E 06 0.81772E 06 0.23236E 07 -0.23155E 07
 0.11002E 06 -0.22537E 07 -0.15709E 08 -0.44766E 08 0.44693E 08
 -0.31014E 06 0.63943E 07 -0.44598E 08 0.12714E 09 -0.12696E 09
 0.22743E 06 -0.46986E 07 0.32778E 08 -0.93458E 08 0.93334E 08
 -0.16333E 02 0.17025E 03 -0.11535E 04 0.32304E 04 -0.31889E 04
 0.99451E 03 -0.19279E 05 0.13368E 06 -0.37977E 06 0.37839E 06
 -0.17958E 05 0.36844E 06 -0.25676E 07 0.73162E 07 -0.73037E 07
 0.50639E 05 -0.10454E 07 0.72897E 07 -0.20780E 08 0.20750E 08
 -0.37138E 05 0.76816E 06 -0.53579E 07 0.1 275E 08 -0.15254E 08
 0.95252E 00 -0.10042E 02 0.67963E 02 -0.19021E 03 0.18769E 03
 -^ 58340E 02 0.11340E 04 -0.78608E 04 0.22327E 05 -0.22243E 05
 0.10550E 04 -0.21669E 05 0.15098E 06 -0.43019E 06 0.42943E 06
 -0.29757E 04 0.61484E 05 -0.42870E 06 0.12220E 07 -0.12201E 07
 ^ 21826E 04 -0.45182E 05 0.31510E 06 -0.89829E 06 0.89701E 06

-0.18597E 03 0.18420E 04-0.12488E 05 0.34986E 05-0.34546E 05
 0.10921E 05-0.20887E 06 0.14486E 07-0.41157E 07 0.41010E 07
 -0.19550E 06 0.39882E 07-0.27796E 08 0.79208E 08-0.79075E 08
 0.55053E 06-0.11312E 08 0.78892E 08-0.22490E 09 0.22458E 09
 -0.40353E 06 0.83113E 07-0.57975E 08 0.1 529E 09-0.16507E 09
 0.20110E 03-0.20640E 04 0.13979E 05-0.39138E 05 0.38630E 05
 -0.12091E 05 0.23342E 06-0.16183E 07 0.45971E 07-0.45801E 07
 0.21757E 06-0.44549E 07 0.31044E 08-0.88455E 08 0.88302E 08
 -0.61311E 06 0.12636E 08-0.88111E 08 0.25116E 09-0.25079E 09
 0.44952E 06-0.92837E 07 0.64750F 08-0.18460E 09 0.18434E 09
 -0.76805E 02 0.80554E 03-0.54467E 04 0.15234E 05-0.15026E 05
 0.46737E 04-0.90701E 05 0.62851E 06-0.17848E 07 0.17779E 07
 -0.84299E 05 0.17298E 07-0.12051E 08 0.34332E 08-0.34269E 08
 0.23764E 06-0.49060E 07 0.34203E 08-0.97483E 08 0.97330E 08
 -0.17426E 06 0.36045E 07-0.25135E 08 0.71648E 08-0.71542E 08
 0.12438E 02-0.13229E 03 0=89324E 03-0.24962E 04 0.24606E 04
 -0.76212E 03 0.14840E 05-0.10279E 06 0.29181E 06-0.29063E 06
 0.13766E 05-0.28285E 06 0.19701E 07-0.51120E 07 0.56013E 07
 -0.38815E 05 0.80222E 06-0.55917E 07 0.1 935E 08-0.15909E 08
 0.28465E 05-0.58939E 06 0.41093E 07-0.11713E 08 0.11694E 08
 -0.72722E 00 0.78086E 01-0.52663E 02 0.14706E 03-0.14490E 03
 0.44747E 02-0.87331E 03 0.60468E 04-0.17163E 05 0.17091E 05
 -0.80904E 03 0.16640E 05-0.11588E 06 0.33006E 06-0.32941E 06
 0.22817E 04-0.47194E 05 0.32891E 06-0.93726E 06 0.93568E 06
 -0.16734E 04 0.34675E 05-0.24172E 06 0.68891E 06-0.68781E 06
 0.61178E 02-0.61261E 03 0.41306E 04-0.11533E 05 0.11362E 05
 -0.35738E 04 0.68453E 05-0.47393E 06 0.13451E 07-0.13394E 07
 0.63841E 05-0.13031E 07 0.90743E 07-0.25846E 08 0.25794E 08
 -0.17975E 06 0.36952E 07-0.25752E 08 0.73380E 08-0.73255E 08
 0.13175E 06-0.27147E 07 0.18924E 08-0.53932E 08 0.53845E 08
 -0.66520E 02 0.68686E 03-0.46259E 04 0.12906E 05-0.12708E 05
 0.39602E 04-0.76510E 05 0.52951E 06-0.15025E 07 0.14960E 07
 -0.71067E 05 0.14557E 07-0.10135E 08 0.28864E 08-0.28805E 08
 0.20023E 06-0.41278E 07 0.28762E 08-0.81951E 08 0.81806E 08
 -0.14680E 06 0.30325E 07-0.21136E 08 0.60232E 08-0.60132E 08
 0.25515E 02-0.26833E 03 0.18037E 04-0.50263E 04 0.49454E 04
 -0.15319E 04 0.29737E 05-0.20568E 06 0.58342E 06-0.58073E 06
 0.27543E 05-0.56528E 06 0.39346E 07-0.11203E 08 0.11179E 08
 -0.77624E 05 0.16028E 07-0.11166E 08 0.31809E 08-0.31750E 08
 0.56918E 05-0.11775E 07 0.82053E 07-0.21380E 08 0.23339E 08
 -0.41451E 01 0.44103E 02-0.29598E 03 0.82391E 03-0.81009E 03
 0.24993E 03-0.48663E 04 0.33640E 05-0.95391E 05 0.94930E 05
 -0.44984E 04 0.92441E 05-0.64326E 06 0.18314E 07-0.18272E 07
 0.12680E 05-0.26211E 06 0.18255E 07-0.51999E 07 0.51898E 07
 -0.92988E 04 0.19257E 06-0.13416E 07 0.38221E 07-0.38151E 07
 0.24292E 00-0.26046E 01 0.17457E 02-0.48555E 02 0.47714E 02
 -0.14679E 02 0.28640E 03-0.19790E 04 0.56102E 04-0.55822E 04
 0.26440E 03-0.54383E 04 0.37836E 05-0.10770E 06 0.10745E 06
 -0.74544E 03 0.15420E 05-0.10738E 06 0.30584E 06-0.30522E 06
 0.54670E 03-0.11329E 05 0.78918E 05-0.22481E 06 0.22438E 06

-0.92198E 01 0.92609E 02 -0.61925E 03 0.17198E 04 -0.16883E 04
 0.52923E 03 -0.10114E 05 0.69830E 05 -0.19787E 06 0.19682E 06
 -0.93884E 04 0.19142E 06 -0.13312E 07 0.37887E 07 -0.37792E 07
 0.26410E 05 -0.54242E 06 0.37759E 07 -0.10752E 08 0.10729E 08
 -0.19352E 05 0.39841E 06 -0.27743E 07 0.79016E 07 -0.78857E 07
 0.10075E 02 -0.10397E 03 0.69425E 03 -0.1 263E 04 0.18899E 04
 -0.58707E 03 0.11311E 05 -0.78058E 05 0.22112E 06 -0.21991E 06
 0.10456E 05 -0.21391E 06 0.14873E 07 -0.42322E 07 0.42212E 07
 -0.29429E 05 0.60611E 06 -0.42184E 07 0.12011E 08 -0.11984E 08
 0.21569E 05 -0.44518E 06 0.30994E 07 -0.88267E 07 0.88083E 07
 -0.38812E 01 0.40697E 02 -0.27114E 03 0.75125E 03 -0.73634E 03
 0.22738E 03 -0.44001E 04 0.30343E 05 -0.85915E 05 0.85419E 05
 -0.40546E 04 0.83106E 05 -0.57762E 06 0.1 433E 07 -0.16388E 07
 0.11415E 05 -0.23546E 06 0.16382E 07 -0.46636E 07 0.46527E 07
 -0.83672E 04 0.17294E 06 -0.12037E 07 0.34273E 07 -0.34198E 07
 0.63275E 00 -0.67010E 01 0.44560E 02 -0.12331E 03 0.12076E 03
 -0.37140E 02 0.72069E 03 -0.49667E 04 0.1 057E 05 -0.13973E 05
 0.66258E 03 -0.13597E 05 0.94377E 05 -0.26873E 06 0.26796E 06
 -0.18656E 04 0.38522E 05 -0.26795E 06 0.76266E 06 -0.76080E 06
 0.13676E 04 -0.28294E 05 0.19688E 06 -0.56051E 06 0.55922E 06
 -0.37186E -01 0.39639E 00 -0.26318E 01 0.72759E 01 -0.71210E 01
 0.21836E 01 -0.42454E 02 0.29243E 03 -0.82739E 03 0.82223E 03
 -0.38966E 02 0.80036E 03 -0.55597E 04 0.15812E 05 -0.15765E 05
 0.10973E 03 -0.22674E 04 0.15768E 05 -0.44875E 05 0.44762E 05
 -0.80445E 02 0.16655E 04 -0.11587E 05 0.32982E 05 -0.32904E 05
 0.52204E 00 -0.52539E 01 0.34766E 02 -0.95900E 02 0.93717E 02
 -0.29293E 02 0.55719E 03 -0.38335E 04 0.10839E 05 -0.10766E 05
 0.51441E 03 -0.10464E 05 0.72646E 05 -0.20653E 06 0.20587E 06
 -0.14450E 04 0.29621E 05 -0.20589E 06 0.58576E 06 -0.58417E 06
 0.10583E 04 -0.21749E 05 0.15123E 06 -0.43037E 06 0.42926E 06
 -0.57302E 00 0.59089E 01 -0.39035E 02 0.10756E 03 -0.10503E 03
 0.32536E 02 -0.62368E 03 0.42884E 04 -0.12120E 05 0.12036E 05
 -0.57322E 03 0.11699E 05 -0.81195E 05 0.23079E 06 -0.23003E 06
 0.16110E 04 -0.33113E 05 0.23010E 06 -0.6 455E 06 0.65271E 06
 -0.11801E 04 0.24312E 05 -0.16902E 06 0.48091E 06 -0.47964E 06
 0.22170E 00 -0.23188E 01 0.15278E 02 -0.42024E 02 0.40989E 02
 -0.12622E 02 0.24294E 03 -0.16688E 04 0.47140E 04 -0.46795E 04
 -0.22247E 03 -0.45485E 04 0.31553E 05 -0.89664E 05 0.89352E 05
 -0.62531E 03 0.12872E 05 -0.89410E 05 0.25428E 06 -0.25352E 06
 0.45809E 03 -0.94502E 04 0.65674E 05 -0.18682E 06 0.18630E 06
 -0.36271E -01 0.38271E 00 -0.25160E 01 0.69104E 01 -0.67336E 01
 0.20649E 01 -0.39843E 02 0.27348E 03 -0.77213E 03 0.76624E 03
 -0.36385E 02 0.74477E 03 -0.51645E 04 0.14672E 05 -0.14619E 05
 0.10227E 03 -0.21073E 04 0.14633E 05 -0.41607E 05 0.41478E 05
 -0.74928E 02 0.15471E 04 -0.10748E 05 0.30570E 05 -0.30481E 05
 0.21378E -02 -0.22687E -01 0.14889E 00 -0.40848E 00 0.39772E 00
 -0.12159E 00 0.23503E 01 -0.16122E 02 0.45501E 02 -0.45143E 02
 0.21416E 01 -0.43874E 02 0.30415E 03 -0.86390E 03 0.86067E 03
 -0.60199E 01 0.12413E 03 -0.86172E 03 0.24498E 04 -0.24419E 04
 0.44105E 01 -0.91132E 02 0.63296E 03 -0.18000E 04 0.17945E 04

-0.28538E 02 0.38558E 03-0.26395E 04 0.74400E 04-0.73755E 04
 0.20905E 04-0.44899E 05 0.31231E 06-0.88894E 06 0.88679E 06
 -0.40270E 05 0.86372E 06-0.60281E 07 0.17193E 08-0.17173E 08
 0.11452E 06-0.24525E 07 0.17124E 08-0.48852E 08 0.48805E 08
 -0.84235E 05 0.18026E 07-0.12589E 08 0.35916E 08-0.35883E 08
 0.30065E 02-0.42934E 03 0.29405E 04-0.82909E 04 0.82207E 04
 -0.23153E 04 0.50065E 05-0.34830E 06 0.99146E 06-0.98912E 06
 0.44879E 05-0.96372E 06 0.67265E 07-0.19185E 08 0.19164E 08
 -0.12772E 06 0.27368E 07-0.19110E 08 0.54520E 08-0.54469E 08
 0.93966E 05-0.20117E 07 0.14049E 08-0.40085E 08 0.40049E 08
 -0.11255E 02 0.16688E 03-0.11419E 04 0.32181E 04-0.31897E 04
 0.89478E 03-0.19419E 05 0.13506E 06-0.38441E 06 0.38346E 06
 -0.17399E 05 0.37383E 06-0.26089E 07 0.74407E 07-0.74321E 07
 0.49533E 05-0.10617E 07 0.74126E 07-0.21146E 08 0.21126E 08
 -0.36448E 05 0.78042E 06-0.54498E 07 0.1 548E 08-0.15534E 08
 0.17950E 01-0.27316E 02 0.18674E 03-0.52596E 03 0.52113E 03
 -0.14580E 03 0.31716E 04-0.22053E 05 0.62755E 05-0.62594E 05
 0.28412E 04-0.61068E 05 0.42613E 06-0.12152E 07 0.12138E 07
 -0.80909E 04 0.17345E 06-0.12109E 07 0.34541E 07-0.34505E 07
 0.59542E 04-0.12750E 06 0.89029E 06-0.2 398E 07 0.25374E 07
 -0.10369E 00 0.16075E 01-0.10981E 02 0.30911E 02-0.30617E 02
 0.85496E 01-0.18629E 03 0.12950E 04-0.3 847E 04 0.36749E 04
 -0.16692E 03 0.35886E 04-0.25039E 05 0.71399E 05-0.71310E 05
 0.47546E 03-0.10194E 05 0.71158E 05-0.20297E 06 0.20275E 06
 -0.34994E 03 0.74941E 04-0.52322E 05 0.14926E 06-0.14911E 06
 0.60712E 02-0.75531E 03 0.51118E 04-0.14307E 05 0.14117E 05
 -0.39683E 04 0.85317E 05-0.59139E 06 0.16798E 07-0.16734E 07
 0.75760E 05-0.16305E 07 0.11361E 08-0.32370E 08 0.32312E 08
 -0.21522E 06 0.46250E 07-0.32248E 08 0.91919E 08-0.91780E 08
 0.15825E 06-0.33980E 07 0.23698E 08-0.67558E 08 0.67461E 08
 -0.63347E 02 0.84193E 03-0.56991E 04 0.15952E 05-0.15742E 05
 0.43976E 04-0.95163E 05 0.65968E 06-0.18738E 07 0.18668E 07
 -0.84466E 05 0.18195E 07-0.12678E 08 0.36124E 08-0.36061E 08
 0.24011E 06-0.51616E 07 0.35990E 08-0.10259E 09 0.10243E 09
 -0.17658E 06 0.37924E 07-0.26449E 08 0.75402E 08-0.75295E 08
 0.23595E 02-0.32722E 03 0.22132E 04-0.61916E 04 0.61079E 04
 -0.16995E 04 0.36912E 05-0.25581E 06 0.72650E 06-0.72371E 06
 0.32750E 05-0.70579E 06 0.49173E 07-0.14010E 08 0.13985E 08
 -0.93133E 05 0.20023E 07-0.13960E 08 0.39789E 08-0.39728E 08
 0.68500E 05-0.14712E 07 0.10259E 08-0.29246E 08 0.29203E 08
 -0.37532E 01 0.53586E 02-0.36206E 03 0.10123E 04-0.99814E 03
 0.27698E 03-0.60295E 04 0.41773E 05-0.11861E 06 0.11814E 06
 -0.53491E 04 0.11530E 06-0.80320E 06 0.22882E 07-0.22839E 07
 0.15215E 05-0.32712E 06 0.22804E 07-0.64992E 07 0.64888E 07
 -0.11192E 05 0.24036E 06-0.16760E 07 0.4 773E 07-0.47701E 07
 0.21656E 00-0.31564E 01 0.21304E 02-0.59525E 02 0.58669E 02
 -0.16249E 02 0.35426E 03-0.24535E 04 0.69653E 04-0.69368E 04
 0.31433E 03-0.67765E 04 0.47198E 05-0.13445E 06 0.13419E 06
 -0.89427E 03 0.19227E 05-0.13401E 06 0.38192E 06-0.38129E 06
 0.65786E 03-0.14128E 05 0.98498E 05-0.28074E 06 0.28031E 06

-0.49127E 02 0.64545E 03-0.43645E 04 0.12209E 05-0.12042E 05
 0.33965E 04-0.72710E 05 0.50386E 06-0.11309E 07 0.14254E 07
 -0.64739E 05 0.13870E 07-0.96626E 07 0.27529E 08-0.27479E 08
 0.18379E 06-0.39323E 07 0.27414E 08-0.78136E 08 0.78014E 08
 -0.13508E 06 0.28882E 07-0.20140E 08 0.57411E 08-0.57326E 08
 0.51858E 02-0.72002E 03 0.48694E 04-0.13622E 05 0.13437E 05
 -0.37687E 04 0.81145E 05-0.56234E 06 0.15970E 07-0.15908E 07
 0.72193E 05-0.15483E 07 0.10787E 08-0.30731E 08 0.30675E 08
 -0.20506E 06 0.43897E 07-0.30604E 08 0.87227E 08-0.87091E 08
 0.15073E 06-0.32242E 07 0.22483E 08-0.64091E 08 0.63996E 08
 -0.19465E 02 0.28010E 03-0.18926E 04 0.52917E 04-0.52180E 04
 0.14583E 04-0.31498E 05 0.21822E 06-0.61964E 06 0.61718E 06
 -0.28003E 05 0.60084E 06-0.41854E 07 0.11924E 08-0.11901E 08
 0.79558E 05-0.17035E 07 0.11875E 08-0.32843E 08 0.33789E 08
 -0.58486E 05 0.12512E 07-0.87239E 07 0.24867E 08-0.24829E 08
 0.31137E 01-0.45919E 02 0.30995E 03-0.86604E 03 0.85361E 03
 -0.23799E 03 0.51500E 04-0.35668E 05 0.10126E 06-0.10085E 06
 0.45763E 04-0.98213E 05 0.68404E 06-0.19485E 07 0.19448E 07
 -0.13003E 05 0.27844E 06-0.19407E 07 0.55306E 07-0.55215E 07
 0.95593E 04-0.20450E 06 0.14257E 07-0.40637E 07 0.40573E 07
 -0.18044E 00 0.27081E 01-0.18261E 02 0.50990E 02-0.50237E 02
 0.13982E 02-0.30294E 03 0.20974E 04-0.59532E 04 0.59281E 04
 -0.26911E 03 0.57762E 04-0.40224E 05 0.11457E 06-0.11434E 06
 0.76472E 03-0.16375E 05 0.11412E 06-0.32520E 06 0.32464E 06
 -0.56220E 03 0.12027E 05-0.83139E 05 0.23894E 06-0.23855E 06
 0.16679E 02-0.22516E 03 0.15166E 04-0.42318E 04 0.41674E 04
 -0.11749E 04 0.25104E 05-0.17375E 06 0.49306E 06-0.49091E 06
 0.22372E 05-0.47835E 06 0.33306E 07-0.94854E 07 0.94660E 07
 -0.63511E 05 0.13563E 07-0.94508E 07 0.26928E 08-0.26881E 08
 0.46682E 05-0.99626E 06 0.69440E 07-0.19789E 08 0.19756E 08
 -0.17730E 02 0.25105E 03-0.16912E 04 0.46193E 04-0.46477E 04
 0.13030E 04-0.28003E 05 0.19382E 06-0.55003E 06 0.54765E 06
 -0.24934E 05 0.53382E 06-0.37169E 07 0.10586E 08-0.10564E 08
 0.70825E 05-0.15137E 07 0.10548E 08-0.30055E 08 0.30002E 08
 -0.52068E 05 0.11119E 07-0.77503E 07 0.22087E 08-0.22050E 08
 0.66860E 01-0.97632E 02 0.65707E 03-0.1 325E 04 0.18039E 04
 -0.50392E 03 0.10864E 05-0.75172E 05 0.21328E 06-0.21233E 06
 0.96668E 04-0.20709E 06 0.14417E 07-0.41056E 07 0.40970E 07
 -0.27467E 05 0.58724E 06-0.40915E 07 0.11657E 08-0.11636E 08
 0.20194E 05-0.43138E 06 0.30064E 07-0.85670E 07 0.85524E 07
 -0.10727E 01 0.15999E 02-0.10754E 03 0.29970E 03-0.29489E 03
 0.82175E 02-0.17750E 04 0.12277E 05-0.34825E 05 0.34665E 05
 -0.15788E 04 0.33835E 05-0.23551E 06 0.67060E 06-0.66914E 06
 0.44870E 04-0.95948E 05 0.66840E 06-0.19042E 07 0.19007E 07
 -0.32992E 04 0.70484E 05-0.49116E 06 0.13995E 07-0.13970E 07
 0.62280E-01-0.94294E 00 0.63311E 01-0.17630E 02 0.17338E 02
 -0.48232E 01 0.10431E 03-0.72120E 03 0.20453E 04-0.20356E 04
 0.92782E 02-0.19887E 04 0.13840E 05-0.39404E 05 0.39316E 05
 -0.26372E 03 0.56399E 04-0.39283E 05 0.11190E 06-0.11169E 06
 0.19393E 03-0.41433E 04 0.28868E 05-0.82247E 05 0.82098E 05

-0.25437E 01 0.34775E 02-0.23252E 03 0.64579E 03-0.63397E 03
 0.17831E 03-0.38007E 04 0.26243E 05-0.74361E 05 0.73968E 05
 -0.33794E 04 0.72147E 05-0.50176E 06 0.14236E 07-0.40539E 07 0.40452E 07
 0.95894E 04-0.20450E 06 0.14236E 07-0.40539E 07 0.40452E 07
 -0.70476E 04 0.15021E 06-0.10460E 07 0.29792E 07-0.29732E 07
 0.27174E 01-0.38764E 02 0.25922E 03-0.71997E 03 0.70683E 03
 -0.19765E 03 0.42385E 04-0.29266E 05 0.82930E 05-0.82492E 05
 0.37648E 04-0.80501E 05 0.55986E 06-0.15934E 07 0.15894E 07
 -0.10690E 05 0.22821E 06-0.15886E 07 0.45239E 07-0.45143E 07
 0.78580E 04-0.16763E 06 0.11673E 07-0.33248E 07 0.33181E 07
 -0.10286E 01 0.15080E 02-0.10073E 03 0.27956E 03-0.27432E 03
 0.76418E 02-0.16441E 04 0.11348E 05-0.32148E 05 0.31974E 05
 -0.14592E 04 0.31225E 05-0.21712E 06 0.61788E 06-0.61630E 06
 0.41447E 04-0.88523E 05 0.61615E 06-0.17544E 07 0.17506E 07
 -0.30472E 04 0.65028E 05-0.45277E 06 0.12895E 07-0.12868E 07
 0.16550E 00-0.24720E 01 0.16489E 02-0.45722E 02 0.44839E 02
 -0.12458E 02 0.26855E 03-0.18527E 04 0.52472E 04-0.52178E 04
 0.23827E 03-0.51007E 04 0.35460E 05-0.10090E 06 0.10063E 06
 -0.67692E 03 0.14462E 05 0.10064E 06 0.28653E 06-0.28588E 06
 0.49772E 03-0.10624E 05 0.73959E 05-0.21061E 06 0.21016E 06
 -0.96291E-02 0.14573E 00-0.97066E 00 0.26892E 01-0.26357E 01
 0.73091E 00-0.15775E 02 0.10878E 03-0.30801E 03 0.30623E 03
 -0.13997E 02 0.29972E 03-0.20832E 04 0.59267E 04-0.59105E 04
 0.39775E 02-0.84988E 03 0.59133E 04-0.11834E 05 0.16794E 05
 -0.29249E 02 0.62439E 03-0.43459E 04 0.12375E 05-0.12347E 05
 0.14517E 00-0.19978E 01 0.13220E 02-0.36470E 02 0.35641E 02
 -0.99926E 01 0.21213E 03-0.14595E 04 0.41267E 04-0.40991E 04
 0.18776E 03-0.40003E 04 0.27773E 05-0.78959E 05 0.78709E 05
 -0.53223E 03 0.11330E 05-0.78756E 05 0.22407E 06-0.22346E 06
 0.39103E 03-0.83202E 04 0.57859E 05-0.16465E 06 0.16423E 06
 -0.15573E 00 0.22272E 01-0.14739E 02 0.40661E 02-0.39738E 02
 0.11074E 02-0.23656E 03 0.16276E 04-0.42021E 04 0.45713E 04
 -0.20913E 03 0.44634E 04-0.30988E 05 0.88102E 05-0.87824E 05
 -0.59319E 03-0.12643E 05 0.87886E 05-0.25005E 06 0.24937E 06
 -0.43592E 03 0.92854E 04-0.64571E 05 0.18376E 06-0.18329E 06
 0.59177E-01-0.86737E 00 0.57320E 01-0.15799E 02 0.15430E 02
 -0.42831E 01 0.91790E 02-0.63124E 03 0.17843E 04-0.17720E 04
 0.81063E 02-0.17315E 04 0.12019E 05-0.34166E 05 0.34055E 05
 -0.23001E 03 0.49052E 04-0.34090E 05 0.96979E 05-0.96710E 05
 0.16905E 03-0.36026E 04 0.25048E 05-0.71274E 05 0.71087E 05
 -0.95516E-02 0.14235E 00-0.93914E 00 0.25857E 01-0.25236E 01
 0.69851E 00-0.14998E 02 0.10308E 03-0.29128E 03 0.28921E 03
 -0.13238E 02 0.28290E 03-0.19631E 04 0.55795E 04-0.55607E 04
 0.37570E 02-0.80147E 03 0.55687E 04-0.15840E 05 0.15794E 05
 -0.27616E 02 0.58866E 03-0.40919E 04 0.11642E 05-0.11611E 05
 0.55718E-03-0.84010E-02 0.55333E-01-0.15218E 00 0.14842E 00
 -0.40996E-01 0.88134E 00-0.60539E 01 0.11100E 02-0.16975E 02
 0.77775E 00-0.16625E 02 0.11534E 03-0.32775E 03 0.32662E 03
 -0.22078E 01 0.47107E 02-0.32723E 03 0.3063E 03-0.92788E 03
 0.16231E 01-0.34602E 02 0.24047E 03-0.6 408E 03 0.68217E 03

E.FOR SECTOR 5

-0.46935E 01 0.96570E 02-0.61694E 03 0.16619E 04-0.15980E 04
 0.36428E 03-0.92586E 04 0.62854E 05-0.1 625E 06 0.17415E 06
 -0.74572E 04 0.17046E 06-0.11756E 07 0.33289E 07-0.33099E 07
 0.21396E 05-0.48152E 06 0.33280E 07-0.94363E 07 0.93906E 07
 -0.15795E 05 0.35343E 06-0.24447E 07 0.69350E 07-0.69035E 07
 0.50745E 01-0.10604E 03 0.67957E 03-0.18347E 04 0.17668E 04
 -0.41218E 03 0.10266E 05-0.69789E 05 0.19587E 06-0.19363E 06
 0.83741E 04-0.18964E 06 0.13088E 07-0.37077E 07 0.36876E 07
 -0.23998E 05 0.53601E 06-0.37069E 07 0.10514E 08-0.10466E 08
 0.17709E 05-0.39353E 06 0.27236E 07-0.77287E 07 0.76954E 07
 -0.19245E 01 0.40980E 02-0.26269E 03 0.70932E 03-0.68316E 03
 0.16162E 03-0.39716E 04 0.27001E 05-0.75784E 05 0.74923E 05
 -0.32635E 04 0.73456E 05-0.50698E 06 0.14363E 07-0.14285E 07
 0.93451E 04-0.20768E 06 0.14364E 07-0.40743E 07 0.40556E 07
 -0.68941E 04 0.15250E 06-0.10555E 07 0.29953E 07-0.29825E 07
 .30972E 00-0.66866E 01 0.42842E 02-0.11565E 03 0.11136E 03
 -0.26583E 02 0.64737E 03-0.44004E 04 0.12349E 05-0.12208E 05
 0.53469E 03-0.11985E 05 0.82715E 05-0.23432E 06 0.23305E 06
 -0.15304E 04 0.33896E 05-0.23442E 06 0.66492E 06-0.66186E 06
 .11289E 04-0.24893E 05 0.17229E 06-0.48891E 06 0.48681E 06
 -0.18013E-01 0.39267E 00-0.25142E 01 0.67836E 01-0.65299E 01
 0.15682E 01-0.37953E 02 0.25791E 03-0.72369E 03 0.71535E 03
 -0.31474E 02 0.70345E 03-0.48543E 04 0.13751E 05-0.13676E 05
 .90072E 02-0.19901E 04 0.13762E 05-0.39034E 05 0.38853E 05
 -0.66440E 02 0.14618E 04-0.10116E 05 0.28707E 05-0.28582E 05
 0.10591E 02-0.15031E 03 0.87932E 03-0.22173E 04 0.20298E 04
 -0.37762E 03 0.10758E 05-0.69573E 05 0.18901E 06-0.18282E 06
 0.71273E 04-0.17990E 06 0.12076E 07-0.33624E 07 0.33066E 07
 -0.20279E 05 0.50081E 06-0.33809E 07 0.94473E 07-0.93128E 07
 0.14933E 05-0.36566E 06 0.24736E 07-0.69212E 07 0.68286E 07
 -0.10667E 02 0.16503E 03-0.96746E 03 0.24437E 04-0.22402E 04
 0.43683E 03-0.119 7E 05 0.77128E 05-0.20976E 06 0.20304E 06
 -0.81585E 04 0.19988E 06-0.13431E 07 0.37419E 07-0.36814E 07
 0.23160E 05-0.55678E 06 0.37620E 07-0.10518E 08 0.10372E 08
 -0.17038E 05 0.40662E 06-0.27529E 07 0.77067E 07-0.76062E 07
 0.38874E 01-0.63540E 02 0.37276E 03-0.94212E 03 0.86405E 03
 -0.17306E 03 0.45981E 04-0.29799E 05 0.81074E 05-0.78497E 05
 0.32114E 04-0.77336E 05 0.51984E 06-0.14486E 07 0.14254E 07
 -0.91041E 04 0.21549E 06-0.14565E 07 0.40729E 07-0.40170E 07
 0.66938E 04-0.15739E 06 0.10659E 07-0.49846E 07 0.29461E 07
 -0.61203E 00 0.10373E 02-0.60132E 02 0.15371E 03-0.14094E 03
 .28729E 02-0.74991E 03 0.48590E 04-0.13218E 05 0.12797E 05
 -0.53018E 03 0.12621E 05-0.84828E 05 0.23638E 06-0.23259E 06
 0.15014E 04-0.35171E 05 0.23770E 06-0.66469E 06 0.65554E 06
 -0.11035E 04 0.25690E 05-0.17397E 06 0.48711E 06-0.48081E 06
 0.35220E-01-0.61160E 00 0.35831E 01-0.90466E 01 0.82902E 01
 -0.17108E 01 0.44068E 02-0.28534E 03 0.77587E 03-0.75090E 03
 0.31416E 02-0.74161E 03 0.49828E 04-0.13882E 05 0.13657E 05
 -0.88892E 02 0.20667E 04-0.13964E 05 0.39040E 05-0.38498E 05
 0.65308E 02-0.15096E 04 0.10220E 05-0.2 611E 05 0.28238E 05

-0.12341E 02 0.18884E 03-0.11728E 04 0.30961E 04-0.29343E 04
 0.71035E 03-0.16542E 05 0.11085E 06-0.30827E 06 0.30292E 06
 -0.13127E 05 0.29373E 06-0.20115E 07 0.56711E 07-0.56229E 07
 0.37071E 05-0.82346E 06 0.56564E 07-0.15977E 08 0.15861E 08
 -0.27183E 05 0.60211E 06-0.41404E 07 0.11703E 08-0.11622E 08
 0.12900E 02-0.20912E 03 0.13014E 04-0.34410E 04 0.32648E 04
 -0.80316E 03 0.18440E 05-0.12369E 06 0.34421E 06-0.33839E 06
 0.14807E 05-0.32780E 06 0.22460E 07-0.63344E 07 0.62819E 07
 -0.41782E 05 0.91896E 06-0.63153E 07 0.17844E 08-0.17717E 08
 0.30626E 05-0.67190E 06 0.46223E 07-0.13068E 08 0.12981E 08
 -0.48185E 01 0.81046E 02-0.50486E 03 0.13359E 04-0.12681E 04
 0.31494E 03-0.71670E 04 0.48098E 05-0.13389E 06 0.13165E 06
 -0.57901E 04 0.12736E 06-0.87285E 06 0.24620E 07-0.24419E 07
 0.16325E 05-0.35695E 06 0.24535E 07-0.69331E 07 0.68843E 07
 -0.11962E 05 0.26094E 06-0.17954E 07 0.50767E 07-0.50430E 07
 0.77154E 00-0.13298E 02 0.82858E 02-0.21928E 03 0.20818E 03
 -0.52034E 02 0.11764E 04-0.78957E 04 0.21981E 05-0.21614E 05
 0.95326E 03-0.20874E 05 0.14306E 06-0.40354E 06 0.40023E 06
 -0.26854E 04 0.58476E 05-0.40194E 06 0.11358E 07-0.11278E 07
 0.19668E 04-0.42736E 05 0.29406E 06-0.83147E 06 0.82594E 06
 -0.44949E-01 0.78778E 00-0.49075E 01 0.12986E 02-0.12328E 02
 0.30957E 01-0.69623E 02 0.46723E 03-0.13007E 04 0.12789E 04
 -0.56480E 02 0.12326E 04-0.84468E 04 0.23825E 05-0.23629E 05
 0.15896E 03-0.345.9E 04 0.23718E 05-0.67018E 05 0.66544E 05
 -0.11637E 03 0.25212E 04-0.17346E 05 0.49045E 05-0.48717E 05
 0.49939E 01-0.78617E 02 0.49245E 03-0.13082E 04 0.12454E 04
 -0.31832E 03 0.70808E 04-0.47645E 05 0.13285E 06-0.13077E 06
 0.58380E 04-0.12714E 06 0.87266E 06-0.24638E 07 0.24450E 07
 -0.16471E 05 0.35718E 06-0.24584E 07 0.69526E 07-0.69072E 07
 0.12075E 05-0.26140E 06 0.18009E 07-0.50962E 07 0.50647E 07
 -0.52933E 01 0.87064E 02-0.54639E 03 0.14535E 04-0.13850E 04
 0.35730E 03-0.78879E 04 0.53123E 05-0.1821E 06 0.14595E 06
 -0.65538E 04 0.14182E 06-0.97386E 06 0.27503E 07-0.27299E 07
 0.18485E 05-0.39845E 06 0.27436E 07-0.77610E 07 0.77115E 07
 -0.13549E 05 0.29160E 06-0.20098E 07 0.56884E 07-0.56542E 07
 0.19925E 01-0.33713E 02 0.21174E 03-0.56357E 03 0.53726E 03
 -0.13936E 03 0.30616E 04-0.20626E 05 0.57561E 05-0.56690E 05
 0.25539E 04-0.55049E 05 0.37809E 06-0.10679E 07 0.10600E 07
 -0.72007E 04 0.15465E 06-0.10650E 07 0.30129E 07-0.29939E 07
 0.52767E 04-0.11317E 06 0.78007E 06-0.22081E 07 0.21950E 07
 -0.32033E 00 0.55231E 01-0.34689E 02 0.92331E 02-0.88021E 02
 0.22915E 02-0.50151E 03 0.33788E 04-0.94290E 04 0.92864E 04
 -0.41919E 03 0.90103E 04-0.61884E 05 0.17479E 06-0.17350E 06
 0.11813E 04-0.25305E 05 0.17426E 06-0.49300E 06 0.48989E 06
 -0.86546E 03 0.18515E 05-0.12762E 06 0.36125E 06-0.35910E 06
 0.18694E-01-0.32649E 00 0.20497E 01-0.54542E 01 0.51985E 01
 -0.13569E 01 0.29602E 02-0.19940E 03 0.55638E 03-0.54792E 03
 0.24763E 02-0.53111E 03 0.36473E 04-0.10301E 05 0.10224E 05
 -0.69744E 02 0.14911E 04-0.10267E 05 0.29044E 05-0.28860E 05
 0.51083E 02-0.10908E 04 0.75178E 04-0.21279E 05 0.21151E 05

-0.85282E 00 0.13508E 02-0.84066E 02 0.22228E 03-0.21089E 03
 0.54985E 02-0.11926E 04 0.80002E 04-0.22263E 05 0.21886E 05
 -0.99358E 03 0.21335E 05-0.14620E 06 0.41237E 06-0.40897E 06
 0.27983E 04-0.59932E 05 0.41194E 06-0.11640E 07 0.11558E 07
 -0.20503E 04 0.43866E 05-0.30183E 06 0.85342E 06-0.84772E 06
 0.91006E 00-0.14941E 02 0.93159E 02-0.24666E 03 0.23426E 03
 -0.61466E 02 0.13271E 04-0.89107E 04 0.24812E 05-0.24401E 05
 0.11126E 04-0.23782E 05 0.16306E 06-0.46004E 06 0.45634E 06
 -0.31334E 04 0.66820E 05-0.45948E 06 0.12987E 07-0.12897E 07
 0.22958E 04-0.48911E 05 0.33667E 06-0.95217E 06 0.94597E 06
 -0.34384E 00 0.57778E 01-0.36053E 02 0.95509E 02-0.90742E 02
 0.23899E 02-0.51443E 03 0.34552E 04-0.96234E 04 0.94655E 04
 -0.43271E 03 0.92238E 04-0.63253E 05 0.1 848E 06-0.17706E 06
 0.12185E 04-0.25916E 05 0.17824E 06-0.50383E 06 0.50039E 06
 -0.89272E 03 0.18970E 05-0.13060E 06 0.36939E 06-0.36700E 06
 0.55393E-01-0.94534E 00 0.58981E 01-0.15624E 02 0.14843E 02
 -0.39190E 01 0.84138E 02-0.56510E 03 0.15739E 04-0.15480E 04
 0.70901E 02-0.15082E 04 0.10342E 05-0.29183E 05 0.28950E 05
 -0.19961E 03 0.42372E 04-0.29140E 05 0.82371E 05-0.81807E 05
 0.14622E 03-0.31013E 04 0.21350E 05-0.60387E 05 0.59997E 05
 -0.32358E-02 0.55801E-01-0.34795E 00 0.92132E 00-0.87503E 00
 0.23144E 00-0.49572E 01 0.33285E 02-0.92685E 02 0.91152E 02
 -0.41812E 01 0.88794E 02-0.60880E 03 0.17177E 04-0.17038E 04
 0.11768E 02-0.24941E 03 0.17151E 04-0.48475E 04 0.48141E 04
 -0.86190E 01 0.18253E 03-0.12564E 04 0.35535E 04-0.35303E 04
 0.53532E-01-0.84411E 00 0.51826E 01-0.13567E 02 0.12779E 02
 -0.33656E 01 0.71367E 02-0.47545E 03 0.13173E 04-0.12911E 04
 0.59460E 02-0.12613E 04 0.86115E 04-0.24233E 05 0.23997E 05
 -0.16695E 03 0.35379E 04-0.24240E 05 0.68359E 05-0.67788E 05
 0.12221E 03-0.25884E 04 0.17756E 05-0.50113E 05 0.49718E 05
 -0.57383E-01 0.93248E 00-0.57362E 01 0.15038E 02-0.14179E 02
 0.37518E 01-0.79340E 02 0.52911E 03-0.14669E 04 0.14384E 04
 -0.66464E 02 0.14052E 04-0.95992E 04 0.27022E 05-0.26765E 05
 0.18666E 03-0.39426E 04 0.27026E 05-0.76240E 05 0.75618E 05
 -0.13664E 03 0.28848E 04-0.19799E 05 0.55893E 05-0.55463E 05
 0.21740E-01-0.36026E 00 0.22177E 01-0.58172E 01 0.54871E 01
 -0.14559E 01 0.30727E 02-0.20500E 03 0.56848E 03-0.55754E 03
 0.25818E 02-0.54469E 03 0.37218E 04-0.10478E 05 0.10380E 05
 -0.72513E 02 0.15285E 04-0.10479E 05 0.29566E 05-0.29327E 05
 0.53082E 02-0.11184E 04 0.76772E 04-0.21676E 05 0.21510E 05
 -0.35091E-02 0.58907E-01-0.36256E 00 0.95089E 00-0.89685E 00
 0.23838E 00-0.5026E 01 0.33498E 02-0.92890E 02 0.91099E 02
 -0.42265E 01 0.89018E 02-0.60822E 03 0.1 124E 04-0.16962E 04
 0.11869E 02-0.24979E 03 0.17125E 04-0.48315E 04 0.47924E 04
 -0.86882E 01 0.18278E 03-0.12546E 04 0.35421E 04-0.35150E 04
 0.20526E-03-0.34755E-02 0.21376E-01-0.56033E-01 0.52828E-01
 -0.14060E-01 0.29560E 00-0.19712E 01 0.54649E 01-0.53586E 01
 0.24904E 00-0.52377E 01 0.35780E 02-0.10072E 03 0.99764E 02
 -0.69924E 00 0.14696E 02-0.10074E 03 0.28418E 03-0.28186E 03
 0.51180E 00-0.10753E 02 0.73797E 02-0.20833E 03 0.20673E 03

F. FOR SECTOR 6

0.42666E 01-0.45522E 02 0.30334E 03-0.84020E 03 0.82315E 03
 -0.30169E 03 0.48832E 04-0.33666E 05 0.95294E 05-0.94714E 05
 0.47951E 04-0.90773E 05 0.63072E 06-0.17939E 07 0.17886E 07
 -0.13191E 05 0.25575E 06-0.17789E 07 0.50626E 07-0.50496E 07
 .95714E 04-0.18718E 06 0.13024E 07-0.37073E 07 0.36981E 07
 -0.43034E 01 0.50570E 02-0.33781E 03 0.93721E 03-0.91918E 03
 0.32651E 03-0.54616E 04 0.37686E 05-0.10673E 06 0.10612E 06
 -0.53098E 04 0.10151E 06-0.70559E 06 0.20073E 07-0.20018E 07
 0.14661E 05-0.28590E 06 0.19893E 07-0.56626E 07 0.56489E 07
 -0.10651E 05 0.20920E 06-0.14561E 07 0.41456E 07-0.41359E 07
 0.15778E 01-0.19449E 02 0.13046E 03-0.36209E 03 0.35654E 03
 - 0.12425E 03 0.21236E 04-0.14674E 05 0.41592E 05-0.41376E 05
 .20501E 04-0.39465E 05 0.27452E 06-0.78130E 06 0.77932E 06
 -0.56718E 04 0.11111E 06-0.77356E 06 0.22028E 07-0.21979E 07
 0.41232E 04-0.81283E 05 0.56605E 06-0.16121E 07 0.16087E 07
 - 0.24997E 00 0.31813E 01-0.21388E 02 0.59582E 02-0.58597E 02
 0.20139E 02-0.34936E 03 0.24158E 04-0.68507E 04 0.68172E 04
 -0.33496E 03 0.64794E 04-0.45086E 05 0.12835E 06-0.12804E 06
 0.92751E 03-0.18229E 05 0.12695E 06-0.36156E 06 0.36080E 06
 -0.67439E 03 0.13330E 05-0.92852E 05 0.26449E 06-0.26395E 06
 0.14483E-01-0.18876E 00 0.12702E 01-0.35406E 01 0.34834E 01
 -0.11842E 01 0.20766E 02-0.14363E 03 0.40738E 03-0.40544E 03
 0.19768E 02-0.38370E 03 0.26702E 04-0.76019E 04 0.75841E 04
 -0.54745E 02 0.10784E 04-0.75109E 04 0.21393E 05-0.21349E 05
 0.39802E 02-0.78818E 03 0.54909E 04-0.15642E 05 0.15611E 05
 -0.75502E 01 0.11839E 03-0.82904E 03 0.23686E 04-0.23681E 04
 0.81296E 03-0.14543E 05 0.10180E 06-0.29081E 06 0.29077E 06
 - 0.14506E 05 0.28 36E 06-0.19624E 07 0.56065E 07-0.56060E 07
 0.40681E 05-0.79484E 06 0.55636E 07-0.15894E 08 0.15892E 08
 - 0.29739E 05 0.58329E 06-0.40827E 07 0.11663E 08-0.11661E 08
 0.81782E 01-0.13032E 03 0.91683E 03-0.26268E 04 0.26309E 04
 -0.88113E 03 0.16201E 05-0.11355E 06 0.32463E 06-0.32474E 06
 0.15949E 05-0.31281E 06 0.21909E 07-0.62613E 07 0.62622E 07
 -0.44817E 05 0.88690E 06-0.62111E 07 0.17750E 08-0.17751E 08
 0.32785E 05-0.65084E 06 0.45576E 07-0.13024E 08 0.13024E 08
 -0.31169E 01 0.50295E 02-0.35474E 03 0.10178E 04-0.10204E 04
 .33668E 03-0.62917E 04 0.44126E 05-0.12621E 06 0.12628E 06
 -0.61413E 04 0.12148E 06-0.85112E 06 0.24329E 07-0.24335E 07
 0.17274E 05-0.34438E 06 0.24124E 07-0.68951E 07 0.68964E 07
 -0.12641E 05 0.25269E 06-0.17700E 07 0.50586E 07-0.50592E 07
 0.50403E 00-0.82145E 01 0.58024E 02-0.16664E 03 0.16715E 03
 - 0.54604E 02 0.10312E 04-0.72354E 04 0.20699E 05-0.20715E 05
 0.10003E 04-0.19895E 05 0.13941E 06-0.39854E 06 0.39867E 06
 -0.28148E 04 0.56379E 05-0.39500E 06 0.11291E 07-0.11294E 07
 0.20599E 04-0.41361E 05 0.28975E 06-0.82820E 06 0.82834E 06
 -0.29466E-01 0.48418E 00-0.34235E 01 0.98377E 01-0.98719E 01
 0.32019E 01-0.60919E 02 0.42753E 03-0.12233E 04 0.12243E 04
 -0.58779E 02 0.11735E 04-0.82239E 04 0.23512E 05-0.23521E 05
 0.16542E 03-0.33241E 04 0.23292E 05-0.66583E 05 0.66602E 05
 -0.12106E 03 0.24381E 04-0.17082E 05 0.48826E 05-0.48838E 05

.23972E 01-0.33520E 02 0.23750E 03-0.68303E 03 0.68562E 03
 -0.27672E 03 0.42492E 04-0.29831E 05 0.85361E 05-0.85431E 05
 0.47498E 04-0.84118E 05 0.58957E 06-0.16856E 07 0.16861E 07
 -0.13283E 05 0.24020E 06-0.16132E 07 0.48115E 07-0.48127E 07
 0.97122E 04-0.17697E 06 0.12399E 07-0.35443E 07 0.35450E 07
 -0.25584E 01 0.35261E 02-0.25377E 03 0.73648E 03-0.74348E 03
 0.28850E 03-0.46520E 04 0.32786E 05-0.94035E 05 0.94252E 05
 -0.50907E 04 0.93015E 05-0.65307E 06 0.18691E 07-0.18710E 07
 0.14302E 05-0.26603E 06 0.18669E 07-0.53416E 07 0.53459E 07
 -0.10477E 05 0.19613E 06-0.13761E 07 0.39367E 07-0.39396E 07
 0.95983E 00-0.13130E 02 0.95406E 02-0.21840E 03 0.28199E 03
 -0.10700E 03 0.17754E 04-0.12541E 05 0.36017E 05-0.36131E 05
 0.19235E 04-0.35783E 05 0.25149E 06-0.72018E 06 0.72118E 06
 -0.54218E 04 0.10249E 06-0.71985E 06 0.20606E 07-0.20630E 07
 0.39768E 04-0.75608E 05 0.53091E 06-0.1 195E 07 0.15211E 07
 -0.15242E 00 0.20741E 01-0.15171E 02 0.44433E 02-0.45109E 02
 0.16896E 02-0.28539E 03 0.20189E 04-0.58034E 04 0.58250E 04
 -0.30811E 03 0.57963E 04-0.40763E 05 0.11678E 06-0.11697E 06
 0.87077E 03-0.16627E 05 0.11684E 06-0.33457E 06 0.33502E 06
 -0.63940E 03 0.12274E 05-0.86230E 05 0.24688E 06-0.24717E 06
 0.87200E-02-0.11802E 00 0.86788E 00-0.25494E 01 0.25928E 01
 -0.96456E 00 0.16476E 02-0.11669E 03 0.33567E 03-0.33706E 03
 0.17807E 02-0.33746E 03 0.23743E 04-0.68039E 04 0.68162E 04
 -0.50443E 02 0.96955E 03-0.68160E 04 0.19522E 05-0.19551E 05
 0.37078E 02-0.71627E 03 0.50338E 04-0.14415E 05 0.14435E 05
 -0.17580E 00 0.45791E-01-0.19867E 01 0.83975E 01-0.10050E 02
 0.24947E 02-0.79059E 02 0.60623E 03-0.18167E 04 0.18671E 04
 -0.31995E 03 0.22816E 04-0.16437E 05 0.47702E 05-0.48138E 05
 0.85725E 03-0.70286E 04 0.50319E 05-0.14554E 06 0.14658E 06
 -0.61975E 03 0.53774E 04-0.38412E 05 0.1 1097E 06-0.11169E 06
 0.15528E 00 0.80640E 00-0.22885E 01 0.93795E 00 0.25423E 01
 -0.21433E 02 0.51882E 02-0.47211E 03 0.15292E 04-0.16404E 04
 0.28930E 03-0.21901E 04 0.16303E 05-0.48183E 05 0.49168E 05
 -0.78808E 03 0.69973E 04-0.51323E 05 0.15050E 06-0.15287E 06
 0.57442E 03-0.54304E 04 0.39626E 05-0.11588E 06 0.11751E 06
 -0.49610E-01-0.53208E 00 0.20995E 01-0.32724E 01 0.15693E 01
 0.67294E 01-0.84826E 01 0.11244E 03-0.40975E 03 0.46472E 03
 -0.95365E 02 0.72851E 03-0.55744E 04 0.16717E 05-0.17207E 05
 0.26415E 03-0.24283E 04 0.18143E 05-0.53741E 05 0.54921E 05
 -0.19416E 03 0.19159E 04-0.14200E 05 0.41885E 05-0.42699E 05
 0.66742E-02 0.11554E 00-0.51009E 00 0.95517E 00-0.64067E 00
 -0.90422E 00-0.49 33E 00-0.63445E 01 0.34490E 02-0.44688E 02
 0.13480E 02-0.98649E 02 0.77815E 03-0.23696E 04 0.24607E 04
 -0.38017E 02 0.34844E 03-0.26504E 04 0.79253E 04-0.81449E 04
 0.28204E 02-0.28089E 03 0.21119E 04-0.62771E 04 0.64286E 04
 -0.31147E-03-0.83633E-02 0.39598E-01-0.81241E-01 0.61240E-01
 0.43186E-01 0.14943E 00-0.42512E 00 0.17338E 00 0.47693E 00
 -0.68358E 00 0.44511E 01-0.36725E 02 0.11425E 03-0.12006E 03
 0.19689E 01-0.17249E 02 0.13417E 03-0.40583E 03 0.41985E 03
 -0.14765E 01 0.14344E 02-0.10966E 03 0.32883E 03-0.33850E 03

-0.22702E-01 0.88930E 00-0.59136E 01 0.16382E 02-0.16066E 02
 0.16957E 01-0.95868E 02 0.66109E 03-0.18726E 04 0.18627E 04
 -0.55054E 02 0.17501E 04-0.12162E 05 0.34605E 05-0.34519E 05
 0.16350E 03-0.48958E 04 0.34057E 05-0.96960E 05 0.96750E 05
 -0.12157E 03 0.35685E 04-0.24832E 05 0.70707E 05-0.70559E 05
 0.32986E-01-0.11436E 01 0.73843E 01-0.20057E 02 0.19406E 02
 -0.28281E 01 0.11305E 03-0.77108E 03 0.21693E 04-0.21483E 04
 0.71324E 02-0.20120E 04 0.13903E 05-0.39420E 05 0.39233E 05
 -0.20708E 03 0.56046E 04-0.38795E 05 0.11011E 06-0.10966E 06
 0.15279E 03-0.40780E 04 0.28244E 05-0.80191E 05 0.79875E 05
 -0.14575E-01 0.48020E 00-0.30623E 01 0.82456E 01-0.79295E 01
 0.13239E 01-0.45627E 02 0.30958E 03-0.86808E 03 0.85781E 03
 -0.30075E 02 0.79865E 03-0.55026E 04 0.15575E 05-0.15483E 05
 0.86272E 02-0.22172E 04 0.15308E 05-0.43382E 05 0.43159E 05
 -0.63373E 02 0.16108E 04-0.11129E 05 0.31550E 05-0.31395E 05
 0.26014E-02-0.82980E-01 0.52302E 00-0.14104E 01 0.13523E 01
 -0.24375E 00 0.77235E 01-0.52264E 02 0.14630E 03-0.14440E 03
 0.52085E 01-0.13338E 03 0.91748E 03-0.25942E 04 0.25772E 04
 -0.14818E 02 0.36912E 03-0.25448E 04 0.72054E 04-0.71642E 04
 0.10849E 02-0.26776E 03 0.18474E 04-0.52328E 04 0.52042E 04
 -0.16474E-03 0.51152E-02-0.32334E-01 0.86519E-01-0.82830E-01
 0.15708E-01-0.47068E 00 0.31807E 01-0.88954E 01 0.87749E 01
 -0.32123E 00 0.80262E 01-0.55159E 02 0.15587E 03-0.15479E 03
 0.90788E 00-0.22145E 02 0.15254E 03-0.43167E 03 0.42905E 03
 -0.66294E 00 0.16040E 02-0.11057E 03 0.31304E 03-0.31122E 03
 0.28633E-02-0.78921E-01 0.53138E 00-0.14833E 01 0.14616E 01
 -0.27052E 00 0.87993E 01-0.60915E 02 0.17293E 03-0.17224E 03
 0.63956E 01-0.16468E 03 0.11467E 04-0.32663E 04 0.32602E 04
 -0.18550E 02 0.46398E 03-0.32332E 04 0.92138E 04-0.91991E 04
 0.13711E 02-0.33953E 03 0.23666E 04-0.67449E 04 0.67345E 04
 -0.37660E-02 0.98358E-01-0.64581E 00 0.17733E 01-0.17282E 01
 0.35539E 00-0.10210E 02 0.70074E 02-0.19787E 03 0.19640E 03
 -0.76959E 01 0.18752E 03-0.13001E 04 0.36936E 04-0.36805E 04
 0.22091E 02-0.52679E 03 0.36573E 04-0.10399E 05 0.10367E 05
 -0.16268E 02 0.38504E 03-0.26744E 04 0.76059E 04-0.75837E 04
 0.15835E-02-0.40504E-01 0.26295E 00-0.71655E 00 0.69469E 00
 -0.15043E 00 0.40643E 01-0.27774E 02 0.7215E 02-0.77501E 02
 0.31173E 01-0.73779E 02 0.51038E 03-0.14480E 04 0.14416E 04
 -0.88950E 01 0.20682E 03-0.14331E 04 0.40699E 04-0.40543E 04
 0.65358E 01-0.15103E 03 0.10471E 04-0.29746E 04 0.29637E 04
 -0.27271E-03 0.68924E-02-0.44478E-01 0.12070E 00-0.11669E 00
 0.26056E-01-0.67856E 00 0.46259E 01-0.13008E 02 0.12876E 02
 -0.52501E 00 0.12208E 02-0.84338E 02 0.23909E 03-0.23791E 03
 0.14918E 01-0.34157E 02 0.23641E 03-0.67090E 03 0.66804E 03
 -0.10943E 01 0.24921E 02-0.17259E 03 0.48996E 03-0.48797E 03
 0.16732E-04-0.41885E-03 0.26933E-02-0.72914E-02 0.70367E-02
 -0.16039E-02 0.40744E-01-0.27735E 00 0.77916E 00-0.77081E 00
 0.31643E-01-0.72703E 00 0.50186E 01-0.14220E 02 0.14144E 02
 -0.89609E-01 0.20306E 01-0.14044E 02 0.39836E 02-0.39654E 02
 0.65639E-01-0.14803E 01 0.10244E 02-0.29069E 02 0.28943E 02

G.FOR SECTOR 7

0.57739E 01-0.84019E 02 0.56859E 03-0.15911E 04 0.15697E 04
 -0.49143E 03 0.94355E 04-0.65401E 05 0.18576E 06-0.18505E 06
 0.86949E 04-0.17809E 06 0.12408E 07-0.35353E 07 0.35289E 07
 -0.24355E 05 0.50344E 06-0.35100E 07 0.10004E 08-0.99889E 07
 0.17800E 05-0.36916E 06 0.25743E 07-0.73385E 07 0.73276E 07
 -0.60023E 01 0.94335E 02-0.63811E 03 0.17851E 04-0.17608E 04
 0.54581E 03-0.10578E 05 0.73309E 05-0.20820E 06 0.20739E 06
 -0.97482E 04 0.19934E 06-0.13887E 07 0.39565E 07-0.39493E 07
 0.27339E 05-0.56327E 06 0.39269E 07-0.11192E 08 0.11175E 08
 -0.19989E 05 0.41295E 06-0.28795E 07 0.82082E 07-0.81958E 07
 0.22434E 01-0.36625E 02 0.24806E 03-0.69452E 03 0.68543E 03
 -0.21109E 03 0.41194E 04-0.28560E 05 0.81130E 05-0.80830E 05
 0.37921E 04-0.77539E 05 0.54029E 06-0.15395E 07 0.15368E 07
 -0.10641E 05 0.21901E 06-0.15271E 07 0.43528E 07-0.43463E 07
 0.77816E 04-0.16053E 06 0.11195E 07-0.31916E 07 0.31869E 07
 -0.36002E 00 0.60161E 01-0.40771E 02 0.11419E 03-0.11272E 03
 0.34545E 02-0.67731E 03 0.46967E 04-0.13343E 05 0.13295E 05
 -0.62207E 03 0.12722E 05-0.88651E 05 0.25260E 06-0.25217E 06
 0.17458E 04-0.35913E 05 0.25042E 06-0.71382E 06 0.71276E 06
 -0.12765E 04 0.26315E 05-0.18353E 06 0.52323E 06-0.52248E 06
 0.21039E-01-0.35709E 00 0.24198E 01-0.67772E 01 0.66900E 01
 -0.20422E 01 0.40169E 02-0.27854E 03 0.79130E 03-0.78842E 03
 0.36774E 02-0.75215E 03 0.52412E 04-0.14934E 05 0.14908E 05
 -0.10318E 03 0.21218E 04-0.14795E 05 0.42172E 05-0.42108E 05
 0.75428E 02-0.15542E 04 0.10839E 05-0.30901E 05 0.30856E 05
 -0.83812E 01 0.13868E 03-0.96028E 03 0.27256E 04-0.27140E 04
 0.85054E 03-0.16547E 05 0.11549E 06-0.32938E 06 0.32901E 06
 -0.15666E 05 0.31625E 06-0.22107E 07 0.63109E 07-0.63075E 07
 0.44116E 05-0.89490E 06 0.62568E 07-0.17863E 08 0.17855E 08
 -0.32290E 05 0.65610E 06-0.4574E 07 0.13097E 08-0.13090E 08
 0.90483E 01-0.15484E 03 0.10734E 04-0.30486E 04 0.30369E 04
 -0.93906E 03 0.18523E 05-0.12931E 06 0.3888E 06-0.36850E 06
 0.17409E 05-0.35371E 06 0.24729E 07-0.70601E 07 0.70567E 07
 -0.49057E 05 0.1006E 07-0.69966E 07 0.19977E 08-0.19968E 08
 0.35912E 05-0.73346E 06 0.51288E 07-0.14644E 08 0.14637E 08
 -0.34481E 01 0.60303E 02-0.41825E 03 0.11883E 04-0.11840E 04
 0.36311E 03-0.72207E 04 0.50418E 05-0.14383E 06 0.14370E 06
 -0.67493E 04 0.13765E 06-0.96243E 06 0.27478E 07-0.27466E 07
 0.19020E 05-0.38919E 06 0.27216E 07-0.71710E 07 0.77677E 07
 -0.13923E 05 0.28521E 06-0.19945E 07 0.51949E 07-0.56923E 07
 0.55891E 00-0.99218E 01 0.68830E 02-0.19558E 03 0.19489E 03
 -0.59429E 02 0.11879E 04-0.82952E 04 0.23666E 05-0.23643E 05
 0.11050E 04-0.22590E 05 0.15795E 06-0.45097E 06 0.45077E 06
 -0.31130E 04 0.63829E 05-0.44635E 06 0.12745E 07-0.12740E 07
 0.22782E 04-0.46758E 05 0.32699E 06-0.93368E 06 0.93325E 06
 -0.32811E-01 0.58884E 00-0.40852E 01 0.11608E 02-0.11568E 02
 0.35122E 01-0.70459E 02 0.49201E 03-0.14037E 04 0.14024E 04
 -0.65225E 02 0.13356E 04-0.93387E 04 0.26663E 05-0.26651E 05
 0.18366E 03-0.37709E 04 0.26370E 05-0.75296E 05 0.75265E 05
 -0.13437E 03 0.27613E 04-0.19311E 05 0.55139E 05-0.55114E 05

0.38201E 01-0.61403E 02 0.42094E 03-0.11874E 04 0.11777E 04
 -0.37731E 03 0.71450E 04 0.49724E 05 0.14157E 06-0.14126E 06
 0.69281E 04-0.13717E 06 0.95761E 06-0.27316E 07 0.27287E 07
 -0.19532E 05 0.38901E 06 0.27168E 07 0.77513E 07-0.77442E 07
 0.14311E 05-0.28560E 06 0.19948E 07-0.56917E 07 0.56865E 07
 -0.41216E 01 0.68048E 02-0.46742E 03 0.13202E 04-0.13103E 04
 0.41206E 03-0.79597E 04 0.55426E 05-0.15786E 06 0.15754E 06
 -0.76384E 04 0.15300E 06-0.10684E 07 0.30480E 07-0.30451E 07
 0.21562E 05-0.43394E 06 0.30312E 07-0.86496E 07 0.86424E 07
 -0.15805E 05 0.31859E 06-0.22257E 07 0.63514E 07-0.63461E 07
 0.15645E 01-0.26305E 02 0.18086E 03-0.51111E 03 0.50749E 03
 -0.15789E 03 0.30846E 04-0.21485E 05 0.61201E 05-0.61084E 05
 0.29428E 04-0.59328E 05 0.41434E 06-0.11822E 07 0.11811E 07
 -0.83130E 04 0.16828E 06-0.11756E 07 0.33548E 07-0.33522E 07
 0.60948E 04-0.12355E 06 0.86319E 06-0.24634E 07 0.246145 07
 -0.252218E 00 0.42938E 01-0.29531E 02 0.83467E 02-0.82884E 02
 0.25612E 02-0.50383E 03 0.35096E 04-0.99978E 04 0.99790E 04
 -0.47892E 03 0.96935E 04-0.67700E 05 0.19316E 06-0.19299E 06
 0.13534E 04-0.27494E 05 0.19208E 06-0.54815E 06 0.54773E 06
 -0.99239E 03 0.20185E 05-0.14103E 06 0.40249E 06-0.40217E 06
 0.14696E-01-0.25250E 00 0.17365E 01-0.49078E 01 0.48734E 01
 -0.14990E 01 0.29622E 02-0.20634E 03 0.58779E 03-0.58668E 03
 0.28089E 02-0.57000E 03 0.39809E 04-0.11358E 05 0.11348E 05
 -0.79397E 02 0.16166E 04-0.11294E 05 0.32231E 05-0.32206E 05
 0.582225 02-0.11868E 04 0.82924E 04-0.23665F 05 0.23647E 05
 -0.82290E 00 0.12450E 02-0.84269E 02 0.23581E 03-0.23263E 03
 0.76906E 02-0.13998E 04 0.97038E 04-0.27564E 05 0.27461E 05
 0.13899E 04 0.26870E 05-0.18724E 06 0.53353E 06-0.53261E 06
 0.39153E 04-0.76309E 05 0.53212E 06-0.15168E 07 0.15146E 07
 -0.28695E 04 0.56085E 05-0.39118E 06 0.11152E 07-0.11136E 07
 0.87782E 00-0.13645E 02 0.92728E 02-0.26014E 03 0.25706E 03
 -0.82868E 02 0.15511E 04-0.10766E 05 0.30605E 05-0.30506E 05
 0.15190E 04-0.29883E 05 0.20837E 06-0.59393E 06 0.59304E 06
 -0.42882E 04 0.84920E 05-0.59246E 06 0.16893E 07-0.16872E 07
 0.31453E 04-0.62430E 05 0.43563E 06-0.12423E 07 0.12407E 07
 -0.33042E 00 0.52295E 01-0.35610E 02 0.10003E 03-0.98923E 02
 0.31441E 02-0.59786E 03 0.41524E 04-0.11808E 05 0.11773E 05
 -0.58155E 03 0.11552E 05-0.80575E 05 0.22972E 06-0.22940E 06
 0.16441E 04-0.32847E 05 0.22922E 06-0.65371E 06 0.65293E 06
 -0.12066E 04 0.24154E 05-0.16859E 06 0.48083E 06-0.48028E 06
 0.52906E-01-0.84751E 00 0.57747E 01-0.16227E 02 0.16052E 02
 -0.50578E 01 0.97085E 02-0.67443E 03 0.19181E 04-0.19125E 04
 0.94141E 02-0.18810E 04 0.13121E 05-0.37409E 05 0.37359E 05
 -0.26643E 03 0.53513E 04-0.37347E 05 0.10651E 06-0.10639E 06
 0.19562E 03-0.39361E 04 0.27475E 05-0.78365E 05 0.178277E 05
 -0.30636E-02 0.49477E-01-0.33710E 00 0.94718E 00-0.93691E 00
 0.29360E 00-0.56691E 01 0.39381E 02-0.11200E 03 0.11167E 03
 -0.54928E 01 0.11015E 03-0.76836E 03 0.21907E 04-0.21877E 04
 0.15560E 02-0.31356E 03 0.21884E 04-0.62413E 04 0.62340E 04
 -0.11429E 02 0.23070E 03-0.16104E 04 0.45932E 04-0.45880E 04

0.90307E-01-0.12598E 01 0.83278E 01-0.22950E 02 0.22410E 02
 -0.76988E 01 0.13251E 03-0.91145E 03 0.25766E 04-0.25590E 04
 .13477E 03-0.25211E 04 0.17503E 05-0.49762E 05 0.49605E 05
 -0.37834E 03 0.71605E 04-0.49774E 05 0.14162E 06-0.14124E 06
 0.27707E 03-0.52657E 04 0.36619E 05-0.10421E 06 0.10395E 06
 -0.94660E-01 0.13578E 01-0.90406E 01 0.25031E 02-0.24519E 02
 0.81561E 01-0.14578E 03 0.10052E 04-0.24460E 04 0.28294E 04
 -0.14566E 03 0.27932E 04-0.19416E 05 0.55242E 05-0.55094E 05
 0.41025E 03-0.79433E 04 0.55273E 05-0.15736E 06 0.15700E 06
 - .30082E 03 0.58444E 04-0.40683E 05 0.11585E 06-0.11560E 06
 0.35234E-01-0.51459E 00 0.34390E 01-0.95445E 01 0.93641E 01
 -0.30587E 01 0.55845E 02-0.38557E 03 0.10925E 04-0.10866E 04
 0.55351E 02-0.10762E 04 0.74854E 04-0.21305E 05 0.21253E 05
 - .15625E 03 0.30639E 04-0.21332E 05 0.67750E 05-0.60624E 05
 0.11468E 03-0.22555E 04 0.15709E 05-0.44745E 05 0.44657E 05
 -0.56018E-02 0.82768E-01-0.55379E 00 0.15381E 01-0.15098E 01
 .48774E 00-0.90169E 01 0.62279E 02-0.17651E 03 0.17559E 03
 - .89097E 01 0.17465E 03-0.12150E 04 0.3587E 04-0.34505E 04
 0.25197E 02-0.49779E 03 0.34664E 04-0.98729E 04 0.98531E 04
 -0.18508E 02 0.36665E 03-0.25540E 04 0.72756E 04-0.72618E 04
 0.32267E-03-0.48014E-02 0.32120E-01-0.89198E-01 0.87544E-01
 -0.28092E-01 0.52325E 00-0.36139E 01 0.10242E 02-0.10188E 02
 0.51721E 00-0.10189E 02 0.70889E 02-0.20179E 03 0.20132E 03
 - .14650E 01 0.29077E 02-0.20248E 03 0.57672E 03-0.57557E 03
 0.10769E 01-0.21430E 02 0.14928E 03-0.42525E 03 0.42444E 03
 -0.41541E-02 0.53003E-01-0.33644E 00 0.90188E 00-0.86392E 00
 0.30972E 00-0.49393E 01 0.33436E 02-0.93586E 02 0.92348E 02
 - .51388E 01 0.91708E 02-0.63174E 03 0.17875E 04-0.17765E 04
 0.14326E 02-0.25998E 03 0.17952E 04-0.50871E 04 0.50603E 04
 -0.10470E 02 0.19116E 03-0.13211E 04 0.37455E 04-0.37270E 04
 0.42506E-02-0.55620E-01 0.35711E 00-0.96492E 00 0.92945E 00
 -0.32072E 00 0.53667E 01-0.36507E 02 0.10249E 03-0.10134E 03
 0.54672E 01-0.10095E 03 0.69714E 03-0.19756E 04 0.19653E 04
 -0.15314E 02 0.28683E 03-0.19848E 04 0.56318E 04-0.56069E 04
 0.11214E 02-0.21110E 03 0.14619E 04-0.41497E 04 0.41324E 04
 -0.15590E-02 0.20729E-01-0.13390E 00 0.36329E 00-0.35093E 00
 0.11846E 00-0.20373E 01 0.13893E 02-0.39064E 02 0.38663E 02
 -0.20564E 01 0.38702E 02-0.26761E 03 0.75897E 03-0.75539E 03
 0.57800E 01-0.11018E 03 0.76328E 03-0.21672E 04 0.21585E 04
 -0.42385E 01 0.81163E 02-0.56264E 03 0.15981E 04-0.15922E 04
 0.24580E-03-0.33009E-02 0.21364E-01-0.58039E-01 0.56114E-01
 -0.18688E-01 0.32654E 00-0.22285E 01 0.62692E 01-0.62068E 01
 0.32862E 00-0.62540E 01 0.43265E 02-0.12274E 03 0.12218E 03
 -0.92614E 00 0.17837E 02-0.12362E 03 0.35109E 03-0.34974E 03
 0.67995E 00-0.13151E 02 0.91205E 02-0.25912E 03 0.25819E 03
 - .14085E-04 0.19016E-03-0.12303E-02 0.33413E-02-0.32297E-02
 0.10670E-02-0.18812E-01 0.12837E 00-0.36110E 00 0.35748E 00
 -0.18961E-01 0.36327E 00-0.25132E 01 0.71299E 01-0.70977E 01
 .53564E-01-0.10381E 01 0.71948E 01-0.20434E 02 0.20356E 02
 - .39368E-01 0.76610E 00-0.53132E 01 0.15096E 02-0.15042E 02

H FOR SECTOR 8

0.63351E 01-0.10235E 03 0.68182E 03-0.1 208E 04 0.18908E 04
 -0.57018E 03 0.11346E 05-0.78499E 05 0.22271E 06-0.22172E 06
 0.10321E 05-0.21381E 06 0.14884E 07-0.42383E 07 0.42293E 07
 -0.29020E 05 0.60458E 06-0.42120E 07 0.12000E 08-0.11978E 08
 .21244E 05-0.44350E 06 0.30906E 07-0.8 066E 07 0.87914E 07
 -0.66456E 01 0.11434E 03-0.77003E 03 0.21482E 04-0.21152E 04
 0.63678E 03-0.12696E 05 0.87860E 05-0.24930E 06 0.24821E 06
 -0.11585E 05 0.23909E 06-0.16645E 07 0.47402E 07-0.47303E 07
 0.32594E 05-0.67591E 06 0.47094E 07-0.13418E 08 0.13394E 08
 -0.23866E 05 0.49576E 06-0.34551E 07 0.9 457E 07-0.98289E 07
 .24872E 01-0.44121E 02 0.29791E 03-0.83250E 03 0.82062E 03
 -0.24664E 03 0.49324E 04-0.34163E 05 0.96987E 05-0.96592E 05
 0.45058E 04-0.92886E 05 0.64692E 06-0.18427E 07 0.18392E 07
 -0.12682E 05 0.26255E 06-0.18299E 07 0.52147E 07-0.52060E 07
 0.92869E 04-0.19255E 06 0.13423E 07-0.38258E 07 0.38198E 07
 -0.39892E 00 0.72065E 01-0.48744E 02 0.13636E 03-0.13451E 03
 0.40363E 02-0.80906E 03 0.56067E 04-0.15923E 05 0.15861E 05
 -0.73868E 03 0.15220E 05-0.10603E 06 0.30207E 06-0.30152E 06
 0.20792E 04-0.43006E 05 0.29980E 06-0.85447E 06 0.85312E 06
 -0.15225E 04 0.31533E 05-0.21988E 06 0.62677E 06-0.62583E 06
 0.23289E-01-0.42564E 00 0.28814E 01-0.80652E 01 0.79587E 01
 -0.23843E 01 0.47870E 02-0.33182E 03 0.94250E 03-0.93896E 03
 0.43629E 02-0.89870E 03 0.62614E 04-0.17840E 05 0.17808E 05
 -0.12277E 03 0.25381E 04-0.17695E 05 0.50436E 05-0.50358E 05
 0.89886E 02-0.18605E 04 0.12975E 05-0.36986E 05 0.36932E 05
 -0.69566E 01 0.11528E 03-0.77704E 03 0.21691E 04-0.21366E 04
 .64601E 03-0.12813E 05 0.88696E 05-0.2 172E 06 0.25064E 06
 -0.11787E 05 0.24008E 06-0.16716E 07 0.47606E 07-0.47507E 07
 0.33118E 05-0.67686E 06 0.47163E 07-0.13437E 08 0.13413E 08
 -0.24208E 05 0.49534E 06-0.34522E 07 0.9 372E 07-0.98197E 07
 0.74139E 01-0.12774E 03 0.86403E 03-0.24172E 04 0.23844E 04
 -0.71739E 03 0.14327E 05-0.99284E 05 0.28196E 06-0.28087E 06
 0.13141E 05-0.26845E 06 0.18701E 07-0.53276E 07 0.53177E 07
 -0.36931E 05 0.75661E 06-0.52743E 07 0.15031E 08-0.15007E 08
 0.26994E 05-0.55358E 06 0.38598E 07-0.11001E 08 0.10983E 08
 -0.27828E 01 0.49216E 02-0.33425E 03 0.93747E 03-0.92633E 03
 0.27774E 03-0.55769E 04 0.38697E 05-0.10998E 06 0.10961E 06
 -0.51003E 04 0.10444E 06-0.72799E 06 0.20747E 07-0.20713E 07
 0.14332E 05-0.29421E 06 0.20519E 07-0.58498E 07 0.58413E 07
 -0.10474E 05 0.21519E 06-0.15011E 07 0.42797E 07-0.42736E 07
 .44635E 00-0.80392E 01 0.54763E 02-0.15389E 03 0.15225E 03
 -0.45522E 02 0.91763E 03-0.63731E 04 0.1 123E 05-0.18068E 05
 0.83606E 03-0.17150E 05 0.11959E 06-0.34092E 06 0.34042E 06
 -0.23481E 04 0.48273E 05-0.33681E 06 0.96040E 06-0.95915E 06
 0.17154E 04-0.35292E 05 0.24628E 06-0.70229E 06 0.70138E 06
 -0.26048E-01 0.47540E 00-0.32454E 01 0.91321E 01-0.90428E 01
 0.26970E 01-0.54521E 02 0.37891E 03-0.10779E 04 0.10749E 04
 -0.49444E 02 0.10155E 04-0.70836E 04 0.20196E 05-0.20169E 05
 0.13876E 03-0.28556E 04 0.19929E 05-0.56835E 05 0.56767E 05
 -0.10132E 03 0.20866E 04-0.14564E 05 0.41538E 05-0.41488E 05

0.33539E 01-0.52627E 02 0.34064E 03-0.92587E 03 0.89573E 03
 -0.27152E 03 0.52248E 04-0.35651E 05 0.10028E 06-0.99282E 05
 0.48215E 04-0.95948E 05 0.66331E 06-0.18809E 07 0.18719E 07
 -0.13507E 05 0.26994E 06-0.18694E 07 0.53066E 07-0.52845E 07
 0.98650E 04-0.19743E 06 0.13680E 07-0.38846E 07 0.3869E 07
 -0.35577E 01 0.57596E 02-0.37475E 03 0.10222E 04-0.99135E 03
 0.29834E 03-0.58053E 04 0.39692E 05-0.11179E 06 0.11077E 06
 -0.53326E 04 0.10691E 06-0.73987E 06 0.20993E 07-0.20900E 07
 .14948E 05-0.30084E 06 0.20852E 07-0.59223E 07 0Q58995E 07
 -0.10919E 05 0.22002E 06-0.15258E 07 0.43348E 07-0.43188E 07
 0.13182E 01-0.21851E 02 0.14306E 03-0.39186E 03 0.38113E 03
 -0.11423E 03 0.22417E 04-0.15363E 05 0.43332E 05-0.42975E 05
 0.20544E 04-0.41408E 05 0.28689E 06-0.81460E 06 0.81137E 06
 -0.57615E 04 0.11652E 06-0.80847E 06 0.22976E 07-0.22897E 07
 0.42087E 04-0.85212E 05 0.59150E 06-0.16814E 07 0.16758E 07
 -0.20874E 00 0.35208E 01-0.23160E 02 0.63636E 02-0.62024E 02
 0.18537E 02-0.36591E 03 0.25120E 04-0.70927E 04 0.70391E 04
 -0.33459E 03 0.67681E 04-0.46931E 05 0.13333E 06-0.13284E 06
 .93847E 03-0.19042E 05 0.13221E 06-0.37590E 06 0.37471E 06
 -0.68547E 03 0.13922E 05-0.96707E 05 0.27501E 06-0.27417E 06
 .12038E-01-0.20567E 00 0.13574E 01-0.37377E 01 0.36485E 01
 -0.10880E 01 0.21564E 02-0.14821E 03 0.41878E 03-0.41581E 03
 0.19668E 02-0.39880E 03 0.27669E 04-0.78632E 04 0.78363E 04
 -0.55153E 02 0.11215E 04-0.77909E 04 0.22157E 05-0.22091E 05
 0.40276E 02-0.81978E 03 0.56969E 04-0.16205E 05 0.16158E 05
 -0.86072E 00 0.12788E 02-0.79046E 02 0.20798E 03-0.19661E 03
 0.59595E 02-0.11038E 04 0.73783E 04-0.20487E 05 0.20109E 05
 -0.10110E 04 0.19602E 05-0.13407E 06 0.37771E 06-0.37429E 06
 0.28164E 04-0.54941E 05 0.37699E 06-0.10641E 07 0.10558E 07
 -0.20536E 04 0.40143E 05-0.27576E 06 0.77888E 06-0.77310E 06
 0.90182E 00-0.13768E 02 0.85709E 02-0.22668E 03 0.21510E 03
 -0.64623E 02 0.12157E 04-0.81554E 04 0.22696E 05-0.22311E 05
 0.11081E 04-0.21737E 05 0.14896E 06-0.42014E 06 0.41667E 06
 -0.30910E 04 0.60977E 05-0.41910E 06 0.11842E 07-0.11757E 07
 0.22548E 04-0.44565E 05 0.30660E 06-0.86683E 06 0.86094E 06
 -0.32824E 00 0.51201E 01-0.32149E 02 0.81557E 02-0.81552E 02
 0.24393E 02-0.46448E 03 0.31286E 04-0.87295E 04 0.85964E 04
 -0.42307E 03 0.83696E 04-0.57480E 05 0.16234E 06-0.16114E 06
 0.11819E 04-0.23500E 05 0.16182E 06-0.45776E 06 0.45483E 06
 -0.86254E 03 0.17179E 05-0.11140E 06 0.33511E 06-0.33307E 06
 0.51172E-01-0.81131E 00 0.51276E 01-0.13710E 02 0.13111E 02
 -0.39111E 01 0.75095E 02-0.50732E 03 0.14182E 04-0.13983E 04
 0.68393E 02-0.13606E 04 0.93590E 04-0.26458E 05 0.26278E 05
 -0.19125E 03 0.38225E 04-0.26357E 05 0.74621E 05-0.74184E 05
 0.13961E 03-0.27947E 04 0.19286E 05-0.54628E 05 0.54322E 05
 -0.29129E-02 0.46744E-01-0.29677E 00 0.79602E 00-0.76302E 00
 0.22717E 00-0.43864E 01 0.29693E 02-0.83111E 02 0.82014E 02
 -0.39943E 01 0.79762E 02-0.54920E 03 0.15536E 04-0.15437E 04
 0.11175E 02-0.22414E 03 0.15469E 04-0.43819E 04 0.43577E 04
 -0.81589E 01 0.16388E 03-0.11318E 04 0.32076E 04-0.31907E 04

0.11960E 00-0.17011E 01 0.10009E 02-0.25355E 02 0.23293E 02
 -0.70291E 01 0.12418E 03-0.80614E 03 0.21955E 04-0.21270E 04
 0.11136E 03-0.20904E 04 0.14063E 05-0.39208E 05 0.38590E 05
 -0.30717E 03 0.58175E 04-0.39345E 05 0.11006E 06-0.10856E 06
 0.22326E 03-0.42412E 04 0.28738E 05-0.80482E 05 0.79443E 05
 -0.12379E 00 0.18009E 01-0.10680E 02 0.27225E 02-0.25133E 02
 .75122E 01-0.13528E 03 0.88288E 03-0.24132E 04 0.23437E 04
 -0.12080E 03 0.23032E 04-0.15544E 05 0.43426E 05-0.42799E 05
 .33397E 03-0.64205E 04 0.43546E 05-0.12203E 06 0.12051E 06
 -0.24293E 03 0.46836E 04-0.31820E 05 0.89264E 05-0.88209E 05
 .44285E-01-0.65598E 00 0.39283E 01-0.10091E 02 0.93712E 01
 -0.27891E 01 0.51005E 02-0.33497E 03 0.91941E 03-0.89548E 03
 .45622E 02-0.88006E 03 0.59613E 04-0.16693E 05 0.16477E 05
 -0.12645E 03 0.24581E 04-0.16725E 05 0.46964E 05-0.46440E 05
 .92066E 02-0.17943E 04 0.12228E 05-0.34367E 05 0.34004E 05
 -0.68023E-02 0.10216E 00-0.61646E 00 0.15930E 01-0.14859E 01
 0.44118E 00-0.81551E 01 0.53804E 02-0.14813E 03 0.14457E 03
 -0.73112E 01 0.14215E 03-0.96546E 03 0.27080E 04-0.26759E 04
 0.20305E 02-0.39762E 03 0.27117E 04-0.76255E 04 0.75477E 04
 -0.14793E 02 0.29038E 03-0.19832E 04 0.55818E 04-0.55277E 04
 .38265E-03-0.58066E-02 0.35222E-01-0.91384F-01 0.85503E-01
 -0.25347E-01 0.47193E 00-0.31231E 01 0.86157E 01-0.84203E 01
 0.42402E 00-0.82874E 01 0.56384E 02-0.15832E 03 0.15656E 03
 -0.11792E 01 0.23204E 02-0.15849E 03 0.44613E 03-0.44185E 03
 .85949E 00-0.16952E 02 0.11595E 03-0.32663E 03 0.32366E 03
 -0.69786E-02 0.96460E-01-0.54279E 00 0.13248E 01-0.11809E 01
 0.35346E 00-0.59324E 01 0.37124E 02-0.98554E 02 0.93775E 02
 -0.51466E 01 0.92925E 02-0.61076E 03 0.16772E 04-0.16341E 04
 .14000E 02-0.25583E 03 0.16948E 04-0.46784E 04 0.45740E 04
 -0.10126E 02 0.18584E 03-0.12346E 04 0.34142E 04-0.33420E 04
 0.71521E-02-0.10063E 00 0.57043E 00-0.14011E 01 0.12557E 01
 -0.37236E 00 0.63799E 01-0.40205E 02 0.10727E 03-0.10244E 03
 0.55190E 01-0.10152E 03 0.67049E 03-0.18471E 04 0.18035E 04
 -0.15060E 02 0.28025E 03-0.18646E 04 0.51616E 04-0.50560E 04
 .10906E 02-0.20377E 03 0.13593E 04-0.37693E 04 0.36962E 04
 -0.25239E-02 0.36002E-01-0.20600E 00 0.51002E 00-0.46007E 00
 0.13591E 00-0.23694E 01 0.15055E 02-0.40404E 02 0.38744E 02
 -0.20580E 01 0.38418E 02-0.25512E 03 0.70536E 03-0.69039E 03
 0.56370E 01-0.10637E 03 0.71124E 03-0.19752E 04 0.19389E 04
 -0.40877E 01 0.77431E 02-0.51899E 03 0.14435E 04-0.14184E 04
 0.38309E-03-0.55233E-02 0.31837E-01-0.79316E-01 0.71910E-01
 -0.21200E-01 0.37417E 00-0.23922E 01 0.64477E 01-0.62016E 01
 0.32651E 00-0.61570E 01 0.41052E 02-0.11380E 03 0.11158E 03
 -0.89697E 00 0.17089E 02-0.11467E 03 0.31919E 03-0.31382E 03
 0.65114E 00-0.12450E 02 0.83737E 02-0.23341E 03 0.22969E 03
 -0.21349E-04 0.31026E-03-0.17976E-02 0.44976E-02-0.40916E-02
 0.12048E-02-0.21442E-01 0.13765E 00-0.37205E 00 0.35857E 00
 -0.18790E-01 0.35673E 00-0.23848E 01 0.66224E 01-0.65007E 01
 0.51732E-01-0.99188E 00 0.66718E 01-0.18599E 02 0.18305E 02
 -0.37584E-01 0.72313E 00-0.48746E 01 0.13607E 02-0.13403E 02

I, FOR SECTOR 9

0.81172E 01-0.12984E 03 0.83210E 03-0.22463E 04 0.21629E 04
 -0.64008E 03 0.12522E 05-0.85107E 05 0.23881E 06-0.23604E 06
 0.11208E 05-0.22849E 06 0.15764E 07-0.44648E 07 0.44399E 07
 -0.31384E 05 0.64354E 06-0.44492E 07 0.12617E 08-0.12557E 08
 0.22947E 05-0.47152E 06 0.32623E 07-0.92554E 07 0.92137E 07
 -0.84400E 01 0.14203E 03-0.91492E 03 0.24786E 04-0.23924E 04
 0.70929E 03-0.13905E 05 0.94704E 05-0.26609E 06 0.26323E 06
 -0.12504E 05 0.25452E 06-0.17579E 07 0.49820E 07-0.49562E 07
 0.35045E 05-0.71711E 06 0.49624E 07-0.14080E 08 0.14018E 08
 -0.25632E 05 0.52548E 06-0.36387E 07 0.10329E 08-0.10286E 08
 0.30907E 01-0.53492E 02 0.34721E 03-0.94549E 03 0.91587E 03
 -0.27178E 03 0.53535E 04-0.36570E 05 0.10294E 06-0.10196E 06
 0.43310E 04-0.98429E 05 0.68085E 06-0.19314E 07 0.19225E 07
 -0.13554E 05 0.27746E 06-0.19225E 07 0.54593E 07-0.54379E 07
 0.99163E 04-0.20334E 06 0.14098E 07-0.40048E 07 0.39901E 07
 -0.48549E 00 0.85593E 01-0.55893E 02 0.15282E 03-0.14845E 03
 0.44061E 02-0.87139E 03 0.59662E 04-0.16818E 05 0.16673E 05
 -0.78762E 03 0.16066E 05-0.11125E 06 0.31582E 06-0.31451E 06
 0.22112E 04-0.45299E 05 0.31418E 06-0.89269E 06 0.88954E 06
 -0.16181E 04 0.33199E 05-0.23039E 06 0.65483E 06-0.65265E 06
 0.27846E-01-0.49724E 00 0.32611E 01-0.89424E 01 0.87037E 01
 -0.25828E 01 0.51231E 02-0.35133E 03 0.99135E 03-0.98344E 03
 0.46313E 02-0.94551E 03 0.65528E 04-0.18610F 05 0.18539E 05
 -0.13006E 03 0.26659E 04-0.18503E 05 0.52594E 05-0.52422E 05
 0.95179E 02-0.19538E 04 0.13567E 05-0.38576E 05 0.38457E 05
 -0.91607E 01 0.13637E 03-0.81092E 03 0.20715E 04-0.19153E 04
 0.55717E 03-0.10286E 05 0.67229E 05-0.18394E 06 0.17875E 06
 -0.88019E 04 0.17177E 06-0.11594E 07 0.32390E 07-0.31922E 07
 0.24183E 05-0.47590E 06 0.32272E 07-0.90427E 07 0.89293E 07
 -0.17528E 05 0.34593E 06-0.23497E 07 0.65902E 07-0.65114E 07
 0.93959E 01-0.14443E 03 0.86741E 03-0.22330E 04 0.20769E 04
 -0.60591E 03 0.11270E 05-0.74122E 05 0.20364E 06-0.19846E 06
 0.96954E 04-0.19003E 06 0.12872E 07-0.36043E 07 0.35576E 07
 -0.26680E 05 0.52703E 06-0.35852E 07 0.10066E 08-0.99523E 07
 0.19346E 05-0.38318E 06 0.26105E 07-0.7354E 07 0.72565E 07
 -0.33327E 01 0.52559E 02-0.31982E 03 0.83160E 03-0.77930E 03
 0.22774E 03-0.42830E 04 0.28384E 05-0.78371E 05 0.76637E 05
 -0.37016E 04 0.73021E 05-0.49675E 06 0.13947E 07-0.13791E 07
 0.10205E 05-0.20273E 06 0.13843E 07-0.38956E 07 0.38576E 07
 -0.74032E 04 0.14743E 06-0.10079E 07 0.2386E 07-0.28121E 07
 0.50798E 00-0.81805E 01 0.50361E 02-0.13210E 03 0.12459E 03
 -0.36437E 02 0.69191E 03-0.46142E 04 0.12792E 05-0.12544E 05
 0.59906E 03-0.11883E 05 0.81114E 05-0.22823E 06 0.22598E 06
 -0.16534E 04 0.33004E 05-0.22603E 06 0.63727E 06-0.63182E 06
 0.11996E 04-0.23999E 05 0.16454E 06-0.4*419E 06 0.46038E 06
 -0.28437E-01 0.46585E 00-0.28959E 01 0.76501E 01-0.72529E 01
 0.21211E 01-0.40595E 02 0.27205E 03-0.75661E 03 0.74345E 03
 -0.35118E 02 0.69960E 03-0.47880E 04 0.13493E 05-0.13375E 05
 0.96962E 02-0.19428E 04 0.13335E 05-0.3649E 05 0.37360E 05
 -0.70346E 02 0.14122E 04-0.97030E 04 0.27410E 05-0.27208E 05
 0.57122E 01-0.79092E 02 0.42870E 03-0.10114E 04 0.87560E 03
 0.21211E 02 0.40595E 03-0.27205E 04 0.75661E 05 0.74345E 05

0.32263E 04-0.57114E 05 0.36237E 06-0.97142E 06 0.93076E 06
 -0.85416E 04 0.15321E 06-0.98196E 06 0.26510E 07-0.25526E 07
 0.61018E 04-0.10994E 06 0.70715E 06-0.19136E 07 0.18454E 07
 -0.57961E 01 0.81599E 02-0.44543E 03 0.10578E 04-0.92108E 03
 0.26268E 03-0.43670E 04 0.26392E 05-0.68273E 05 0.63735E 05
 -0.34624E 04 0.61914E 05-0.39573E 06 0.10663E 07-0.10254E 07
 0.91918E 04-0.16653E 06 0.10746E 07-0.29147E 07 0.28156E 07
 -0.65715E 04 0.11959E 06-0.77428E 06 0.21047E 07-0.20361E 07
 0.20064E 01-0.28645E 02 0.15793E 03-0.37848E 03 0.33218E 03
 -0.94951E 02 0.16012E 04-0.97944E 04 0.25570E 05-0.24033E 05
 ..14808E 04-0.23207E 05 0.14970E 06-0.40594E 06 0.39209E 06
 -0.34130E 04 0.62616E 05-0.40748E 06 0.11116E 07-0.10780E 07
 0.24427E 04-0.45006E 05 0.29376E 06-0.80291E 06 0.77965E 06
 -0.29820E 00 0.4311E 01-0.23993E 02 0.57996E 02-0.51278E 02
 0.14679E 02-0.25086E 03 0.15509E 04-0.40811E 04 0.38583E 04
 -0.10194E 03 0.37007E 04-0.24055E 05 0.67573E 05-0.63565E 05
 0.53963E 03-0.10007E 05 0.65575E 05-0.17972E 06 0.17485E 06
 -0.38649E 03 0.71955E 04-0.47282E 05 0.12981E 06-0.12643E 06
 0.16309E-01-0.23830E 00 0.13380E 01-0.31589E 01 0.28999E 01
 -0.83084E 00 0.14362E 02-0.89580E 02 0.23724E 03-0.22534E 03
 0.11601E 02-0.21454E 03 0.14030E 04-0.31400E 04 0.37328E 04
 -0.31057E 02 0C58081E 03-0.38268E 04 0.10526E 05-0.10266E 05
 0.22251E 02-0.41768E 03 0.27589E 04-0.76003E 04 0.74199E 04
 -0.19466E 01 0.26257E 02-0.13548E 03 0.30454E 03-0.25201E 03
 0.70541E 02-0.10553E 04 0.57816E 04-0.13778E 05 0.12033E 05
 -0.76168E 03 0.12019E 05-0.69650E 05 0.17428E 06-0.15855E 06
 0.19343E 04-0.30879E 05 0.18116E 06-0.45782E 06 0.41978E 06
 -0.13595E 04 0.21788E 05-0.12837E 06 0.32552E 06-0.29923E 06
 0.19629E 01-0.26695E 02 0.13819E 03-0.31171E 03 0.25879E 03
 -0.72582E 02 0.10926E 04-0.60313E 04 0.14472E 05-0.12715E 05
 0.79323E 03-0.12651E 05 0.73973E 05-0.18646E 06 0.17062E 06
 -0.20193E 04 0.32609E 05-0.19302E 06 0.49129E 06-0.45298E 06
 0.14202E 04-0.23031E 05 0.13690E 06-0.34960E 06 0.32311E 06
 -0.67069E 00 0.91763E 01-0.47736E 02 0.10821E 03-0.90268E 02
 0.25351E 02-0.38551E 03 0.21506E 04-0.52089E 04 0.46137E 04
 -0.28217E 03 0.45646E 04-0.27011E 05 0.68737E 05-0.63372E 05
 0.72096E 03-0.11815E 05 0.70762E 05-0.11178E 06 0.16880E 06
 -0.50761E 03 0.83549E 04-0.50243E 05 0.12947E 06-0.12049E 06
 0.98303E-01-0.13521E 01 0.70685E 01-0.16102E 02 0.13497E 02
 -0.37939E 01 0.58285E 02-0.32842E 03 0.80250E 03-0.71608E 03
 0.42959E 02-0.70405E 03 0.42108E 04-0.10806E 05 0.10027E 05
 -0.11011E 03 0.18285E 04-0.11065E 05 0.2.654E 05-0.26769E 05
 0.77592E 02-0.12941E 04 0.78620E 04-0.20418E 05 0.19114E 05
 -0.53048E-02 0.73317E-01-0.38507E 00 0.88127E 00-0.74192E 00
 0.20867E 00-0.32359E 01 0.18396E 02-0.47297E 02 0.40676E 02
 -0.23971E 01 0.39724E 02-0.23970E 03 0.61939E 03-0.57775E 03
 0.61590E 01-0.10342E 03 0.63119E 03-0.16451E 04 0.15443E 04
 -0.43424E 01 0.73225E 02-0.44859E 03 0.11723E 04-0.11026E 04
 0.33690E 00-0.45240E 01 0.22873E 02-0.50327E 02 0.40765E 02
 -0.11339E 02 0.16093E 03-0.83426E 03 0.18845E 04-0.15670E 04

0.10996E 03-0.15968E 04 0.85416E 04-0.19904E 05 0.17040E 05
 -0.27131E 03 0.39599E 04-0.21349E 05 0.50117E 05-0.43194E 05
 0.18852E 03-0.27552E 04 0.14892E 05-0.35042E 05 0.30262E 05
 -0.33919E 00 0.45742E 01-0.23155E 02 0.51016E 02-0.41379E 02
 11519E 02-0.16390E 03 0.85278E 03-0.19336E 04 0.16136E 04
 -0.11226E 03 0.16406E 04-0.88279E 04 0.20687E 05-0.17802E 05
 27724E 03-0.40763E 04 0.22114E 05-0.52220E 05 0.45245E 05
 -0.19267E 03 0.28375E 04-0.15434E 05 0.36534E 05-0.31717E 05
 11538E 00-0.15597E 01 0.79102E 01-0.17462E 02 0.14192E 02
 -0.39521E 01 0.56488E 02-0.29549E 03 0.67363E 03-0.56509E 03
 38842E 02-0.57254E 03 0.31066E 04-0.73375E 04 0.63589E 04
 -0.96094E 02 0.14262E 04-0.78056E 04 0.18583E 05-0.16217E 05
 66807E 02-0.99344E 03 0.54516E 04-0.13010E 05 0.11376E 05
 -0.16826E-01 0.22789E 00-0.11580E 01 0.25616E 01-0.20861E 01
 58097E 00-0.83438E 01 0.43883E 02-0.10058E 03 0.84806E 02
 -0.57584E 01 0.85586E 02-0.46812E 03 0.11139E 04-0.97170E 03
 14269E 02-0.21367E 03 0.11792E 04-0.2 286E 04 0.24847E 04
 -0.99233E 01 0.14890E 03-0.82390E 03 0.19810E 04-0.17435E 04
 90340F-03-0.12257E-01 0.62395E-01-0.13829E 00 0.11285E 00
 -0.31426E-01 0.45342E 00-0.23967E 01 0.55208E 01-0.46768E 01
 31385E 00-0.46993E 01 0.25886E 02-0.61999E 02 0.54392E 02
 -0.77873E 00 0.11752E 02-0.65327E 02 0.15773E 03-0.13934E 03
 54164E 00-0.81911E 01 0.45652E 02-0.11048E 03 0.97769E 02
 -0.22537E-01 0.30320E 00-0.15213E 01 0.33196E 01-0.26661E 01
 74046E 00-0.10272E 02 0.51928E 02-0.11425E 03 0.92544E 02
 -0.68430E 01 0.95374E 02-0.48742E 03 0.10849E 04-0.88917E 03
 16649E 02-0.23209E 03 0.11892E 04-0.26539E 04 0.21808E 04
 -0.11505E 02 0.16029E 03-0.82169E 03 0.11347E 04-0.15081E 04
 22697E-01-0.30611E 00 0.15364E 01-0.33541E 01 0.26950E 01
 -0.74870E 00 0.10392E 02-0.52594E 02 0.11586E 03-0.93972E 02
 69248E 01-0.96761E 02 0.49559E 03-0.11057E 04 0.90827E 03
 -0.16847E 02 0.23558E 03-0.12098E 04 0.27067E 04-0.22296E 04
 11639E 02-0.16269E 03 0.83593E 03-0.18710E 04 0.15417E 04
 -0.77156E-02 0.10416E 00-0.52309E 00 0.11426E 01-0.91869E 00
 25517E 00-0.35466E 01 0.17981E 02-0.39686E 02 0.32250E 02
 -0.23656E 01 0.33162E 02-0.17039E 03 0.38143E 03-0.31439E 03
 57564E 01-0.80787E 02 0.41631E 03-0.93470E 03 0.77263E 03
 -0.39764E 01 0.55788E 02-0.28761E 03 0.64598E 03-0.53411E 03
 11240E-02-0.15182E-01 0.76294E-01-0.16677E 00 0.13417E 00
 -0.37255E-01 0.51858E 00-0.26339E 01 0.51246E 01-0.47427E 01
 34622E 00-0.48687E 01 0.25097E 02-0.56370E 02 0.46616E 02
 -0.84268E 00 0.11867E 02-0.61355E 02 0.13823E 03-0.11465E 03
 58200E 00-0.81929E 01 0.42375E 02-0.9 498E 02 0.79220E 02
 -0.60273E-04 0.81455E-03-0.40957E-02 0.89582E-02-0.72119E-02
 20018E-02-0.27906E-01 0.14198E 00-0.31456E 00 0.25661E 00
 -0.18646E-01 0.26296E 00-0.13595E 01 0.30629E 01-0.25406E 01
 45389E-01-0.64109E 00 0.33247E 01-0.7 140E 01 0.62512E 01
 -0.31341E-01 0.44249E 00-0.22953E 01 0.51883E 01-0.43165E 01

J. FOR SECTOR 10

0.12649E 02-0.18725E 03 0.10986E 04-0.27764E 04 0.25458E 04
 -0.74347E 03 0.13534E 05-0.87684E 05 0.23848E 06-0.23081E 06
 0.11622E 05-0.22521E 06 0.15128E 07-0.42135E 07 0.41443E 07
 -0.31991E 05 0.62597E 06-0.42279E 07 0.11817E 08-0.11650E 08
 0.23250E 05-0.45655E 06 0.30897E 07-0.86465E 07 0.85311E 07
 -0.13299E 02 0.20363E 03-0.11998E 04 0.30425E 04-0.27972E 04
 0.81882E 03-0.14946E 05 0.97120E 05-0.26467E 06 0.25651E 06
 -0.12886E 05 0.25003E 06-0.16825E 07 0.46915E 07-0.46179E 07
 0.35505E 05-0.69552E 06 0.47050E 07-0.13163E 08 0.12985E 08
 -0.25812E 05 0.50741E 06-0.34390E 07 0.96328E 07-0.95100E 07
 0.48799E 01-0.76099E 02 0.45117E 03-0.11498E 04 0.10612E 04
 -0.31114E 03 0.57112E 04-0.37267E 05 0.10184E 06-0.98898E 05
 0.49447E 04-0.96259E 05 0.64934E 06-0.18135E 07 0.17869E 07
 -0.13644E 05 0.26805E 06-0.18172E 07 0.50911E 07-0.50268E 07
 0.99248E 04-0.19563E 06 0.13286E 07-0.37263E 07 0.36820E 07
 -0.76439E 00 0.12069E 02-0.71941E 02 0.18412E 03-0.17048E 03
 0.50035E 02-0.92301E 03 0.60438E 04-0.16555E 05 0.16102E 05
 -0.80141E 03 0.15647E 05-0.10576E 06 0.29574E 06-0.29165E 06
 0.22140E 04-0.43606E 05 0.29614E 06-0.83057E 06 0.82068E 06
 -0.16111E 04 0.31832E 05-0.21655E 06 0.60799E 06-0.60116E 06
 0.43596E-01-0.69462E 00 0.41582E 01-0.10678E 02 0.99124E 01
 -0.29108E 01 0.53914E 02-0.35398E 03 0.97135E 03-0.94589E 03
 0.46885E 02-0.91748E 03 0.62110E 04-0.17385E 05 0.17155E 05
 -0.12963E 03 0.25582E 04-0.17397E 05 0.48832E 05-0.48277E 05
 0.94354E 02-0.18678E 04 0.12722E 05-0.3 747E 05 0.35364E 05
 -0.19226E 02 0.26388E 03-0.13936E 04 0.32072E 04-0.27142E 04
 0.77005E 03-0.12117E 05 0.69739E 05-0.17349E 06 0.15710E 06
 -0.91040E 04 0.15471E 06-0.94690E 06 0.24729E 07-0.23249E 07
 0.23651E 05-0.40850E 06 0.25305E 07-0.66678E 07 0.63097E 07
 -0.16786E 05 0.29168E 06-0.18148E 07 0.47970E 07-0.45496E 07
 .20197E 02-0.28111E 03 0.14893E 04-0.34377E 04 0.29176E 04
 -0.83097E 03 0.13115E 05-0.75890E 05 0.18965E 06-0.17235E 06
 .99164E 04-0.16914E 06 0.10404E 07-0.27271E 07 0.25710E 07
 -0.25806E 05 0.44734E 06-0.27842E 07 0.73617E 07-0.69838E 07
 0.18326E 05-0.31957E 06 0.19975E 07-0.52976E 07 0.50365E 07
 -0.73079E 01 0.10265E 03-0.54621E 03 0.12662E 04-0.10788E 04
 0.30806E 03-0.48948E 04 0.28531E 05-0.71727E 05 0.65495E 05
 -0.37230E 04 0.63953E 05-0.39595E 06 0.10429E 07-0.98664E 06
 0.97113E 04-0.16950E 06 0.10615E 07-0.28190E 07 0.26829E 07
 -0.69013E 04 0.12116E 06-0.76184E 06 0.20292E 07-0.19351E 07
 0.11273E 01-0.15947E 02 0.85222E 02-0.19838E 03 0.16968E 03
 -0.48533E 02 0.77659E 03-0.45578E 04 0.11522E 05-0.10567E 05
 0.59304E 03-0.10258E 05 0.63876E 05-0.16896E 06 0.16034E 06
 -0.15498E 04 0.27228E 05-0.17144E 06 0.45707E 06-0.43620E 06
 0.11019E 04-0.19470E 05 0.12307E 06-0.32901E 06 0.31459E 06
 -0.63395E-01 0.90215E 00-0.48308E 01 0.11313E 02-0.97103E 01
 0.27805E 01-0.44794E 02 0.26453E 03-0.67203E 03 0.61872E 03
 -0.34277E 02 0.59656E 03-0.37334E 04 0.99109E 04-0.94295E 04
 0.89695E 02-0.15851E 04 0.10026E 05-0.26817E 05 0.25652E 05
 -0.63793E 02 0.11336E 04-0.71970E 04 0.19301E 05-0.18495E 05

0.14407E 02-0.19273E 03 0.96730E 03-0.21116E 04 0.16966E 04
 -0.47316E 03 0.65856E 04-0.33403E 05 0.73751E 05-0.59950E 05
 0.43467E 04-0.61226E 05 0.31401E 06-0.70148E 06 0.57692E 06
 -0.10537E 05 0.14872E 06-0.76415E 06 0.17102E 07-0.14090E 07
 0.72638E 04-0.10252E 06 0.52664E 06-0.11782E 07 0.97028E 06
 -0.15162E 02 0.20395E 03-0.10241E 04 0.22366E 04-0.17980E 04
 0.50297E 03-0C69907E 04 0.35514E 05-0.78546E 05 0.63958E 05
 -0.46289E 04 0.65131E 05-0.33482E 06 0.74975E 06-0.61808E 06
 0.11222E 05-0.15821E 06 0.81475E 06-0.18278E 07 0.15093E 07
 -0.77346E 04 0.10903E 06-0.56128E 06 0.12586E 07-0.10387E 07
 0.54681E 01-0.73769E 02 0.37066E 03-0.81015E 03 0.65176E 03
 -0.18267E 03 0.25404E 04-0.12937E 05 0.28685E 05-0.23417E 05
 0.16850E 04-0.23742E 05 0.12246E 06-0.27520E 06 0.22765E 06
 -0.40851E 04 0.57669E 05-0.29799E 06 0.67081E 06-0.55582E 06
 0.28148E 04-0.39724E 05 0.20516E 06-0.46156E 06 0.38216E 06
 -0.83977E 00 0.11353E 02-0.57094E 02 0.12490E 03-0.10058E 03
 0.28225E 02-0.39316E 03 0.20079E 04-0.44656E 04 0.36566E 04
 -0.26099E 03 0.36864E 04-0.19089E 05 0.43068E 05-0.35765E 05
 0.63271E 03-0.89534E 04 0.46441E 05-0.10495E 06 0.87290E 05
 -0.43582E 03 0.61641E 04-0.31951E 05 0.72149E 05-0.59952E 05
 0.47003E-01-0.63661E 00 0.32046E 01-0.70183E 01 0.56579E 01
 -0.15892E 01 0.22188E 02-0.11369E 03 0.2 374E 03-0.20849E 03
 0.14731E 02-0.20875E 03 0.10856E 04-0.24602E 04 0.20517E 04
 -0.35711E 02 0.50695E 03-0.26407E 04 0.59935E 04-0.50055E 04
 0.24590E 02-0.34884E 03 0.18155E 04-0.41166E 04 0.34343E 04
 -0.53410E 01 0.71427E 02-0.35409E 03 0.76248E 03-0.60391E 03
 0.16775E 03-0.22436E 04 0.10854E 05-0.22725E 05 0.17451E 05
 -0.14160E 04 0.18259E 05-0.84035E 05 0.16532E 06-0.11774E 06
 0.33385E 04-0.42407E 05 0.19105E 06-0.36512E 06 0.25007E 06
 -Q.22743E 04 0.28665E 05-0.12768E 06 0.24011E 06-0.16072E 06
 0.56271E 01-0.75439E 02 0.37383E 03-0.80463E 03 0.63698E 03
 -0.17729E 03 0.23636E 04-0.11416E 05 0.23856E 05-0.18281E 05
 0.14916E 04-0.19116E 05 0.87528E 05-0.17102E 06 0.12071E 06
 -0.35113E 04 0.44268E 05-0.19802E 06 0.37468E 06-0.25304E 06
 0.23900E 04-0.29873E 05 0.13196E 06-0.24520E 06 0.16126E 06
 -0.20278E 01 0.27209E 02-0.13476E 03 0.28987E 03-0.22933E 03
 0.63901E 02-0.84953E 03 0.40944E 04-0.85342E 04 0.65208E 04
 -0.53493E 03 0.68109E 04-0.30962E 05 0.59911E 05-0.41740E 05
 0.12563E 04-0.15706E 05 0.69548E 05-0.12969E 06 0.85761E 05
 -0.85401E 03 0.10574E 05-0.46152E 05 0.84252E 05-0.53933E 05
 0.31103E 00-0.41751E 01 0.20669E 02-0.44441E 02 0.35142E 02
 -Q.97996E 01 0.13002E 03-0.62565E 03 0.13016E 04-0.99230E 03
 0.81665E 02-0.10343E 04 0.46728E 04-0.89653E 04 0.61741E 04
 -0.19137E 03 0.23756E 04-0.10424E 05 0.19181E 05-0.12433E 05
 0.12992E 03-0.15955E 04 0.68882E 04-0.12367E 05 0.77093E 04
 -0.17383E-01 0.23341E 00-0.11553E 01 0.24834E 01-0.19632E 01
 0.54777E 00-0.72598E 01 0.34903E 02-0.72537E 02 0.55237E 02
 -0.45485E 01 0.57394E 02-0.25814E 03 0.49221E 03-0.33607E 03
 0.10638E 02-0.13136E 03 0.57240E 03-0.10424E 04 0.66486E 03
 -0.72135E 01 0.88034E 02-0.37681E 03 0.66747E 03-0.40690E 03
 0.94709E 00-0.12726E 02 0.63027E 02-0.13557E 03 0.10726E 03
 -0.29805E 02 0.39697E 03-0.19125E 04 0.39844E 04-0.30427E 04

0.25026E 03-0.31995E 04 0.14580E 05+0.28303E 05 0.19806E 05
 -0.58938E 03 0.74138E 04-0.33004E 05 0.62025E 05-0.41486E 05
 0.40150E 03-0.50098E 04 0.22039E 05-0.40707E 05 0.26536E 05
 -0.99873E 00 0.13437E 02-0.66516E 02 0.14300E 03-0.11306E 03
 0.31458E 02-0.41774E 03 0.20082E 04-0.41732E 04 0.31777E 04
 -0.26311E 03 0.33428E 04-0.15135E 05 0.29126E 05-0.20142E 05
 0.61863E 03-0.77218E 04 0.34078E 05-0.63246E 05 0.41530E 05
 -0.42106E 03 0.52094E 04,0.22690E 05 0.41293E 05-0.26310E 05
 0.35995E 00-0.48438E 01 0.23960E 02-0.51468E 02 0.40657E 02
 -0.11321E 02 0.14987E 03-0.71834E 03 0.14875E 04-0.11279E 04
 0.94134E 02-0.11871E 04 0.53253E 04-0.10117E 05 0.68730E 04
 -0.22079E 03 0.27298E 04-0.11896E 05 0.21667E 05-0.13825E 05
 0.15008E 03-0.18373E 04 0.78862E 04-0.14033E 05 0.86223E 04
 -0.55199E-01 0.74278E 00-0.36719E 01 0.78818E 01-0.62215E 01
 0.17332E 01-0.22888E 02 0.10942E 03-0.22586E 03 0.17064E 03
 -0.14334E 02 0.17958E 03-0.79870E 03 0.13991E 04-0.10008E 04
 0.33540E 02-0.41116E 03 0.17704E 04-0.31658E 04 0.19613E 04
 -0.22771E 02 0.27607E 03-0.11685E 04 0.20331E 04-0.12021E 04
 0.30840E-02-0.41496E-01 0.20503E 00-0.43987E 00 0.34700E 00
 -0.96709E-01 0.12747E 01-0.60816E 01 0.12523E 02-0.94348E 01
 0.79614E 00-0.99217E 01 0.43815E 02-0.81396E 02 0.53526E 02
 -0.16591E 01 0.22629E 02-0.96444E 02 0.16971E 03-0.10234E 03
 0.12608E 01-0.15162E 02 0.63398E 02-0.10813E 03 0.61641E 02
 -0.63241E-01 0.85351E 00-0.42332E 01 0.91208E 01-0.72281E 01
 0.20108E 01-0.26893E 02 0.13035E 03-0.27353E 03 0.21059E 03
 -0.17094E 02 0.22114E 03-0.10255E 04 0.20377E 04-0.14699E 04
 0.40454E 02-0.51671E 03 0.23544E 04-0.41702E 04 0.31976E 04
 -0.27626E 02 0.35070E 03-0.15841E 04 0.30385E 04-0.20917E 04
 0.66730E-01-0.90132E 00 0.44683E 01-0.96224E 01 0.76215E 01
 -0.21221E 01 0.28315E 02-0.13699E 03 0.28685E 03-0.22031E 03
 0.17982E 02-0.23148E 03 0.10680E 04-0.21081E 04 0.15078E 04
 -0.42500E 02 0.53959E 03-0.24423E 04 0.46979E 04-0.32468E 04
 0.29005E 02-0.36579E 03 0.16399E 04-0.31128E 04 0.21118E 04
 -0.24055E-01 0.32490E 00-0.16097E 01 0.34639E 01-0.27415E 01
 0.76374E 00-0.10164E 02 0.49050E 02-0.10240E 03 0.78374E 02
 -0.64402E 01 0.82408E 02-0.37745E 03 0.73781E 03-0.52105E 03
 0.15192E 02-0.19144E 03 0.85813E 03-0.1286E 04 0.11047E 04
 -0.10358E 02 0.12955E 03-0.57445E 03 0.10735E 04-0.71206E 03
 0.36890E-02-0.49819E-01 0.24668E 00-0.53049E 00 0.41957E 00
 -0.11693E 00 0.15528E 01-0.74758E 01 0.15563E 02-0.11875E 02
 0.98149E 00-0.12492E 02 0.56823E 02-0.11005E 03 0.76766E 02
 -0.23109E 01 0.28922E 02-0.12846E 03 0.24061E 03-0.16016E 03
 0.15741E 01-0.19538E 02 0.85730E 02-0.15776E 03 0.10226E 03
 -0.20610E-03 0.27827E-02-0.13772E-01 0.29602E-01-0.23399E-01
 0.65229E-02-0.86474E-01 0.41555E 00-0.86316E 00 0.65690E 00
 -0.54542E-01 0.69109E 00-0.31253E 01 0.60047E 01-0.41435E 01
 0.12821E 00-0.15954E 01 0.70295E 01-0.13015E 02 0.85165E 01
 -0.87259E-01 0.10761E 01-0.46785E 01 0.84912E 01-0.53875E 01

KUFOR SECTOR 11

0.46798E 01-0.67063F 02 0.44845E 03-0.12455F 04 0.12227E 04
 -0.30667F 02 0.73208E 04-0.50548E 05 0.14323E 06-0.14248E 06
 0.68015E 04-0.13800E 06 0.95967E 06-0.27312E 07 0.27244E 07
 -0.19225E 05 0.34060E 06-0.27190E 07 0.77426E 07-0.77261E 07
 0.14109E 05-0.28676E 06 0.19968E 07-0.56874E 07 0.56761E 07
 -0.49290E 01 0.77211E 02-0.51260E 03 0.14170E 04-0.13868E 04
 0.41638E 03-0.82606E 04 0.56898E 05-0.16099E 06 0.15998E 06
 -0.76408E 04 0.15490E 06-0.10760E 07 0.30600F 07-0.30509E 07
 0.21560E 05-0.43814E 06 0.30468E 0 0.8 706E 07 0.86488E 07
 -0.15812E 05 0.32158E 06-0.22371E 07 0.63680E 07-0.63530E 07
 0.18194E 01-0.29718E 02 0.19782E 03-0.54777E 03 0.53669E 03
 -0.16129E 03 0.32022E 04-0.22076E 05 0.62496E 05-0.62129E 05
 0.29603F 04-0.60101E 05 0.41765E 06-0.11881E 07 0.11848E 07
 -0.83515F 04 0.17201E 06-0.11826E 07 0.33664E 07-0.33584E 07
 0.61246E 04-0.12478E 06 0.86836E 06-0.24723E 07 0.24668E 07
 -0.28689E 00 0.48084E 01-0.32114E 02 0.89118E 02-0.87442E 02
 0.26288E 02-0.52281E 03 0.36083E 04-0.10222E 05 0.10166E 05
 -0.48314E 03 0.98228E 04-0.68296E 05 0.19434E 06-0.19384E 06
 0.13631E 04-0.27788E 05 0.19339E 06-0.55065E 06 0.54944E 06
 -0.99962F 03 0.20396E 05-0.14200E 06 0.40440E 06-0.40356E 06
 0.16468E-01-0.28090E 00 0.18812E 01-0.52296E 01 0.51373E 01
 -0.15444F 01 0.30764E 02-0.21251E 03 0.60236E 03-0.59930E 03
 0.28408E 02-0.57821E 03 0.40219E 04-0.11448E 05 0.11420E 05
 -0.80150F 02 0.16357E 04-0.11388E 05 0.32433E 05-0.32366E 05
 0.58776E 02-0.12006E 04 0.83614E 04-0.23817E 05 0.23771E 05
 -0.25551E 01 0.26434E 02-0.16977E 03 0.45905E 03-0.44255E 03
 0.13033E 03-0.25665E 04 0.17459E 05-0.49020E 05 0.48475E 05
 -0.22338E 04 0.45902E 05-0.31673E 06 0.89718E 06-0.89224E 06
 0.62037E 04-0.12813E 06 0.88578E 06-0.25118E 07 0.24997E 07
 -0.45073E 04 0.93246E 05-0.64501E 06 0.18296E 07-0.18209E 07
 0.28348E 01-0.33809E 02 0.21155E 03-0.56164E 03 0.53446E 03
 -0.15940E 03 0.30293E 04-0.20371E 05 0.56784E 05-0.55883E 05
 0.26293E 04-0.52811E 05 0.36214E 06-0.10219E 07 0.10137E 07
 -0.72551E 04 0.14680E 06-0.10093E 07 0.28527E 07-0.28327E 07
 0.52585E 04-0.10666E 06 0.73397E 06-0.20753E 07 0.20613E 07
 -0.10104E 01 0.12815E 02-0.80859E 02 0.21596E 03-0.20640E 03
 0.62049E 02-0.11770E 04 0.79454E 04-0.22202E 05 0.21885E 05
 -0.10259E 04 0.20551E 05-0.14121E 06 0.39894E 06-0.39607E 06
 0.28291E 04-0.57090E 05 0.39320E 06-0.11125E 07 0.11054E 07
 -0.20494E 04 0.41458E 05-0.28575E 06 0.80878E 06-0.80381E 06
 0.15107E 00-0.19970E 01 0.12791E 02-0.34524E 02 0.33241E 02
 -0.10041E 02 0.19163F 03-0.13020E 04 0.36530E 04-0.36105E 04
 0.16745E 03-0.33620E 04 0.23178E 05-0.65617E 05 0.65233E 05
 -0.46185E 03 0.93364E 04-0.64490E 05 0.18278E 06-0.18184E 06
 0.33448E 03-0.67768E 04 0.46838E 05-0.13279E 06 0.13212E 06
 -0.82103E-02 0.11223F 00-0.73080E 00 0.19949E 01-0.19359E 01
 0.58626E 00-0.11283E 02 0.77160E 02-0.21738F 03 0.21542E 03
 -0.98533E 01 0.19858E 03-0.13736E 04 0.38968E 04-0.38791E 04
 0.27179E 02-0.55113E 03 0.38180E 04-0.10841E 05 0.10797E 05
 -0.19677E 02 0.39981E 03-0.27710E 04 0.78693E 04-0.78380E 04

0.10865E 01-0.72167E 01 0.29447E 02-0.48221E 02 0.25398E 02
 -0.53397E 01-0.56580F 02 0.10962E 04-0.43241E 04 0.50811E 04
 -0.20916E 03 0.51474E 04-0.42353E 05 0.13177E 06-0.13860E 06
 0.72374E 03-0.16556E 05 0.13119E 06-0.40092E 06 0.41755E 06
 -0.57695E 03 0.12849E 05-0.10052E 06 0.30529E 06-0.31689E 06
 -0.13470E 01 0.11641E 02-0.50970E 02 0.93596E 02-0.60521E 02
 0.16375E 02-0.62940E 02-0.57350E 03 0.33663E 04-0.44640E 04
 0.12901E 03-0.45835E 04 0.41239E 05-0.13342E 06 0.14333E 06
 -0.55509E 03 0.15698E 05-0.13204E 06 0.41503E 06-0.43910E 06
 0.46679L 03-0.12443E 05 0.10241E 06-0.31875E 06 0.33551E 06
 0.47651E 00-0.42619E 01 0.18602E 02-0.33998E 02 0.21828E 02
 -0.61664E 01 0.19869E 02 0.23414E 03-0.13047E 04 0.17086E 04
 -0.48982E 02 0.18053E 04-0.16006E 05 0.51472E 05-0.55119E 05
 0.21186E 03-0.61689E 04 0.51335E 05-0.16058F 06 0.16944E 06
 -0.17869E 03 0.48917E 04-0.39875E 05 0.12356E 06-0.12973E 06
 -0.68638E-01 0.60964E 00-0.26268E 01 0.47089E 01-0.29321E 01
 0.85396F 00-0.12018E 01-0.46096E 02 0.22451E 03-0.28347E 03
 0.90289L 01-0.31040E 03 0.26649E 04-0.84521E 04 0.89847E 04
 -0.37045E 02 0.10475E 04-0.85235E 04 0.26384E 05-0.27679E 05
 0.30913E 02-0.82837E 03 0.66217E 04-0.20327E 05 0.21230E 05
 0.35467E-02-0.30814E-01 0.13087E 00-0.22939F 00 0.13757E 00
 -0.41226E-01-0.33906E-01 0.30552E 01-0.13525E 02 0.16570E 02
 -0.59227E 00 0.18962E 02-0.15818E 03 0.49525E 03-0.52277E 03
 0.23253E 01-0.63413E 02 0.50548E 03-0.15493E 04 0.16162E 04
 -0.19222E 01 0.50066F 02-0.39304E 03 0.11958E 04-0.12426E 04
 -0.32615F 00 0.21814E 01-0.63490E 01 0.29277E 01 0.67425E 01
 -0.28313E 01 0.13129E 03-0.12155E 04 0.39781E 04-0.42991E 04
 0.17836E 03-0.41497E 04 0.317255 05-0.95201E 05 0.98097E 05
 -0.55659E 03 0.12479E 05-0.93829E 05 0.27912E 06-0.28614E 06
 0.42394E 03-0.93919E 04 0.70213E 05-0.20824E 06 0.21311E 06
 0.43415E 00-0.37723E 01 0.13802E 02-0.17934E 02 0.42640E 01
 -0.47262E 00-0.10099E 03 0.11259E 04-0.39310E 04 0.43848E 04
 -0.16315E 03 0.42178E 04-0.33306E 05 0.10161E 06-0.10570E 06
 0.53245E 03-0.12936E 05 0.99699E 05-0.30045E 06 0.31038E 06
 -0.41146E 03 0.98030E 04-0.74933E 05 0.22488E 06-0.23175E 06
 -0.15415E 00 0.13509E 01-0.48079E 01 0.58084E 01-0.76797E 00
 0.27505E-02 0.42286E 02-0.45049E 03 0.15504E 04-0.17178E 04
 0.64183F 02-0.16623E 04 0.13031E 05-0.39607E 05 0.41117E 05
 -0.20839E 03 0.50851E 04-0.38968E 05 0.11709E 06-0.12075E 06
 0.16085E 03-0.38513E 04 0.29288E 05-0.87655E 05 0.90192E 05
 0.21912E-01-0.18460E 00 0.60842E 00-0.57238E 00-0.16877E 00
 0.75847E-01-0.79727E 01 0.8529E 02-0.26308E 03 0.28769E 03
 -0.11089E 02 0.28076E 03-0.1705E 04 0.61508E 04-0.67729E 04
 0.35487E 02-0.85367E 03 0.4717E 04-0.19337E 05 0.19875E 05
 -0.27280E 02 0.64545E 03-0.8607E 04 0.14473E 05-0.14846E 05
 -0.11063E-02 0.87255E-02-0.25397E-01 0.11733E-01 0.26928E-01
 -0.90167E-02 0.52908E 00-0.48890E 01 0.15988E 02-0.17271E 02
 0.68891E 00-0.17017E 02 0.12982E 03-0.38916E 03 0.40075E 03
 -0.21755E 01 0.51458E 02-0.38610E 03 0.11473E 04-0.11754E 04
 0.16660E 01-0.38849E 02 0.28982E 03-0.85860E 03 0.87811E 03

0.60321E-01-0.52625E 00 0.19103E 01-0.24326E 01 0.50882E 00
 -0.21050E-02-0.14724E 02 0.16202E 03-0.56343E 03 0.62731E 03
 -0.23597E 04 0.59624E 03-0.47058E 04 0.14352E 05-0.14929E 05
 0.78236E 04-0.18194E 04 0.14023E 05-0.42259E 05 0.43655E 05
 -0.58628E 04-0.13743E 04-0.10508E 05 0.31538E 05-0.32504E 05
 -0.81119E-01 0.81883E 00-0.32918E 01 0.52416E 01-0.25939E 01
 0.60689E 00 0.86508E 01-0.14167E 03 0.5 311E 03-0.63106E 03
 0.20473E 02-0.59510E 03 0.48979E 04-0.15242E 05 0.16036E 05
 -0.70647E 02 0.18616E 04-0.14801E 05 0.45309E 05-0.47230E 05
 0.55405E 02-0.14178E 04 0.11146E 07-0.33931E 05 0.35259E 05
 0.29047E-01-0.29392E 00 0.11597E 01-0.17818E 01 0.80785E 00
 -0.18771E 00-0.40914E 01 0.58480E 02-0.21797E 03 0.25032E 03
 -0.82806E 01 0.43735E 03-0.19308E 04 0.59759E 04-0.62679E 04
 0.28180E 02-0.73832E 03 0.58195E 04-0.1 738E 05 0.18445E 05
 -0.224021E 02 0.56143E 03-0.43794E 04 0.13280E 05-0.13768E 05
 -0.41614E-02 0.41012E-01-0.15473E 00 0.21632E 00-0.72764E-01
 0.14809E-01 0.88982E 00-0.10628E 02 0.37865E 02-0.42632E 02
 0.14860E 01-0.40746E 02 0.32493E 03-0.99608E 03 0.10391E 04
 -0.49234E 01 0.12547E 03-0.97428E 03 0.29474E 04-0.30516E 04
 0.38185E 01-0.95118E 02 0.73208E 03-0.22048E 04 0.22768E 04
 0.21167E-03-0.20005E-02 0.70668E-02-0.83600E-02 0.83841E-03
 0.67413E-04-0.65067E-01 0.68598E 00-0.23529E 01 0.26027E 01
 -0.95373E-01 0.25080E 01-0.19637E 02 0.59654E 02-0.61909E 02
 0.30878E 00-0.76529E 01 0.58603E 02-0.17602E 03 0.18148E 03
 -0.23790E 00 0.57859E 01-0.43974E 02 0.13157E 03-0.13535E 03
 -0.44158E-02 0.45673E-01-0.19017E 00 0.32230E 00-0.18172E 00
 0.43646E-01 0.18735E 00-0.56178E 01 0.23397E 02-0.28067E 02
 0.84526E 00-0.26199E 02 0.22157E 03-0.69934E 03 0.74148E 03
 -0.30463E 01 0.82916E 02-0.67438E 03 0.20871E 04-0.21891E 04
 0.24152E 01-0.63410E 02 0.50870E 03-0.15641E 04 0.16345E 04
 0.58718E-02-0.65841E-01 0.28666E 00-0.52166E 00 0.33253E 00
 -0.86675E-01 0.28797E 00 0.37765E 01-0.20673E 02 0.26957E 02
 -0.58087E 00 0.24643E 02-0.22478E 03 0.73142E 03-0.78813E 03
 0.25103E 01-0.81746E 02 0.69860E 03-0.22116E 04 0.23488E 04
 -0.20785E 01 0.63352E 02-0.53065E 03 0.16650E 04-0.17597E 04
 -0.21093E-02 0.23667E-01-0.10188E 00 0.18221E 00-0.11297E 00
 0.29494E-01-0.51216E-01-0.17621E 01 0.86522E 01-0.10953E 02
 0.25820E 00-0.10102E 02 0.89853E 02-0.28937E 03 0.31013E 03
 -0.10510E 01 0.33043E 02-0.27757E 03 0.87200E 03-0.92222E 03
 0.85916E 00-0.25507E 02 0.21047E 03-0.65583E 03 0.69052E 03
 0.30401E-03-0.33561E-02 0.14103E-01-0.24271E-01 0.14081E-01
 -0.36269E-02-0.81968E-02 0.36951E 00-0.15882E 01 0.19267E 01
 -0.52479E-01 0.17990E 01-0.15411E 02 0.48836E 02-0.51891E 02
 0.19647E 00-0.57617E 01 0.47143E 02-0.14631E 03 0.15371E 03
 -0.15746E 00 0.44201E 01-0.35640E 02 0.10985E 03-0.11496E 03
 -0.15575E-04 0.16772E-03-0.68202E-03 0.11092E-02-0.57535E-03
 0.14373E-03 0.14333E-02-0.26387E-01 0.10328E 00-0.12102E 00
 0.36923E-02-0.11427E 00 0.94753E 00-0.29590E 01 0.31191E 01
 -0.13016E-01 0.35952E 00-0.28735E 01 0.88189E 01-0.92063E 01
 0.10271E-01-0.27434E 00 0.21666E 01-0.66107E 01 0.68785E 01

L.FOR SECTOR 12

.77840F 00 0.11527E 01 0.35288E 02-0.17480E 03 0.22182E 03
 -0.76342F 02 0.17985E 04-0.14030E 05 0.42545E 05-0.44105E 05
 0.20250F 04-0.42130E 05 0.30792E 06-0.90193E 06 0.91599E 06
 -0.59751F 04 0.12239E 06-0.88812E 06 0.25911E 07-0.26251E 07
 0.44527F 04-0.90670E 05 0.65636E 06-0.19123E 07 0.19357E 07
 -0.44660F 00-0.17298E 00-0.45058E 02 0.20767E 03-0.25783E 03
 0.88554F 04-0.20480E 04 0.15874E 05-0.47977E 05 0.49641E 05
 -0.22545L 04 0.47416F 05-0.34579E 06 0.10116E 07-0.10266E 07
 0.66205E 04-0.13757E 06 0.99650E 07-0.29043E 07 0.29406E 07
 -0.49249L 04 0.10187E 06-0.73623E 06 0.21429E 07-0.21679E 07
 0.55408E-01 0.54787E 00 0.15125E 02-0.75561E 02 0.96118E 02
 -0.33302E 02 0.78033E 03-0.60924E 04 0.18482E 05-0.19164E 05
 0.85861E 03-0.18277E 05 0.13362E 06-0.39147E 06 0.39762E 06
 -0.25230F 04 0.53088E 05-0.38536E 06 0.11245E 07-0.11393E 07
 0.18771E 04-0.39329E 05 0.28478E 06-0.82981E 06 0.84006E 06
 .50972E-02-0.17989E 00-0.20299E 01 0.11411E 02-0.14977E 02
 .52359E 01-0.12488E 03 0.98349E 03-0.29964E 04 0.31147E 04
 -0.13791E 03 0.29648E 04-0.21740E 05 0.63796E 05-0.64863E 05
 0.40590L 03-0.86237E 04 0.62750E 05-0.18335E 06 0.18593E 06
 -0.30213E 03 0.63915E 04-0.46385E 05 0.13533E 06-0.13711E 06
 -0.92755E-03 0.15296E-01 0.96490E-01-0.62296E 00 0.84368E 00
 -0.29724L 00 0.72140E 01-0.57262E 02 0.17514E 03-0.18247E 03
 0.79974E 01-0.17331E 03 0.12742E 04-0.3 447E 04 0.38107E 04
 -0.23578F 02 0.50470E 03-0.36804E 04 0.10767E 05-0.10927E 05
 0.17559F 02-0.37421E 03 0.27212E 04-0.79483E 04 0.80584E 04
 0.33059F 01-0.60957E 02 0.29266E 03-0.60738E 03 0.46190E 03
 -0.12484F 03 0.15044E 04-0.60738E 04 0.97502E 04-0.49191E 04
 0.83918E 03-0.66757E 04 0.65187E 04 0.49966E 05-0.93529E 05
 -0.18069E 04 0.10950E 05 0.20520E 05-0.22433E 06 0.32953E 06
 0.11839F 04-0.60926E 04-0.24349E 05 0.18378E 06-0.25623E 06
 -0.39567E 01 0.66545E 02-0.31898E 03 0.66077E 03-0.50144E 03
 0.13326E 03-0.16223E 04 0.64740E 04-0.10169E 05 0.48774E 04
 -0.87305E 03 0.69072E 04-0.43038E 04-0.62834E 05 0.11055E 06
 0.18590E 04-0.10914E 05-0.30036E 05 0.26732E 06-0.38253E 06
 -0.12118E 04 0.59088F 04 0.32026E 05-0.21661E 06 0.29596E 06
 0.16723F 01-0.26672E 02 0.12792E 03-0.26515E 03 0.20136E 03
 -0.53220E 02 0.65382E 03-0.26224E 04 0.41583E 04-0.20399E 04
 .34962F 03-0.28846F 04 0.25582E 04 0.22770E 05-0.41872E 05
 -0.74662E 03 0.47339E 04 0.94751E 04-0.99739E 05 0.14587E 06
 0.48758E 03-0.26424E 04-0.10885E 05 0.81188E 05-0.11296E 06
 -0.29488E 00 0.45527E 01-0.21852E 02 0.45338E 02-0.34468E 02
 0.91028E 01-0.11245E 03 0.45413E 03-0.72933E 03 0.36833E 03
 -0.60391E 02 0.51866E 03-0.62557E 03-0.33385E 04 0.65939E 04
 0.12977E 03-0.88839E 03-0.10429E 04 0.15363E 05-0.23225E 05
 -0.85036E 02 0.51193E 03 0.14235E 04-0.12603E 05 0.18018E 05
 0.18494E-01-0.27951E 00 0.13423E 01-0.27867E 01 0.21201E 01
 -0.56049E 00 0.69418E 01-0.28171E 02 0.45645E 02-0.23506E 02
 0.37563E 01-0.33219E 02 0.48260E 02 0.17645E 03-0.37609E 03
 -0.81206E 01 0.58818E 02 0.33575E 02-0.85536E 03 0.13375E 04
 .53389E 01-0.34689E 02-0.64224E 02 0.70697E 03-0.10391E 04

-0.32992E 01 0.-535 2E 02-0.27119E 03 0.59748E 03-0.48472E 03
 0.13549E 03-0.19442E 04 0.10155E 05-0.23121E 05 0.19376E 05
 -0.13980E 04 0.20069E 05-0.10932E 06 0.25916E 06-0.22538E 06
 0.35243E 04-0.50660E 05 0.27930E 06-0.66953E 06 0.58794E 06
 -0.24780E 04 0.35657E 05-0.19766E 06 0.47618E 06-0.41996E 06
 0.37310E 01-0.58409E 02 0.29563E 03-0.61136E 03 0.52846E 03
 -0.14666E 03 0.21212E 04-0.11083E 05 0.25243E 05-0.21161E 05
 0.15040E 04-0.21951E 05 0.11968E 06-0.28400E 06 0.24719E 06
 -0.37859E 04 0.55468E 05-0.30618E 06 0.73477E 06-0.64585E 06
 0.26605E 04-0.39063E 05 0.21683E 06-0.52298E 06 0.46171E 06
 -0.15264E 01 0.23308E 02-0.11789E 03 0.2 955E 03-0.21043E 03
 0.58208E 02-0.84310E 03 0.43966E 04-0.99936E 04 0.83618E 04
 -0.59186E 03 0.86931E 04-0.47271E 05 0.11189E 06-0.97174E 05
 0.14867E 04-0.21952E 05 0.12084E 06-0.28928E 06 0.25373E 06
 -0.10439E 04 0.15456E 05-0.85564E 05 0.20588E 06-0.18138E 06
 0.26398E 00-0.39640E 01 0.20032E 02-0.44063E 02 0.35689E 02
 -0.98601E 01 0.14264E 03-0.74192E 03 0.16820E 04-0.14039E 04
 0.99476E 02-0.14634E 04 0.79290E 04-0.1 705E 05 0.16196E 05
 -0.24939E 03 0.36915E 04-0.20246E 05 0.48304E 05-0.42245E 05
 0.17498E 03-0.25984E 04 0.14331E 05-0.34367E 05 0.30191E 05
 -0.16357E-01 0.24276E 00-0.12257E 01 0.26934E 01-0.21793E 01
 0.60191E 00-0.86872E 01 0.45061E 02-0.10188E 03 0.84800E 02
 -0.60321E 01 0.88678E 02-0.47864E 03 0.11251E 04-0.97111E 03
 0.15098E 02-0.22345E 03 0.12207E 04-0.29021E 04 0.25301E 04
 -0.10587E 02 0.15723E 03-0.86377E 03 0.20641E 04-0.18077E 04
 0.13661E 01-0.20843E 02 0.10607E 03-0.23506E 03 0.19182E 03
 -0.53752E 02 0.78131E 03-0.41447E 04 0.95818E 04-0.81450E 04
 0.56394E 03-0.83483E 04 0.46488E 05-0.11243E 06 0.99471E 05
 -0.14272E 04 0.21242E 05-0.11981E 06 0.29304E 06-0.26173E 06
 0.10046E 04-0.14988E 05 0.85000E 05-0.20888E 06 0.18730E 06
 -0.15189E 01 0.22727E 02-0.11569E 03 0.25646E 03-0.20935E 03
 0.58450E 02-0.85380E 03 0.45335E 04-0.10490E 05 0.89250E 04
 -0.61067E 03 0.91521E 04-0.51044E 05 0.12362E 06-0.10950E 06
 0.15438E 04-0.23310E 05 0.13171E 06-0.32262E 06 0.28851E 06
 -0.10862E 04 0.16456E 05-0.93491E 05 0.23010E 06-0.20659E 06
 0.61461E 00-0.90659E 01 0.46119E 02-0.10216E 03 0.83337E 02
 -0.23229E 02 0.33927E 03-0.17982E 04 0.41537E 04-0.35282E 04
 0.24084E 03-0.36223E 04 0.20153E 05-0.4 702E 05 0.43060E 05
 -0.60766E 03 0.92181E 04-0.51952E 05 0.12698E 06-0.11335E 06
 0.42721E 03-0.65054E 04 0.36866E 05-0.90539E 05 0.81143E 05
 -0.10556E 00 0.15416E 01-0.78355E 01 0.17341E 02-0.14132E 02
 0.39365E 01-0.57389E 02 0.30344E 03-0.69923E 03 0.59262E 03
 -0.40514E 02 0.60935E 03-0.33786E 04 0.81398E 04-0.71782E 04
 0.10203E 03-0.15487E 04 0.86974E 04-0.21193E 05 0.18870E 05
 -0.71675E 02 0.10924E 04-0.61688E 04 0.15104E 05-0.13502E 05
 0.65123E-02-0.94425E-01 0.47950E 00-0.10602E 01 0.86319E 00
 -0.24039E 00 0.34962E 01-0.18439E 02 0.42387E 02-0.35841E 02
 0.24581E 01-0.36916E 02 0.20397E 03-0.48986E 03 0.43082E 03
 -0.61801E 01 0.93700E 02-0.52431E 03 0.12735E 04-0.11309E 04
 0.43387E 01-0.66062E 02 0.37169E 03-0.9 717E 03 0.80885E 03

-0.254835 00 0.37512E 01-0.19039E 02 0.42070E 02-0.34231E 02
 0.95851E 01-0.13817E 03 0.72715E 03-0.1 678E 04 0.14073E 04
 -0.98051E 02 0.14425E 04-0.79313E 04 0.18964E 05-0.16614E 05
 0.24634E 03-0.36454E 04 0.20283E 05-0.49018E 05 0.43340E 05
 -0.17282E 03 0.25642E 04-0.14339E 05 0.34808E 05-0.30893E 05
 0.28125E 00-0.40911E 01 0.20769E 02-0.45908E 02 0.37365E 02
 -0.10443E 02 0.15100E 03-0.79536E 03 0.18259E 04-0.15420E 04
 0.10649E 03-0.15809E 04 0.87053E 04-0.20843E 05 0.18282E 05
 -0.26731E 03 0.39987E 04-0.22286E 05 0.53937E 05-0.47749E 05
 0.18748E 03-0.28138E 04 0.15762E 05-0.38321E 05 0.34055E 05
 -0.11327E 00 0.16328E 01-0.82848E 01 0.1 302E 02-0.14888E 02
 0.41572E 01-0.60075E 02 0.31596E 03-0.72428E 03 0.61081E 03
 -0.42131E 02 0.62672E 03-0.34436E 04 0.82285E 04-0.72050E 04
 0.10558E 03-0.15839E 04 0.88071E 04-0.21272E 05 0.18799E 05
 -0.73996E 02 0.11142E 04-0.62270E 04 0.15108E 05-0.13403E 05
 0.19399E-01-0.27782E 00 0.14087E 01-0.31097E 01 0.25276E 01
 -0.70559E 00 0.10178E 02-0.53423E 02 0.12221E 03-0.10287E 03
 0.71073E 01-0.10566E 03 0.57879E 03-0.13792E 04 0.12047E 04
 -0.17782E 02 0.26670E 03-0.14782E 04 0.35602E 04-0.31386E 04
 ,12454E 02-0.18752E 03 0.10446E 04-0.25272E 04 0.22365E 04
 -0.11947E-02 0.17028E-01-0.86281E-01 0.19032E 00-0.15458E 00
 0.43148E-01-0.62114E 00 0.32535E 01-0.74276E 01 0.62399E 01
 -0.43231E 00 0.64163E 01-0.35038E 02 0.83255E 02-0.72541E 02
 0.10800E 01-0.16176E 02 0.89361E 02-0.21459E 03 0.18870E 03
 -0.75599E 00 0.11368E 02-0.63115E 02 0.15224E 03-0.13439E 03
 0.17828E-01-0.25661E 00 0.12977E 01-0.28566E 01 0.23151E 01
 -0.64772E 00 0.92344E 01-0.48063E 02 0.10902E 03-0.91027E 02
 0.64386E 01-0.93497E 02 0.50491E 03-0.11873E 04 0.10249E 04
 -0.16041E 02 0.23421E 03-0.12780E 04 0.30344E 04-0.264215 04
 0.11212E 02-0.16411E 03 0.89947E 03-0.21444E 04 0.18739E 04
 -0.19625E-01 0.28025E 00-0.14176E 01 0.31210E 01-0.25300E 01
 0.70712E 00-0.10100E 02 0.52608E 02-0.11942F 03 0.99775E 02
 -0.70121E 01 0.10249E 03-0.55417E 03 0.13046E 04-0.11274E 04
 ,17457F 02-0.25692E 03 0.14039E 04-0.33375E 04 0.29093E 04
 -0.12199E 02 0.18008E 03-0.98843E 03 0.23596E 04-0.20644E 04
 0.78893E-02-0.11197E 00 0.56616E 00-0.12460E 01 0.10096E 01
 -0.28205E 00 0.40256E 01-0.20942E 02 0.47480E 02-0.39624E 02
 0.27832E 01-0.40727E 02 0.21978E 03-0.51648E 03 0.44560E 03
 -0.69197E 01 0.10201E 03-0.55627E 03 0.13199E 04-0.11487E 04
 0.48327E 01-0.71480E 02 0.39152E 03-0.93285E 03 0.81476E 03
 -0.13477E-02 0.19071E-01-0.96376E-01 0.21198E 00-0.17166E 00
 0.47951E-01-0.68337E 00 0.35492E 01-0.80335E 01 0.66936E 01
 -0.47093E 00 0.68851E 01-0.37058E 02 0.8 868E 02-0.74781E 02
 0.11692E 01-0.17227E 02 0.93672E 02-0.22169E 03 0.19248E 03
 -0.81614E 00 0.12066E 02-0.65896E 02 0.1 659E 03-0.13645E 03
 0.83062E-04-0.11699E-02 0.59089E-02-0.12989E-01 0.10513E-01
 -0.29366E-02 0.41781E-01-0.21664E 00 0.48955E 00-0.40724E 00
 0.28719E-01-0.41924E 00 0.22505E 01-0.52622E 01 0.45197E 01
 -0.71221E-01 0.10478E 01-0.56813E 01 0.13410E 02-0.11616E 02
 0.49689E-01-0.73356E 00 0.39946E 01-0.94669E 01 0.82298E 01

-0.29831E 03 0.62281E 04-0.43532E 05 0.12427E 06-0.12420E 06
 0.35980E 05-0.74921E 06 0.52423E 07-0.14974E 08 0.14972E 08
 -0.63526E 06 0.13233E 08-0.92614E 08 0.26458E 09-0.26456E 09
 0.17794E 07-0.37070E 08 0.25944E 09-0.74118E 09 0.74112E 09
 -0.13010E 07 0.27105E 08-0.18970E 09 0.53194E 09-0.54189E 09
 0.34595E 03-0.72119E 04 0.50413E 05-0.14392E 06 0.14384E 06
 -0.41578E 05 0.86582E 06-0.60584E 07 0.17306E 08-0.17303E 08
 0.72623E 06-0.15128E 08 0.10587E 09-0.30246E 09 0.30243E 09
 -0.20307E 07 0.42303E 08-0.29607E 09 0.84581E 09-0.84574E 09
 0.14838E 07-0.30911E 08 0.21634E 09-0.61804E 09 0.61798E 09
 -0.14133E 03 0.29441E 04-0.20580E 05 0.58752E 05-0.58722E 05
 0.16924E 05-0.35242E 06 0.24660E 07-0.70442E 07 0.70431E 07
 -0.29130E 06 0.60678E 07-0.42466E 08 0.12132E 09-0.12131E 09
 0.81258E 06-0.16927E 08 0.11847E 09-0.33844E 09 0.33841E 09
 -0.59321E 06 0.12357E 08-0.86486E 08 0.24707E 09-0.24705E 09
 0.24598E 02-0.51221E 03 0.35807E 04-0.10223E 05 0.10217E 05
 -0.29346E 04 0.61109E 05-0.42760E 06 0.12215E 07-0.12213E 07
 0.49635E 05-0.10339E 07 0.72357E 07-0.20671E 08 0.2n669E 08
 -0.13805E 06 0.28757E 07-0.20127E 08 0.57498E 08-0.57494E 08
 0.10067E 06-0.20971E 07 0.14677E 08-0.41930E 08 0.41926E 08
 -0.15569E 01 0.32412E 02-0.22659E 03 0.64691E 03-0.64660E 03
 0.18501E 03-0.38527E 04 0.26959E 05-0.77009E 05 0.76999E 05
 -0.30685E 04 0.63914E 05-0.44731E 06 0.12779E 07-0.12778E 07
 0.85061E 04-0.17718E 06 0.12401E 07-0.35427E 07 0.35424E 07
 -0.61951E 04 0.12905E 06-0.90316E 06 0.25802F 07-0.25800E 07
 0.67736E 03-0.14093E 05 0.98464E 05-0.28101E 06 0.28081E 06
 -0.81070E 05 0.16874E 07-0.11806E 08 0.33721E 08-0.33714E 08
 0.14056E 07-0.29270E 08 0.20483E 09-0.58514E 09 0.58508E 09
 -0.39265E 07 0.81767E 08-0.57223E 09 0.16347E 10-0.16345E 10
 0.28682F 07-0.59728E 08 0.41800E 09-0.11941E 10 0.11940E 10
 -0.78967E 03 0.16422F 05-0.11475E 06 0.32752E 06-0.32730E 06
 0.94256E 05-0.19621E 07 0.13728E 08-0.39210E 08 0.39203E 08
 -0.16144E 07 0.33618E 08-0.23527E 09 0.67208E 09-0.67201E 09
 0.45007E 07-0.93726E 08 0.65593E 09-0.18738E 10 0.18736E 10
 -0.32851E 07 0.68413E 08-0.47878E 09 0.13678E 10-0.13676E 10
 0.32509E 03-0.67595E 04 0.47236E 05-0.13482E 06 0.13474E 06
 -0.38676E 05 0.80512E 06-0.56332E 07 0.16090E 08-0.16087E 08
 0.65169E 06-0.13571E 08 0.94972E 08-0.27131E 09 0.27128E 09
 -0.18119E 07 0.37732E 08-0.26407E 09 0.75437E 09-0.75430E 09
 0.13212F 07-0.27514E 08 0.19255E 09-0.55007E 09 0.55002E 09
 -0.57106E 02 0.11873E 04-0.82976E 04 0.23685E 05-0.23670E 05
 0.67694E 04-0.14092E 06 0.98601E 06-0.28164E 07 0.28159E 07
 -0.11190E 06 0.23302E 07-0.16307E 08 0.46585E 08-0.46580E 08
 0.31009E 06-0.64577E 07 0.45194E 08-0.12911E 09 0.12910E 09
 -0.22583E 06 0.47030E 07-0.32914E 08 0.94027E 08-0.94018E 08
 0.36511E 01-0.75911E 02 0.53057E 03-0.15145E 04 0.15136E 04
 -0.43116E 03 0.89762E 04-0.62806E 05 0.17940E 06-0.17937E 06
 0.69780E 04-0.14531E 06 0.10169E 07-0.29051E 07 0.29049E 07
 -0.19266E 05 0.40123E 06-0.28080E 07 0.80219E 07-0.80212E 07
 0.14012E 05-0.29180E 06 0.20422E 07-0.58341E 07 0.58335E 07
 -0.49423E 03 0.10271E 05-0.71754E 05 0.20476E 06-0.20460E 06
 0.59294E 05-0.12341E 07 0.86336E 07-0.24659E 08 0.24654E 08
 -0.10473E 07 0.21806E 08-0.15260E 09 0.43591E 09-0.43586E 09

0.29344E 07-0.61103E 08 0.42761E 09-0.12216E 10 0.12214E 10
 -0.21461E 07 0.44688E 08-0.31274E 09 0.89340E 09-0.89330E 09
 0.57225E 03-0.11891E 05 0.83077E 05-0.23709E 06 0.23691E 06
 -0.68504E 05 0.14258E 07-0.99756E 07 0.2*493E 08-0.28487E 08
 0.11970E 07-0.24924E 08 0.17442E 09-0.49826E 09 0.49820E 09
 -0.33482E 07 0.69721E 08-0.48793E 09 0.13939E 10-0.13937E 10
 0.24471E 07-0.50958E 08 0.35662E 09-0.10188E 10 0.10187E 10
 -0.23353E 03 0.48523E 04-0.33903E 05 0.96757E 05-0.96689E 05
 0.27875E 05-0.58021E 06 0.40594E 07-0.11595E 08 0.11592E 08
 -0.48000E 06 0.99450E 07-0.69946E 08 0.19981E 09-0.19979E 09
 0.13305E 07-0.27894E 08 0.19521E 09-0.55766E 09 0.55760E 09
 -0.77814E 06 0.20369E 08-0.14255E 09 0.40723E 09-0.40719E 09
 0.40613E 02-0.84386E 03 0.58965E 04-0.16829E 05 0.16817E 05
 -0.46517E 04 0.10057E 06-0.70367E 06 0.20099E 07-0.20095E 07
 0.81766E 05-0.17026E 07 0.11915E 08-0.31038E 08 0.34034E 08
 -0.22752E 06 0.47380E 07-0.33158E 08 0.94724E 08-0.94715E 08
 0.16597E 06-0.34562E 07 0.24188E 08-0.69098E 08 0.69091E 08
 -0.25687E 01 0.53375E 02-0.37298E 03 0.10646E 04-0.10639E 04
 0.30450E 03-0.63385E 04 0.44348E 05-0.12667E 06 0.12665E 06
 -0.50533E 04 0.10523E 06-0.73639E 06 0.21036E 07-0.21034E 07
 0.14015E 05-0.29186E 06 0.20425E 07-0.58350E 07 0.58344E 07
 -0.10211E 05 0.21264E 06-0.14881E 07 0.42511E 07-0.42507E 07
 0.16788E 03-0.34858E 04 0.24345E 05-0.69460E 05 0.69399E 05
 -0.20195E 05 0.42026E 06-0.29400E 07 0.83968E 07-0.83947E 07
 0.36381E 06-0.75748E 07 0.53007E 08-0.15142E 09 0.15140E 09
 -0.10226E 07 0.21292E 08-0.14900E 09 0.42566E 09-0.42561E 09
 0.74873E 06-0.15590E 08 0.10910E 09-0.31167E 09 0.31163E 09
 -0.19294E 03 0.40061E 04-0.27981E 05 0.79840E 05-0.79773E 05
 0.23170E 05-0.48220E 06 0.33733E 07-0.96345E 07 0.96323E 07
 -0.41369E 06 0.86135E 07-0.60276E 08 0.17219E 09-0.17216E 09
 0.11612E 07-0.24179E 08 0.16920E 09-0.48336E 09 0.48331E 09
 -0.84975E 06 0.17694E 08-0.12383E 09 0.35374E 09-0.35370E 09
 0.77969E 02-0.16189E 04 0.11308E 05-0.32266E 05 0.32240E 05
 -0.93403E 04 0.19439E 06-0.13599E 07 0.38840E 07-0.38831E 07
 0.16472E 06-0.34298E 07 0.24001E 08-0.68562E 08 0.68554E 08
 -0.46146E 06 0.96090E 07-0.67245E 08 0.19210E 09-0.19208E 09
 0.33746E 06-0.70271E 07 0.49177E 08-0.14048E 09 0.14047E 09
 -0.13405E 02 0.27832E 03-0.19442E 04 0.55479E 04-0.55435E 04
 0.16011E 04-0.33322E 05 0.23312E 06-0.66583E 06 0.66568E 06
 -0.27818E 05 0.57923E 06-0.40534E 07 0.11579E 08-0.11578E 08
 0.77745E 05-0.16189E 07 0.11329E 08-0.32364E 08 0.32361E 08
 -0.56804E 05 0.11829E 07-0.82779E 07 0.23647E 08-0.23645E 08
 0.83708E 00-0.17382E 02 0.12143E 03-0.34651E 03 0.34624E 03
 -0.99661E 02 0.20742E 04-0.14511E 05 0.41447E 05-0.41438E 05
 0.17021E 04-0.35442E 05 0.24802E 06-0.70850E 06 0.70841E 06
 -0.47438E 04 0.98781E 05-0.69129E 06 0.19748E 07-0.19746E 07
 0.34624E 04-0.72100E 05 0.50457E 06-0.14414E 07 0.14412E 07
 -0.26379E 02 0.54725E 03-0.38205E 04 0.10898E 05-0.10887E 05
 0.31778E 04-0.66118E 05 0.46248E 06-0.13208E 07 0.13204E 07
 -0.58058E 05 0.12087E 07-0.84579E 07 0.24160E 08-0.24157E 08

0.16355E 06-0.34051E 07 0.23828E 08-0.68068E 08 0.68059E 08
 -0.11984E 06 0.24953E 07-0.17462E 08 0.49881E 08-0.49875E 08
 0.30152E 02-0.62553E 03 0.43674E 04-0.12459E 05 0.12447E 05
 -0.36273E 04 0.75473E 05-0.52794E 06 0.15077E 07-0.15073E 07
 0.65777E 05-0.13694E 07 0.95827E 07-0.27373E 08 0.27370E 08
 -0.18508E 06 0.38536E 07-0.26967E 08 0.77033E 08-0.77024E 08
 0.13557E 06-0.28228E 07 0.19753E 08-0.56428E 08 0.56421E 08
 -0.12095E 02 0.25093E 03-0.17521E 04 0.49984E 04-0.49935E 04
 0.14520E 04-0.30213E 05 0.21134E 06-0.60358E 06 0.60342E 06
 -0.26059E 05 0.54253E 06 0.37964E 07 0.10845E 08-0.10843E 08
 0.73205E 05-0.15242E 07 0.10666E 08-0.30470E 08 0.30466E 08
 -0.53590E 05 0.11159E 07-0.78087E 07 0.22306E 08-0.22303E 08
 0.20613E 01-0.42764E 02 0.29861E 03-0.85189E 03 0.85108E 03
 -0.24682E 03 0.51357E 04-0.35925E 05 0.10260E 06-0.10257E 06
 0.43732E 04-0.91050E 05 0.63713E 06-0.18200E 07 0.18197E 07
 -0.12261E 05 0.25529E 06-0.17165E 07 0.51033E 07-0.51027E 07
 0.69691E 04-0.18676E 06 0.13069E 07-0.37333E 07 0.37328E 07
 -0.12745E 00 0.26442E 01-0.18464E 02 0.52679E 02-0.52630E 02
 0.15216E 02-0.31662E 03 0.22149E 04-0.63256E 04 0.63240E 04
 -0.26962E 03 0.55303E 04-0.38698E 05 0.11054E 06-0.11053E 06
 0.74296E 03-0.15470E 05 0.10825E 06-0.30924E 06 0.30920E 06
 -0.54301E 03 0.1137E 05-0.79123E 05 0.22602E 06-0.22600E 06
 0.15410E 01-0.31934E 02 0.22283E 03-0.63544E 03 0.63466E 03
 -0.18563E 03 0.38612E 04-0.27005E 05 0.77116E 05-0.77090E 05
 0.34228E 04-0.71252E 05 0.49855E 06-0.14240E 07 0.14238E 07
 -0.96554E 04 0.20101E 06-0.14066E 07 0.40179E 07-0.40172E 07
 0.70790E 04-0.14738E 06 0.10313E 07-0.29459E 07 0.29455E 07
 -0.17547E 01 0.36367E 02-0.25378E 03 0.72375E 03-0.72290E 03
 0.21114E 03-0.43921E 04 0.30719E 05-0.87723E 05 0.87695E 05
 -0.38685E 04 0.80531E 05-0.56348E 06 0.16095E 07-0.16093E 07
 0.10902E 05-0.22697E 06 0.15882E 07-0.45368E 07 0.45362E 07
 -0.79903E 04 0.16636E 06-0.11641E 07 0.33253E 07-0.33248E 07
 0.70033E 00-0.14515E 02 0.10129E 03-0.28888E 03 0.28855E 03
 -0.84116E 02 0.17498E 04-0.12238E 05 0.34949E 05-0.34937E 05
 0.15274E 04-0.31796E 05 0.22248E 06-0.63549E 06 0.63538E 06
 -0.42985E 04 0.89493E 05-0.62623E 06 0.17888E 07-0.17886E 07
 0.31489E 04-0.65560E 05 0.45876E 06-0.13105E 07 0.13103E 07
 -0.11862E 00 0.24584E 01-0.17157E 02 0.48932E 02-0.48875E 02
 0.14214E 02-0.29569E 03 0.20681E 04-0.59060E 04 0.59041E 04
 -0.25924E 03 0.53135E 04-0.37179E 05 0.10620E 06-0.10618E 06
 0.71712E 03-0.14930E 05 0.10447E 06-0.29842E 06 0.29838E 06
 -0.52499E 03 0.10930E 05-0.76486E 05 0.21848E 06-0.21845E 06
 0.72821E-02-0.15093E 00 0.10534E 01-0.30044E 01 0.30010E 01
 -0.87037E 00 0.18106E 02-0.12664E 03 0.36165E 03-0.36153E 03
 0.15425E 02-0.32111E 03 0.22468E 04-0.64179E 04 0.64169E 04
 -0.43249E 02 0.90043E 03-0.63007E 04 0.17998E 05-0.17995E 05
 0.31638E 02-0.65871E 03 0.46094E 04-0.13167E 05 0.13165E 05
 -0.14085E-04 0.19016E-03-0.12303E-02 0.3*413E-02-0.32297E-02
 0.10670E-02-0.18812E-01 0.12837E 00-0.36110E 00 0.35748E 00
 -0.18961E-01 0.36327E 00-0.25132E 01 0.71299E 01-0.70977E 01
 0.53564E-01-0.10381E 01 0.71948E 01-0.20434E 02 0.20356E 02
 -0.39368E-01 0.76610E 00-0.53132E 01 0.15096E 02-0.15042E 02




FIG. 3.1 APPROXIMATIONS FOR THE ELLIPTIC INTEGRALS
IN REFERENCE NO. 6.




FIG. 3.2 DEFLECTION CONTOURS FOR A SINGLE CONCENTRATED LOAD AT FIRST RADIAL POSITION FOR $D=0.1$ AND $u=1$




FIG. 3-3 DEFLECTION CONTOURS FOR A SINGLE LOAD AT SECOND RADIAL POSITION FOR $\bar{D} = .01$ AND $\mu = 2$




FIG. 3-4 DEFLECTION CONTOURS FOR A SINGLE LOAD AT
THIRD RADIAL POSITION FOR $\delta = .01$ AND $N = 2$




FIG. 3.5 DEFLECTION CONTOURS FOR A SINGLE LOAD AT
FOURTH RADIAL POSITION FOR $D = .01$ AND $H = .2$




FIG. 3-6 DEFLECTION CONTOURS FOR A SINGLE CONCENTRATED LOAD AT FIFTH RADIAL POSITION FOR $D=0.1$ AND $M=2$





FIG. 3.7 DEFLECTION CONTOURS FOR A SINGLE CONCENTRIC LOAD AT SIXTH RADIAL POSITION FOR $D=0.1$ AND $L=1$



● LOAD POSITIONS

FIG. 3.8 DEFLECTION CONTOURS FOR SIX CONCENTRATED LOAD ON FIFTH PITCH CIRCLE FOR $\bar{D} = .01$




FIG. 3-9 DEFLECTION CONTOURS FOR RADIAL LINE LOAD
FOR $\bar{D} = 0.01 \mu = 2$






FIG. 3.10. DEFLECTION CONTOURS FOR A DIAMETRAL LINE LOAD FOR $D=0.1$ AND $\mu=2$

Centre of plate

$$\bar{D} = .16$$

$$\mu = .35$$

Six equally spaced concentrated loads of 9 LBS, fifth pitch circle
Curves are for sector 3

— Present analysis
- - - Experimental⁶
— Theoretical analysis of
Ghosh and Chatterjee⁶

Distance along radius (ρ) →





FIG. 3-II COMPARISON OF THE RESULTS



CHAPTER IV

CONCLUSIONS

4.1 Relative Merits of the Proposed Method Over the Conventional Design Methods

The difficulty in presenting a rationalised design procedure for a circular raft lies in the proper assessment of intensity and distribution of contact pressure below the slab. Due to unpredictable behaviour of natural soils, as well as, the occurrence of different local conditions, the characteristics of the different element in a particular raft foundation problem are the essential requirements for design.

The conventional design procedures followed so far are not based on any sound basis and so the designer has to be guided by some ill-defined rules.

A solution of the problem has been presented by Hanna and Dawood¹², in which they have treated the raft by plate theory, assuming a uniform contact pressure distribution. The settlement of the soil is assumed to be axysymmetric. They have assumed

differential settlement of flexible raft to occur due to compaction of elastic soil mass below the raft foundation.

Two more recent works, one by Smith and Zar³¹ and the other by Chu and Afandani⁸, have detailed design procedures, applying thin plate theory. The first of these works deals with piled and raft foundations for chimneys. This method, though a valuable contribution to practical design aspects, is not theoretically justifiable. The solution is obtained for the raft foundation by superimposing the two loading cases of axially symmetrical ring loads and uniformly distributed loads on slabs, simply supported along edges. This design procedure is valid if the load is a ring load and it is symmetrically placed about the vertical axis through the centre of the raft, and the slab is simply supported by the chimney. In their work Chu and Afandani⁸ have assumed a linear reactive pressure variation below the raft. Solutions are obtained considering this linear reactive pressure as the load on the circular raft, simply supported or fixed at the chimney wall. They have supplied a series of curves for different cases considered. This design procedure is also valid for only a ring loading case.

In a more recent work by Chatterjee and Ghosh⁶, a more rationalised design procedure has been arrived at. But their design procedure is valid only for six equally spaced concentrated loads and concentric loading case. The design procedure described in the present analysis is a generalisation of this work.

As in the case of Chatterjee and Ghosh⁶, the main merit of the present method is that it does not assume the nature of contact pressure distribution. Equations are formulated eliminating this unknown pressure distribution from the condition of equilibrium and compatibility of the forces and deflected shape of the plate and the subgrade surface. The contact pressure distribution is a function of the rigidity of the plate and the properties of the plate and the subgrade material. This when assumed to be uniform or in linear variation is bound to set a major limitation to the validity of any suggested method. The main advantage of the present method over that of Chatterjee and Ghosh⁶ is that this work is perfectly general and may be used for any type of particular loading case by proper superposition as shown in Examples I through X in the Chapter III. Another advantage of the method is that all the quantities are non-dimensional. And so by using this method solutions can be obtained for any plate dimension and any type of plate and subgrade material.

4.2 Conclusions

Based on this work involving analysis of circular elastic plates on elastic foundation several important conclusions can be drawn. These are as follows:

i) For a single concentrated load of a particular magnitude the maximum deflection is dependent on the load position and this maximum deflection becomes a minimum when the load is applied at the

fifth radial position for small values of \bar{D} and at fourth radial position for moderate and larger values of \bar{D} . The same phenomenon takes place in case of the moments also.

ii) Very good agreement between the experimental results and the results obtained by the present method is observed.

iii) With the help of the Polynomial Co-efficients and the program given in section 3.4, solution for circular plates of any dimension and material on any type of subgrade can be obtained for any type of loading with the help of a small computer. Even desk calculators can be used to get the solution.

iv) In case of Winkler type subgrade the same method of solution can be obtained much more easily by the present method of solution with the following modifications:

$\gamma(I, J, K) = 1$ for $I = J$ and $K = 1$ and all other $\gamma(I, J, K)$'s are zero,

and $\frac{(1-\nu^2)}{R E_s \lambda \delta}$ is replaced by the reciprocal of the subgrade modulus.

REFERENCES

1. Atsushi Saito, "Bending of Circular Plate on Elastic Foundation Loaded over Concentric or Eccentric Circular Domain", Proceedings of 8th Japan National Congress for Applied Mechanics, 1958.
2. Atsushi Saito, Chao Chin Lin, "Bending of Circular Plates on an Elastic Foundation Under Radially Distributed Load", Proceedings of the 10th Japan National Congress for Applied Mechanics, 1960.
3. D.K. Bazaj and J.H. Kissel, "Use of Polar Finite Difference Approximation for Plates", Int. J. Mech. Sci., V.12, n1, Jan. 1970.
4. S.G. Bergstrom, "Circular plates on Elastic Foundation", Bulletin No.6, Swedish Cement and Concrete Research Inst., 1946.
5. R. Chatterjee, "Bending of Circular plate on Elastic Foundation", M.E. Thesis, Calcutta University, 1967.
6. R. Chatterjee and A. Ghosh, "Analysis of Circular Plates or Semi-infinite Elastic Subgrade", Indian J. of Tech., V.7, Oct. 1969.
7. Y.K. Cheung and O.C. Zienkiewicz, "Plates and Tanks on Elastic Foundation", Int. J. of Solids and Structures, V.1, Nov. 1965.
8. K.H. Chu and O.F. Afandani, "Analysis of Circular and Annular Slabs for Chimney Foundations", A.C.I. J., Dec. 1966.
9. A. Ralston, "A First Course in Numerical Analysis", McGraw Hill Book Co. Inc.
10. D.Q. Fletcher and L.R. Hermann, "Elastic Foundation Representation of Continuum", J. Engg. Mech. Div., A.S.C.E. Proc., V.70, Feb. 1971.
11. H.J. Fletcher and C.J. Thorne, "Thin Rectangular Plates on Elastic Foundation", J. Appl. Mech., A.S.M.E. Trans., V.19, Sept. 1952.
12. M.M. Hanna and H. Dawood, "Stresses in Circular Tank Floors and Walls Subjected to Settlement on Uniform Soils", Proc. Inst. of Civil Engineers, Jan. 1965.
13. A.H. Hausrath, "Small Deflection of Elastically Supported Plates", Proc. 9th Int. Congress for Appl. Mech., Univ. of Brussels, 1957.
14. M. Hetenyi, "Beams and Plates on Elastic Foundations and Related Problems", App. Mech. Review, V.19, 1966.
15. M. Hetenyi, "A General Solution for Beams on Elastic Foundation", J. Appl. Phys. V.21, n1., Jan. 1950.
16. M. Hetenyi, "Beams on Elastic Foundation", Univ. of Michigan Press.

17. A.H.A. Hogg, "Equilibrium of a Thin Plate Symmetrically Loaded Resting on an Elastic Foundation", Phil. Mag., 1938.
18. D.L. Holl, "Thin Plates on Elastic Foundations", Proc. 5th, Int. Congress of Appl. Mech., Cambridge, 1938.
19. K. Terzaghi, "Theoretical Soil Mechanics", John Wiley & Sons.
20. A.D. Kerr, "Elastic and Visco-elastic Foundation Models", J. Appl. Mech., A.S.M.E. Trans., V.31, Sept. 1964.
21. B.G. Korenov, "Structural Mechanics in U.S.S.R. , 1917-1957", Pergamon Press.
22. B.G. Korenov, "The Problems of Mechanics of Beams and Plates on Elastic Foundation", Proc. 9th Int. Congress for Appl. Mech., Univ. of Brussels, 1957.
23. H.C. Lee, "Plates on Generalised Elastic Foundation", Ph.D. Thesis, Stanford Univ., 1967.
24. R.K. Livesley, "Some Notes on Mathematical Theory of a Loaded Elastic Plate Resting on an Elastic Foundation", Quart. J. Mech. Appl. Math., V. 6, Pt. 1, 1953.
25. F.J. McCormick and Salvadori, "Numerical Methods in FORTRAN", Prentice Hall.
26. G. Pickett and S. Badruddin, "Influence Charts for Bending of Semi-infinite Pavement Slab", Proc. 9th Int. Congress for Appl. Mech., Univ. of Brussels, 1957.
27. G. Pickett and G.K. Roy, "Influence Charts for Concrete Pavements", A.S.C.E. Proc., 1951.
28. E. Reissner, "A Note on Deflections of Plates on a Viscoelastic Foundation", J. Appl. Mech., A.S.M.E. Trans., V. 80, 1958.
29. W.J. Rhines, "A Study of Reissner Foundation Model", Proc. 5th U.S. National Congress of App. Mech., 1966.
30. Salvadori and Baron, "Numerical Methods in Engineering", Prentice Hall.
31. J.W. Smith and M. Zar, "Chimney Foundations", A.C.I.J., June 1964.
32. S.P. Timoshenko and Goodier, "Theory of Elasticity", McGraw Hill Book Co. Inc.

33. S.P. Timoshenko and S.W. Krieger, "Theory of Plates and Shells", McGraw Hill Book Co. Inc.
34. G.C.K. Yeh, "Bending of Rectangular Plates on an Elastic Foundation", Proc. 2nd U.S. National Congress of Appl. Mech., 1954.
35. H.M. Westergaard, "New Formulae for Stresses in Concrete Pavement of Airfields", A.S.C.E. Proc., 1948.
36. E. Winkler, "Die Lehre von der Elasticitaet und Festigkeit", Prag Dominicus, 1867.

APPENDIX - ASelection of the Proper Sign in Equations (2.16) and (2.17)

While calculating r_I by using equation (2.16) three cases may arise,

- (i) The radius may, at some point on curve I, become tangential to curve I.
- (ii) The radius r_I makes an acute angle with a line joining any point on curve I to the centre of the plate, at that point.
- (iii) The radius of r_I makes an obtuse angle with a line joining any point on curve I to the centre of the plate, at that point.

Defining a the angle Ψ_{cr} as shown in Fig. A1 it is seen that in case I $(K+0.5)\lambda > \Psi_{cr}$ and $(K-0.5)\lambda < \Psi_{cr}$. In that case

while integrating $\int r_I d\theta$ from θ_T to θ_{cr} , where $\theta_{cr} = \frac{\lambda}{2} - \Psi_{cr}$
 $r_I = \delta \left[(J-0.5) \cos \theta - \sqrt{I^2 - (J-0.5)^2 \sin^2 \theta} \right]$ and while integrating from θ_{cr} to θ_T

$$r_I = \delta \left[(J-0.5) \cos \theta + \sqrt{I^2 - (J-0.5)^2 \sin^2 \theta} \right]$$

In case II $(K+0.5)\lambda \leq \Psi_{cr}$. In this case

$$r_I = \left[(J-0.5) \cos \theta - \sqrt{I^2 - (J-0.5)^2 \sin^2 \theta} \right] \delta$$




In case III $(K-0.5)\lambda \geq \Psi_{cr}$. In this case

$$r_I = \left[(J-0.5) \cos \theta + \sqrt{I^2 - (J-0.5)^2 \sin^2 \theta} \right] \delta$$

The above three cases are shown in Fig. A1.

From Fig. A1(a) $\Psi_{cr} = \cos^{-1} \left(\frac{I}{J-5} \right)$.

Exactly the same cases arise while determining r_{III} from equation (2.17). Here the only change is that I is replaced by (I-1) and θ_T and θ_S are replaced by θ_V and θ_U respectively.



APPENDIX BDetermination of Polynomial Equations

While determining the polynomial equations it is to be noted that the deflection of a point depends upon the co-ordinates of the point, the non-dimensional flexural rigidity \bar{D} , the Poisson's Ratio of the plate material, μ , and the position of the load. So a general polynomial will consist of all the above mentioned variables. So that the polynomial does not become unmanageably complicated different polynomials have been determined for the thirteen sectors. The polynomial equations are determined as described below.

The present method gives the deflections at discrete points of the plate and the load positions also being discrete. The discrete points in both the cases being the node points, which, as pointed out earlier, are the central point of each element. So instead of trying to fit a least square polynomial it has been attempted to determine a polynomial which will give the exact deflection at these discrete node points. In the present analysis six radial positions has been taken. Thus for a particular \bar{D} , μ and load position the deflection is assumed as,

$$w = \sum_{i=0}^{5} c_i r^i$$

where r is the radial position of the element under consideration.

By using this equation for the six different or six simultaneous equations are obtained. By solving these, C's are determined.

Next C's are determined for a particular \bar{D} and μ and for five different load positions. Next each of these C's are expressed as

$$C = \sum_{i=0}^4 B_i L^i$$

where L is the load position. The B's are numbered 1 to 30 such that 1 to 5 are for C_0 , 6 to 10 for C_1 and so on.

Next each of B's are expressed as,

$$B = \sum_{i=0}^4 E_i \bar{D}^i$$

E's are numbered 1 to 150 in the same fashion as B.

Next each of E's are expressed as,

$$E = \sum_{i=0}^4 F_i \mu^i$$

F's are numbered 1 to 750 such that 1 to 5 corresponds to E_1 , 6 to 10 corresponds to E_2 and so on.

Thus 750 coefficients for each sector are determined.

APPENDIX CComputer Programs

There are two computer programs. The first one is to calculate the deflections and moments of the various elements by using; the theoretical analysis method as described in section 2.4. The second program is used to determine the deflections of the various elements by using; the co-efficients of the polynomial equations as described in section 3.4. A brief description of the programs is given below:

Program No.1 : This program as pointed out previously calculates the deflections and moments for the various elements of the plate. The program is perfectly general in the sense that it can be used to find the deflections and moments for any number of divisions of the plate (i.e. grid size), with a few minor changes in the dimension cards as will be pointed out as and when they appear. The program has been divided into various subroutines. The description of each subroutine is given below.

MAIN Program : The main program reads the input quantities and calls the various subroutines. All the print statements are also in this routine.

The input quantities are \bar{D} , μ , number of sectors and number of radial divisions.

Subroutine GAMMA : This routine calculates the deflection co-efficients $\gamma(I, J, K)$ for the subgrade. In this program the first and third integrals of equation (2.25) are calculated by numerical integration using Simpson's Rule.

The input quantities in this program are the total number of sectors, number of radial divisions, number of sectors for which $\gamma(I, J, K)$ need to be calculated by using symmetry.

Subroutine TANINV : This subroutine is used to find out in which quadrants the angles θ_S , θ_T , θ_U , θ_V in equation (2.25) lies. This is needed because while calculating an angle from its tangent the computer gives the value in only two quadrants depending upon the sign of the tangent.

The input quantities are the numerator and denominator of the tangent.

Subroutine CHECK : This subroutine is used to get the proper sign of the parts under radical sign in equations (2.16) and (2.17) by using the method as described in Appendix A.

The input quantities are the radial positions of the two elements for which $\gamma(I, J, K)$ is being calculated and the difference in their angle K.

Subroutine SIMPSN : This subroutine is used to calculate the first and the third integrals in equations (2.25) by using Simpson's Rule of numerical integration using 50 divisions.

The input quantities are the limits of the integration. The function to be integrated is defined inside the routine.

Subroutine MATGEN : This subroutine generates the co-efficient matrix. First it calculates the co-efficients for all the elements and then group them together. In this routine the dimension of Q will be the total number of elements including the imaginary elements.

The input quantities are $\gamma(I, J, K)$, \bar{N} , μ , number of sectors and number of radial division.

Subroutine MATINV : This subroutine inverts the co-efficient matrix by using pivotal method of Gauss-Jordan²⁵. The inverse of the matrix is stored in the memory in the place of the matrix and the original matrix is destroyed. In this routine the dimensions for PIVOT and IPIVOT and the first dimension for INDEX will be equal to the total number of elements for which the deflection has to be calculated, including the imaginary elements.

The input to this routine is the co-efficient matrix and the order of the matrix.

Subroutine DFLCTN : This subroutine calculates the deflections of the various elements. In this routine the proper dimensions for $\gamma(I, J, K)$ has to be given in GAM and the dimension of BC, the vector on the right hand side of the set of simultaneous equations, is equal to the number of elements for which deflection has to be calculated.

The input quantities are the inverted co-efficient matrix, $\gamma(I, J, K)$, number of sectors, number of radial divisions,

number of elements for which deflection is to be calculated, including the imaginary elements.

Subroutine MOMMR : This subroutine calculates the non-dimensional moments \bar{M}_ϕ from the non-dimensional deflections \bar{w} .

The input quantities are the deflections, the total number of sectors and radial divisions, total number of elements for which \bar{M}_ϕ is to be calculated and the total number of elements for which deflection has been calculated.

Subroutine MOMMT : This subroutine calculates the non-dimensional moments \bar{M}_θ from the non-dimensional deflections \bar{w} .

The input quantities are the same as routine MOMMR.

Program No. 2 : As pointed out earlier this program is used to calculate the deflections of the various elements by using the polynomial equations. The method used in this program is nothing but just the inverse of the method used to determine the polynomial equations as described in Appendix B. Here the co-efficient F's for the particular sector is given as an input quantity. The program first calculates the co-efficients E's. After that it calculates the co-efficients B's and finally the co-efficients C's. From C's it calculates the deflections \bar{w} 's.

The input quantities are \bar{D}_μ , the proper set of F, the radial position of the particular element, the position of the load.

A listing of both the programs is given in the next few pages.

COMPUTER PROGRAM NO. 1

```

BFTC MAIN
INTEGER RADIAL
REAL MR
REAL MT
DIMENSION MT(78),MR(78)
DIMENSION RADIAL(8)
DIMENSION C(104,104),GAM(10,6,24),BC(104),W(104)
DIMENSION O(192)

*****N1=TOTAL NO OF SECTORS
N2=TOTAL NO OF RADIAL DIVISIONS
N3=NO OF SECTORS FOR WHICH CALCULATIONS OF GAM. IS NEEDED
N4=NO OF SECTORS FOR WHICH CALCULATION OF W IS NEEDED
N5=N2+2
N6=N5*N4
N7=NO OF ELEMENTS FOR WHICH MR AND MT IS TO BE CALCULATED
N8=NO OF ELEMENTS FOR WHICH DEFLECTION IS TO CALCULATED
DB= $\bar{D}$ 
AMU= $\mu$ 
*****05 FORMAT(50X,*ANALYSIS FOR LOAD AT RADIAL POSITION NO =*,I2,/50X,
140(1H-))
06 FORMAT(/////////62X,*THE DEFLECTIONS ARE*,/62X,19(1H-))
08 FORMAT(/////////62X,*MOMENTS MRHO ARE*,/62X,19(1H-))
10 FORMAT(/////////62X,*MOMENTS MTHETA ARE*,/62X,19(1H-))
09 FORMAT(16X,102(1H-))
08 FORMAT(7X,8(2X,*POSITION=*,I2,2X))
14 FORMAT(1X,6E13.6)
08 FORMAT(7X,*SECTOR=*,I3,1X,8E4.7)
17 FORMAT(24X,*MOMENT MTHETA*)
15 FORMAT(20X,18(1H-))
16 FORMAT(23X,34(1H-),/23X,*FOR LOAD AT RADIAL POSITION NO=*,I3,/23X,
134(1H-))
03 FORMAT(1H1)
04 FORMAT(////48X,*ANALYSIS FOR DB=*,F6.3,*AND MU=*,F6.3,/48X,35(1H*..)
1)
12 FORMAT(20X,*DB=*,F6.3,*MU=*,F6.3)
2 FORMAT(2F5.2)
READ2,DB,AMU
PRINT403
PRINT404,DB,AMU
PRINT403
CALL GAMMA(6,13,10,24,GAM)

```

```

DO 1 J=1,6
DO 1 I=1,8
DO 1 K=14,24
IK=26-K
GAM(I,J,K)=GAM(I,J,IK)
CONTINUE
1 CALL MATGEN(6,8,13,24,104,GAM,C,DB,AMU)
CALL MATINV(C,104,104)
II=1
IV=1
DO 111 L=1,8
RADIAL(L)=L
111 CONTINUE
DO 43 IJKL=1,6
PRINT405,IT
CALL DFLCTN(C,GAM,6,13,104,8,W)
DO 106 J=1,6
DO 106 N=1,13
JN=(J-1)*13+N
NJ=(N-1)*6+J
BC(NJ)=W(JN)
106 CONTINUE
PRINT406
PRINT300
PRINT108,(RADIAL(L),L=1,8)
PRINT300
JJ=1
DO 46 K=1,13
JJJ=JJ+7
KK=JJJ-2
PRINT48,K,(BC(KL),KL=JJ,KK)
PRINT300
JJ=JJ+8
46 CONTINUE
PRINT403
CALL MOMMR(W,6,13,104,78,MR)
DO 424 J=1,6
DO 424 N=1,13
JN=(J-1)*13+N
NJ=(N-1)*6+J
BCM(NJ)=MR(JN)
424 CONTINUE
PRINT408
PRINT300
PRINT300
JJ=1
DO 426 K=1,13
JJJ=JJ+5
PRINT48,K,(BCM(KL),KL=JJ,JJJ)
PRINT300
JJ=JJ+6
426 CONTINUE

```

```

PRINT403
CALL MOMMT(W,6,13,104,78,MT)
DO 425 J=1,6
DO 425 N=1,13
JN=(J-1)*13+N
NJ=(N-1)*6+J
BCM(NJ)=MT(JN)
425 CONTINUE
PRINT410
PRINT300
PRINT108,(RADIAL(L),L=1,8)
PRINT300
PRINT300
JJ=1
DO 427 K=1,13
JJJ=JJ+5
PRINT48,K,(BCM(KL),KL=JJ,JJJ)
PRINT300
JJ=JJ+6
427 CONTINUE
PRINT403
II=II+1
43 CONTINUE
STOP
END

```

```

$IB+TC  SUB1
SUBROUTINE TANINV(A,B,C)
PI=4.*ATAN(1.)
IF(B.EQ..0) GO TO 1
C=ATAN(ABS(A/B))
IF(A) 2,3,3
3 IF(B) 4,5,5
5 GO TO 6
4 C=PI-C
GO TO 6
2 IF(B) 7,8,8
8 C=-C
GO TO 6
7 C=PI+C
GO TO 6
1 IF(A.GE..0) C=PI/2.
IF(A.LT..0) C=3.*PI/2.
6 RETURN
END

```

```

IBFTC GAMMA
SUBROUTINE GAMMA(N2,N4,N5,N1,GAM)
DIMENSION GAM(N5,N2,N1)
PI=4.*ATAN(1.)
AL=2.*PI/FLOAT(N1)
DO 1 I=1,N2
DO 1 J=1,N2
DO 1 K=1,N4
A=FLOAT(I)
FI=A
B=FLOAT(J)-.5
Z=FLOAT(I)-1.
D=FLOAT(K)-1.
AA=A*SIN((D-.5)*AL)
BB=B-A*COS((D-.5)*AL)
CC=Z*SIN((D-.5)*AL)
DD=B-Z*COS((D-.5)*AL)
EE=A*SIN((D+.5)*AL)
FF=B-A*COS((D+.5)*AL)
GG=Z*SIN((D+.5)*AL)
HH=B-Z*COS((D+.5)*AL)
CALL TANINV(AA,BB,TS)
CALL TANINV(CC,DD,TV)
CALL TANINV(EE,FF,TT)
CALL TANINV(GG,HH,TU)
E(G,T1,T2)= ALOG(TAN((G*AL+T1)/2.)/TAN((G*AL+T2)/2.))
AD=D+.5
AE=D-.5
CALL CHECK(XA,TT,TS,A,B,FI,D)
CALL CHECK(XC,TV,TU,Z,B,FI,D)
XB=(B/(A-.5))*SIN((D+.5)*AL)*E(AD,TT,TU)
XD=(B/(A-.5))*SIN((D-.5)*AL)*E(AE,TV,TS)
GAM(I,J,K)=XA+XB+XC+XD
1 CONTINUE
RETURN
END

```

```

$IBFTC MATGEN
SUBROUTINE MATGEN(N2,N5,N3,N1,N6,GAM,C,DB,AMU)
DIMENSION C(N6,N6),GAM(N5,N2,N1)
DIMENSION Q(192)
DO 10 J=1,N2
DO 10 N=1,N3
DO 18 I=1,N5
DO 18 IV=1,N1
K=INT(ABS(FLOAT(IV)-FLOAT(N))+1.)
K1=K-1
K2=K-2
IF(K.EQ.1) GO TO 13
GO TO 14
13 K1=N1
K2=N1-1
14 IF(K.EQ.2) K2=N1
K6=K+1
IF(K6.GT.N1) K6=K6-N1
K7=K+2
IF(K7.GT.N1) K7=K7-N1
JN=(J-1)*N3+N
IIV=(I-1)*N1+N
F=FLOAT(I)
C3=(F-.5)*(6.0+6.0/(((F-.5)**4)*(AL**4))+8.0/(((F-.5)**2)*(AL**2))-18.0/(((F-.5)**4)*(AL**2))+2.0/((F-.5)**2))
C4=(F+.5)*(-4.0-4.0/(((F+.5)**2)*(AL**2))+2.0/(F+.5)-2.0/(((F+.5)**3)*(AL**2))-1.0/((F+.5)**2)-1.0/(2.0*((F+.5)**3)))
C5=(F+1.5)*(1.0-1.0/(F+1.5))
C8=(F-.5)*(1.0/(((F-.5)**4)*(AL**4)))
C9=(F-.5)*(-4.0/(((F-.5)**4)*(AL**4))-4.0/(((F-.5)**2)*(AL**2))+14.0/(((F-.5)**4)*(AL**2)))
C12=(F+.5)*(2.0/(((F+.5)**2)*(AL**2))+1.0/(((F+.5)**3)*(AL**2)))
IF(I.EQ.1) GO TO 11
C2=(F-1.5)*(-4.0-4.0/(((F-1.5)*AL)**2)-2.0/(F-1.5)+2.0/(((F-1.5)**3)*(AL**2))-1.0/((F-1.5)**2)+1.0/(2.0*((F-1.5)**3)))
C6=(F-1.5)*(2.0/(((F-1.5)*AL)**2)-1.0/(((F-1.5)**3)*(AL**2)))
IF(I.EQ.2) GO TO 12
C1=(F-2.0)*(1.0+1.0/(F-2.0))
Q(IIV)=(C1*GAM(I-2,J,K)+C2*(GAM(I-1,J,K))+C3*GAM(I,J,K)+C4*GAM(I+1,J,K)+C5*GAM(I+2,J,K)+C6*(GAM(I-1,J,K6)+GAM(I-1,J,K1))+C8*(2*(GAM(I,J,K7)+GAM(I,J,K2))+C9*(GAM(I,J,K6)+GAM(I,J,K1))+C12*(GAM3(I+1,J,K6)+GAM(I+1,J,K1)))*DB
GO TO 18
12 C1=(1.0-1.0/(F-1.5))*(F-1.5)
K3=K+12
IF(K3.GT.N1) K3=K3-N1
Q(IIV)=(C1*GAM(I-1,J,K3)+C2*(GAM(I-1,J,K))+C3*GAM(I,J,K)+C4*GAM(I+1,J,K)+C5*GAM(I+2,J,K)+C6*(GAM(I-1,J,K6)+GAM(I-1,J,K1))+C8*(2*(GAM(I,J,K7)+GAM(I,J,K2))+C9*(GAM(I,J,K6)+GAM(I,J,K1))+C12*(GAM3(I+1,J,K6)+GAM(I+1,J,K1)))*DB

```

```

11 GO TO 18
    C1=(F+.5)*(1.-1./(F+.5))
    C2=(F-.5)*(-4.-4./(((F-.5)*AL)**2)+2./(F-.5)-2./(((F-.5)**3)*
1 (AL**2))-1./((F-.5)**2)-1./(2.*((F-.5)**3)))
    C6=(F-.5)*(2./(((F-.5)*AL)**2)+1./((F-.5)**3)*(AL**2)))
    K3=K+12
    IF(K3.GT.N1) K3=K3-N1
    K4=K+11
    IF(K4.GT.N1) K4=K4-N1
    K5=K+13
    IF(K5.GT.N1) K5=K5-N1
    Q(IIV)=(C1*GAM(I+1,J,K3)+C2*GAM(I,J,K3)+C3*GAM(I,J,K)+C4*GAM
1(I+1,J,K)+C5*GAM(I+2,J,K)+C6*(GAM(I,J,K4)+GAM(I,J,K5))+C8*
2(GAM(I,J,K7)+GAM(I,J,K2))+C9*(GAM(I,J,K6)+GAM(I,J,K1))+C12*(GAM
3(I+1,J,K..)+GAM(I+1,J,K1)))*DB
18 CONTINUE

```

GROUPING OF THE COEFFICIENTS
THIS PART OF THE PROGRAM HAS TO BE CHANGED ACCORDING TO THE PROBLEM

```

DO 5000 I=1,
DO 5000 IV=1,13
IV1=26-IV
IIV=(I-1)*13+IV
IIV1=(I-1)*24+IV1
IIV2=(I-1)*24+IV
IF(IV.EQ.1.OR.IV.EQ.13) GO TO 5001
C(JN,IIV)=Q(IIV2)+Q(IIV1)
GO TO 114
5001 C(JN,IIV)=Q(IIV2)
114 IF(JN.EQ.1) C(JN,IIV)=C(JN,IIV)+1.
5000 CONTINUE
10 CONTINUE
A=FLOAT(N2)
NA=N2
N7=N2+1
DO 21 N=1,N3
DO 21 J=N7,15
JN=(J-1)*N3+N
IV=N
IIV1=(NA+1)*N3+IV
IIV2=NA*N3+IV-1
IIV3=NA*N3+IV
IIV4=NA*N3+IV+1
IIV5=(NA-1)*N3+IV
IIV6=(NA-1)*N3+IV+1
IIV7=(NA-2)*N3+IV
IIV8=(NA-1)*N3+IV-1
IF(J.EQ.N5) GO TO 24
IIV1=(NA+1)*13+IV
IIV2=NA*13+IV-1
IIV3=NA*13+IV

```

```

IIV4=NA*13+IV+1
IIV5=(NA-1)*13+IV
IIV6=(NA-1)*13+IV+1
IIV7=(NA-2)*13+IV
IIV8=(NA-1)*13+IV-1
IF(J.EQ.8) GO TO 24
C(JN,IIV1)=.5
C(JN,IIV5)=-.5-AMU/A-AMU/((A*AL)**2)
C(JN,IIV7)=.5
C(JN,IIV3)=-.5+AMU/A-AMU/((A*AL)**2)
IF(IV.EQ.13) GO TO 22
IF(IV.EQ.1) GO TO 23
C(JN,IIV2)=AMU/(2.*((A*AL)**2))
C(JN,IIV4)=C(JN,IIV2)
C(JN,IIV6)=C(JN,IIV2)
C(JN,IIV8)=C(JN,IIV2)
GO TO 21
22 C(JN,IIV8)=AMU/((A*AL)**2)
C(JN,IIV2)=AMU/((A*AL)**2)
GO TO 21
23 C(JN,IIV6)=AMU/((A*AL)**2)
C(JN,IIV4)=CUJN,IIV6
GO TO 21
24 C(JN,IIV1)=1.+1./(2.*A)
C(JN,IIV3)=-3.-1./(2.*A)-1./(A**2)-2.* (2.-AMU)/((A*AL)**2)
1+(3.-AMU)/((A**3)*(AL**2))
C(JN,IIV5)=3.-1./(2.*A)+1./(A**2)+2.* (2.-AMU)/((A*AL)**2)
1+(3.-AMU)/((A**3)*(AL**2))
C(JN,IIV7)=-1.+1./(2.*A)
IF(IV.EQ.13) GO TO 25
C(JN,IIV4)=(2.-AMU)/((A*AL)**2)-(3.-AMU)/(2.*(A**3)*(AL**2))
C(JN,IIV6)=- (2.-AMU)/((A*AL)**2)-(3.-AMU)/(2.*(A**3)*(AL**2))
IF(IV.EQ.1) GO TO 26
C(JN,IIV2)=C(JN,IIV4)
C(JN,IIV8)=C(JN,IIV6)
GO TO 21
26 C(JN,IIV6)=C(JN,IIV6)*2.
C(JN,IIV4)=C(JN,IIV4)*2.
GO TO 21
25 C(JN,IIV2)=(2.-AMU)/((A*AL)**2)-(3.-AMU)/(2.*(A**3)*(AL**2))
C(JN,IIV8)=- (2.-AMU)/((A*AL)**2)-(3.-AMU)/(2.*(A**3)*(AL**2))
C(JN,IIV2)=C(JN,IIV2)*2.
C(JN,IIV8)=C(JN,IIV8)*2.
21 CONTINUE
RETURN
END

```

```

$IBFTC MATINV
  SUBROUTINE MATINV(A,N,NN)
  DIMENSION A(NN,NN),PIVOT(104),IPIVOT(104),INDEX(104,2)
  EQUIVALENCE (IROW,D1,JROW),(ICOLUMN,D2,JCOLUMN),(AMAX,T,SWAP)
  IF ( N-2 ) 11,12,15
11  A( N,N)=1.0/A( N,N)
  RETURN
12  D1=A(1,1)*A(2,2)-A(1,2)*A(2,1)
  D2=A(1,1)
  A(1,1)=A(2,2)/D1
  A(2,2)=D2/D1
  A(2,1)=-A(2,1)/D1
  A(1,2)=-A(1,2)/D1
  RETURN
C**      INITIALIZATION
15  DO 20 J=1,N
20  IPIVOT(J)=0
  DO 550 I=1,N
C**      SEARCH FOR PIVOT ELEMENT
  AMAX= .0
  DO 105 J=1,N
  IF ( IPIVOT(J)=1) 60,105,60
60  DO 100 K=1,N
  IF ( IPIVOT(K)=1) 80,100,740
80  IF ( ABS(AMAX)=ABS(A(J,K)) ) 85,100,100
85  IROW=J
  ICOLUMN=K
  AMAX=A(J,K)
100 CONTINUE
105 CONTINUE
  IPIVOT(ICOLUMN)=IPIVOT(ICOLUMN)+1
C**      INTERCHANGE ROWS TO PUT PIVOT ELEMENT ON DIAGONAL
  IF ( IROW=ICOLUMN) 150,260,150
150 DO 200 L=1,N
  SWAP=A(IROW,L)
  A(IROW,L)=A(ICOLUMN,L)
200 A(ICOLUMN,L)=SWAP
260 INDEX(I,1)=IROW
  INDEX(I,2)=ICOLUMN
  PIVOT(I)=A(ICOLUMN,ICOLUMN)
C**      DIVIDE PIVOT ROW BY PIVOT ELEMENT
  A(ICOLUMN,ICOLUMN)=1.0
  DO 350 L=1,N
350 A(ICOLUMN,L)=A(ICOLUMN,L)/PIVOT(I)
C**      REDUCE NON-PIVOT ROWS
380 DO 550 L1=1,N
  IF ( L1-ICOLUMN ) 400,550,400
400 T=A(L1,ICOLUMN)
  A(L1,ICOLUMN)=0.0

```

```

DO 450 L=1,N
450 A(L1,L)=A(L1,L)-A(ICOLUMN,L)*T
550 CONTINUE
** INTERCHANGF COLUMN
DO 710 I=1,N
L=N-I+1
IF ( INDEX (L,1) - INDEX(L,2) ) 630,710,630
630 JROW=INDEX(L,1)
JCOLUMN=INDEX(L,2)
DO 705 K=1,N
SWAP=A(K,JROW)
A(K,JCOLUMN)=A(K,JCOLUMN)
705 A(K,JCOLUMN)=SWAP
710 CONTINUE
740 RETURN
END

```

```

IBFTC CHECK
SUBROUTINE CHECK(G,A,B,C,D,FI,F)
PI=4.*ATAN(1.)
AL=PI/12.
E=C/D
IF(E.LT.1.) GO TO 1
INDEX=1
GO TO 2
1 PSCR=ARCCOS(E)
PS1=(F+.5)*AL
PS2=(F-.5)*AL
IF(PS1.GT.PSCR.AND.ABS(PS2).LT.PSCR) GO TO 3
IF(PS1.LE.PSCR) INDEX=-1
IF(ABS(PS2).GE.PSCR) INDEX=1
2 CALL SIMPSN(G,A,B,C,D,FI,INDEX)
GO TO 4
3 TCR=ARSIN(E)
INDEX=1
CALL SIMPSN(G2,TCR,B,C,D,FI,INDEX)
INDEX=-1
CALL SIMPSN(G1,A,TCR,C,D,FI,INDEX)
G=G1+G2
4 RETURN
END

```

```

;IBFTC SIMPSN
SUBROUTINE SIMPSN(G,A,B,C,D,FI,INDEX)
IF(A.EQ.B) GO TO 3
Y=(D/C)**2
F(T)=FLOAT(INDEX)*SQRT(1.-Y*(SIN(T)**2))
DIV=50.
H=(B-A)/DIV
X=A
N=INT(DIV/2.)
SUM=0.
DO 2 I=1,N
SUM=SUM+(H/3.)*(F(X)+4.*F(X+I)+F(X+2.*H))
X=X+2.*H
2 CONTINUE
G=C*SUM(FI=.5)+D*(SIN(B)-SIN(A))/(FI=.5)
GO TO 4
3 G=0.
4 RETURN
END

```

```

;IBFTC MOMMR
SUBROUTINE MOMMR(W,N2,N3,N8,N7,MR)
REAL MR
DIMENSION MR(N7),W(N8)
DO 401 IV=1,N3
DO 401 I=1,N2
IV1=IV-1
IF(IV.EQ.1) IV1=2
IV2=IV+1
IF(IV.EQ.N3) IV2=N3-1
IIV=(I-1)*N3+IV
IIV1=I*13+IV
IIV2=(I-2)*N3+IV
IIV3=(I-1)*N3+IV1
IIV4=(I-1)*N3+IV2
FI=FLOAT(I)-.5
IF(I.EQ.1) GO TO 402
MR(IIV)=-DB*(W(IIV1)*(1.+AMU/(2.*FI))+W(IIV)*(-2.-2.*AMU/((FI*AL)
1**2))+W(IIV2)*(1.-AMU/(2.*FI))+(W(IIV3)+W(IIV4))*AMU/((FI*AL)**2))
GO TO 401
402 IV3=IV+12
IF(IV3.GT.N3) IV3=N3-(IV3-N3)
IIV5=(I-1)*N3+IV3
MR(IIV)=-DB*(W(IIV1)*(1.+AMU/(2.*FI))+W(IIV)*(-2.-2.*AMU/((FI*AL)
1**2))+W(IIV5)*(1.-AMU/(2.*FI))+(W(IIV3)+W(IIV4))*AMU/((FI*AL)**2))
401 CONTINUE
RETURN
END

```

IBFTC MOMMT

```

SUBROUTINE MOMMT(W,N2,N3,N8,N7,MT)
REAL MT
DIMENSION MT(N7),W(N8)
DO 401 IV=1,N3
DO 401 I=1,N2
IV1=IV-1
IF(IV.EQ.1) IV1=2
IV2=IV+1
IF(IV.EQ.N3) IV2=N3-1
IIV=(I-1)*N3+IV
IIV1=I*13+IV
IIV2=(I-2)*N3+IV
IIV3=(I-1)*N3+IV1
IIV4=(I-1)*N3+IV2
FI=FLOAT(I)-.5
IF(I.EQ.1) GO TO 402
MT(IIV)=-DB*(W(IIV1)*(1./(2.*FI)+AMU)+W(IIV)*(-2./*((FI*AL)**2)-2.*1AMU)+W(IIV2)*(-1./*(2.*FI)+AMU)+(W(IIV3)+W(IIV4))/((FI*AL)**2))
GO TO 401
402 IV3=IV+12
IF(IV3.GT.N3) IV3=N3-(IV3-N3)
IIV5=(I-1)*N3+IV3
MT(IIV)=-DB*(W(IIV1)*(1./*(2.*FI)+AMU)+W(IIV)*(-2./*((FI*AL)**2)-2.*1AMU)+W(IIV5)*(-1./*(2.*FI)+AMU)+(W(IIV3)+W(IIV4))/((FI*AL)**2))
01 CONTINUE
RETURN
END


```

BFTC DFLCTN

```

SUBROUTINE DFLCTN(C,GAM,N2,N3,N6,N5,W)
DIMENSION GAM(10,8,24)
DIMENSION BC(130)
DIMENSION C(N6,N6),W(N6)
DO 42 J=1,N2
DO 42 N=1,N3
JN=(J-1)*N3+N
K=INT(ABS(FLOAT(IV)-FLOAT(N))+1.)
BC(JN)=GAM(II,J,K)
2 CONTINUE
DO 44 J=1,N2
DO 44 N=1,N3
JN=(J-1)*N3+N
W(JN)=0.
DO 44 M=1,N6
W(JN)=W(JN)+C(JN,M)*BC(M)
4 CONTINUE
RETURN
END

```



COMPUTER PROGRAM NO. 2

```

R=RADIAL POSITION
I SEC=SECTOR NO.
LP=LOAD POSITION
DIMENSION F(750),E(150),D(30),C(6),W(7)
1  FORMAT(I1)
3  FORMAT(I2)
4  FORMAT(10X,5E12.5)
2  FORMAT(2F5.2)
16 FORMAT(//20XT2F5.2)
100 FORMAT(F5.2)
READ100,R
READ1,LP
READ3,I SEC
READ4,(F(I),I=1,750)
READ2,DB,AMU
PRINT16,DB,AMU
DO 5 I=1,150
E(I)=0.
DO 5 L=1,5
K=L-1
IJ=(I-1)*5+L
E(I)=E(I)+F(IJ)*(AMU**K)
CONTINUE
DO 6 I=1,30
D(I)=0.
DO 6 J=1,5
K=J-1
IJ=(I-1)*5+J
D(I)=D(I)+E(IJ)*(DB**K)
CONTINUE
A=FLOAT(LP)
DO 7 I=1,6
C(I)=0.
DO 7 J=1,5
IJ=(I-1)*5+J
K=J-1
C(I)=C(I)+D(IJ)*(A**K)
7  CONTINUE
W(I)=0.
DO 8 J=1,6
K=J-1
W(I)=W(I)+C(J)*(R**K)
PRINT10
PRINT9,I SEC
9  FORMAT(//55X,*FOR ELEMENTS IN SECTOR=*,I2,/)
10 FORMAT(1H1)
PRINT11,(W(I),I=1,7)
11 FORMAT(10X,7E15.6)
15 CONTINUE
14 CONTINUE
PRINT10
STOP

```